

ASBESTOS HAZARD EMERGENCY RESPONSE ACT (AHRA)
GENERAL DATA (FORM A)

LOCAL EDUCATION AGENCY Central California Conference of SDA	County Fresno
--	------------------

SCHOOL NAME Monterey Bay Academy	Phone number (408)728-1481
-------------------------------------	-------------------------------

ADDRESS (number) 783	(street) San Andreas Road	(city) La Selva Beach	(zip code) 95076-1907
-------------------------	------------------------------	--------------------------	--------------------------

CDS Code 44-69799-6940787	School Enrollment 350	# of Employees 61	# of Buildings 45
------------------------------	--------------------------	----------------------	----------------------

LEA AHRA DESIGNEE

NAME ESLINGER ENTERPRISES HERBERT J. ESLINGER - GILBERT D. ESLINGER	Phone number 209-387-4375
---	------------------------------

Address (number) 9545 West Hwy 152	(street)	(city) Dos Palos	(zip code) 93620
---------------------------------------	----------	---------------------	---------------------

Training Course(s) & Date(s) Competent person - March 8-11 Certified Worker - March 21-25 Inspector & Mgt./Planner - May 2-6	Hours 32 40 40	Total Training hr. 112 HRS.
---	-------------------------	--------------------------------

MANAGEMENT PLANNER

Name Herbert J. Eslinger	Phone number 209-387-4375
-----------------------------	------------------------------

Address (number) 9545 West Hwy. 152	(street)	(city) Dos Palos	(zip code) 93620
--	----------	---------------------	---------------------

Accreditation # MP 2107 88	MP 2108 88	Training Agency Northwest Envirocon, Portland
-------------------------------	------------	--

Documents Attached

☒ Form B
 ☒ Form C
 ☒ Form D
 ☒ Form E
☒ Form F
 ☒ Form G
 ☒ Form H

We certify that the general Local Education Agency (LEA) responsibilities, as stipulated by 40CFR Part 763, have been met or will be met, and that this submission includes all buildings at this school.

Management Planner Signature <i>H. Eslinger</i>	Date 1-26-89
LEA Designee Signature <i>H. Eslinger</i>	Date 1-26-89
LEA Superintendent Signature M.E. THORMAN, Ed. Sec. <i>M.E. Thorman</i>	Date 2/3/89

OFFICE OF LOCAL ASSISTANCE USE ONLY

Date Returned	Date Resubmittal Received	(date stamp)
---------------	---------------------------	--------------

Reason(s) For Return

Printed Name of Reviewer	Date
--------------------------	------

Reviewer's Signature

RECORD OF FRIABLE AND NONFRIABLE ACBM
(FORM B)

23

CDS CODE
44-69799-6940787

SCHOOL
Monterey Bay Academy

SCHOOL PHONE #
(408)728-1481

ADDRESS (number) (street) (city) (zip code)
783 San Andreas Road La Selva Beach 95076-1907

-IMPORTANT-

Each building and functional space with friable ACBM or friable assumed ACBM listed on this form requires completion of FORM C (PHYSICAL AND HAZARD ASSESSMENT OF FRIABLE ACBM OR FRIABLE ASSUMED ACBM).

Indicate location of material on blueprint, diagram or narrative in square or linear feet, and attach a copy (Sec. 763.93).

line	BUILDING NAME & FUNCTIONAL SPACE (indicate address if different)	CHECK ONE			CHECK ONE			
		Sur fac ing	TSI	MISC.	ACBM		ASSUMED ACBM	
					Fri able	Non fri	Fri able	Non friable
1.	Adm. & Class. - Storage #13 (23-A13-T)			X		X		
2.	Adm. & Class. - Janitors Rm. #16 (23-A16-T)			X		X		
3.	Adm. & Class. - Stairs to Attic #15 (23-A15-T)			X		X		
4.	Adm. & Class. - Attic #15 (23-A15-HV)		X			X		
5.	Music Dept. - Rehearsal Rm. #5 (23-M5-T)			X		X		
6.	Music Dept. - Janitors #24 (23-M24-V)			X		X		
7.	Industrial Arts - Office #4 (23-I4-T)			X		X		
8.	Cafeteria - Office Storage #4 (23-C4-T)			X		X		
9.	Cafeteria - Serving Area #1 (23-C1-V)	X				X		
10.	Cafeteria - Store Area #12 (23-C12-PI)		X		X			
11.	Rainbow Fins - Office #4 (23-R4-V)			X		X		
12.	Auto Mech. - Shop Area #1 (23-AM1-C)	X			X			
13.	Maintenance Dept. - Office #8 (23-M8-AS)	X			X			
14.	Dairy - west wall #6 (23-D6-S)	X				X		

15.	Boys Dorm. - Boiler Rm. #10 (23-BD10-PI)		X		X			
16.	Boys Dorm. - N.restrm.1st.fl. #4 (23-BD4-V)			X		X		
17.	Boys Dorm. - Chapel #1 (23-BD1-AS)	X			X			
18.	Girls Dorm. - Janitors #8 (23-GD8-T)			X		X		
19.	Girls Dorm. - Restroom #2 (23-GD2-V)			X		X		
20.	Girls Dorm. - Shower Area #7 (23-GD7-V)			X		X		
21.	Girls Dorm. - Storage #4 (23-GD4-PI)		X		X			
22.	Girls Dorm. - Boiler Rm. #3 (23-GD3-PI)		X		X			
23.	Girls Dorm. - Chapel #5 (23-GD5-AS)	X			X			
24.	Church - Cradle Rm. #4 (23-CU4-AS)	X			X			
25.	Cafeteria - Roof	X						X
26.	Girls Dormitory - Roof	X						X
27.	Girls Dorm. New Wing - hallway	X					X	
28.	Boys Dormitory - Roof	X						X
29.	Administration Building - Roof	X						X
30.								
31.								

ESLINGER ENTERPRISES

The following Inspection Report was completed by Herbert and Gilbert Eslinger. Samples were taken randomly and in areas of convenience and inconspicuously according to Sec. 763.86 of the Federal Register.

Date: 12-14-88

Herbert Eslinger I-1107-88
Herbert Eslinger (accreditation #)

Gilbert Eslinger I-1108-88
Gilbert Eslinger (accreditation #)

The holder of this card has successfully completed the training needed to comply with AHERA regulations 40 CFR 763 and TSCA Title II.

Instructor Signature

Robert E. Hastings

The holder of this card has successfully completed the training needed to comply with AHERA regulations 40 CFR 763 and TSCA Title II.

Instructor Signature

Robert E. Hastings

NOTICE

IF YOU WORK ON AN ASBESTOS REMOVAL OR ENCAPSULATION PROJECT, YOU MUST BE PREPARED AT ANY TIME TO SHOW THIS CARD TO AN INSPECTOR. YOU CANNOT LET ANYONE ELSE USE THIS CARD. YOU MUST TAKE A REFRESHER COURSE BEFORE APPLYING FOR A RENEWAL OF THIS CARD

NOT VALID UNTIL SIGNED

Gilbert Eslinger

Northwest Envirocon, Inc.



NAME
GILBERT ESLINGER
I.D. # _____ CERT. #
1-1108-88
BIRTHDATE EXP. DATE
04/17/51 05/04/89
CERTIFICATION TYPE
ACCREDITED INSPECTOR



Northwest Envirocon, Inc.



NAME
GILBERT ESLINGER
I.D. # _____ CERT. #
MP-2108-88
BIRTHDATE EXP. DATE
04/17/51 05/06/89
CERTIFICATION TYPE
ACCREDITED MGT/PLANNER


Department of
LABOR & INDUSTRIES

Division of
INDUSTRIAL SAFETY & HEALTH

 CERTIFIED ASBESTOS WORKER 



NAME
Gilbert Eslinger
IDENTIFICATION NO.
E7393
BIRTHDATE
04/17/51
CERTIFICATE NO.
3043 W
EXPIRATION DATE
03/25/90
JOSEPH A. DEAR, DIRECTOR
Joseph A. Dear





NAME
HERBERT J. ESLINGER

I.D.# **I-1107-88**

BIRTHDATE **12/29/22** EXP. DATE **05/04/89**

CERTIFICATION TYPE
ACCREDITED INSPECTOR

NOTICE

IF YOU WORK ON AN ASBESTOS REMOVAL OR ENCAPSULATION PROJECT YOU MUST BE PREPARED AT ANY TIME TO SHOW THIS CARD TO AN INSPECTOR YOU CANNOT LET ANYONE ELSE USE THIS CARD. YOU MUST TAKE A REFRESHER COURSE BEFORE APPLYING FOR A RENEWAL OF THIS CARD

NOT VALID UNTIL SIGNED

Herbert J. Eslinger

THIS CERTIFIES THAT

HERBERT ESLINGER

has successfully completed the training needed to comply with AHERA regulations 40 CFR 763 and TSCA Title II.

0158 3/11/88 RANDY HALL

The holder of this card has successfully completed the training needed to comply with AHERA regulations 40 CFR 763 and TSCA Title II.

Instructor Signature

Robert E. Hastings

Department of
LABOR & INDUSTRIES

Division of
INDUSTRIAL SAFETY & HEALTH



CERTIFIED ASBESTOS WORKER



NAME
Herbert J Eslinger

CERTIFICATION NO. E6218	CERTIFICATE NO. 3042 W
BIRTHDATE 12/29/22	EXPIRATION DATE 03/25/90

JOSEPH A. DEAR, Director
Joseph A. Dear

Northwest Envirocon, Inc.



NAME
HERBERT J. ESLINGER

I.D.# **MP-2107-88**

BIRTHDATE **12/29/22** EXP. DATE **05/06/89**

CERTIFICATION TYPE
ACCREDITED MGT/PLANNER

The holder of this card has successfully completed the training needed to comply with AHERA regulations 40 CFR 763 and TSCA Title II.

Instructor Signature

Robert E. Hastings

Northwest ENVIROCON, Inc.

THIS CERTIFIES THAT

HERBERT ESLINGER

has successfully completed the training needed to comply with AHERA regulations 40 CFR 763 and TSCA Title II.

0158 3/11/88 RANDY HALL

[REDACTED]

[REDACTED]

SCHOOL:

MBA - Admin. + classrooms

ROOM #	ROOM NAME	FLOOR COVERING	WALL TEXTURE	CEILING TEXTURE	MISC. COVERING	REMARKS
	classroom #1	crypt over 9x9	plas.	12x12		
	" J.P. Jr.	"	panel over plas. + w.p.	2x4 clear glass panels		Drum wall paper
	Career ed. & labor.	"	plas.	Same as hallway		(crawl space)
	wt. experience coordinator	"	SR	SR		drop ceiling
	Sec. J.P. Jr.	"	gumy sack SR, panel	SR		
	mini graph rm.	9x9	plas.	plas.		sample
	Principal's Office	crypt over 9x9	plas. + vinyl w.p.	Same as hallway		
	" K.R.	9x9	plas.	plas.	same	sample brown
	Storage	"	"	"		
	Stair case	9x9	Same as music hall ceiling	open to attic		sample (black + green)
	Attic storage	wood	SR	wood	gas vent, heat duct	sample
*	24. rm. has one or two heaters and are vented through to roof with suspect material					
	Waiting rm.	crypt over 9x9	plas. + vinyl w.p.	12x12	Same w.p. as prin. off	fair water spots
	Secretary's Office	"	plas.	12x12 fiber		bad water spots
	Registrar's Office	"	"	"	same	fair
	" work rm.	"	" with 12x12	"		
	Business office	"	"	"		
	Vault	9x9	plas over conc.	conc.		
	Business Office Reception	crypt over 9x9	SR	SR		drop ceiling
	+ mail rm.	"	"	"		
	Offices in bus. off.	"	plas.	SR.		drop ceiling

SCHOOL:


MBA - Adm. & Class Rm.

ROOM #	ROOM NAME	FLOOR COVERING	WALL TEXTURE	CEILING TEXTURE	MISC. COVERING	REMARKS
	hallway	new cprt over conc	plaz & SR	Opposem? (50 ft)	sound insul. ation	(water spots sample)
	Class. #6	cprt over 9x9	plaz/wood SR panel	1 1/2 x 3 (2x4)		fiber board & cellulose
	Class rm. #7	"	SR/plaz/wood panel	1 1/2 x 3 (2x4)	office ceilings are 2x4	office wood panel
	" #5	"	"	"	cellulose	(drop ceilings)
	" #4	"	plaz	1 1/2 x 3		
	staff bath	cer. tile	SR/wall paper	SR		
	Vice Principal's Office	cprt over 9x9	plaz/wall paper	2x4 drop ceiling		
	Janitors	9x9 tile	plaz	plaz		fan
	Women restroom	cer. tile	plaz	plaz		
	Storage behind	cprt over 9x9	plaz	1.5 x 3		
	Chapel	cprt assumed over 9x9	plaz/wood panel	12x12 ac. tile		water spots (ridges)
	"	rubber over steps				
	" stage	cprt		Same as hallway		crawl space
	Men R.P.	cer. tile	plaz/cer. tile	plaz		
	staff bathroom	cer. tile	plaz	plaz		
	Copier room	cprt over 9x9	plaz	2x4 over 1 1/2 x 3		drop ceiling
	Class rm. 3	cprt over 9x9 tile	plaz	1 1/2 x 3		
	" Office	"	"	2x4 over 1 1/2 x 3		drop ceiling
	librarian office	"	"	1 1/2 x 3		
	computer office	"	"	"		
	library	"	"	Same as hallway		
	Class rm. #2	"	wood panel over plaz	1 1/2 x 3		
	" office	"	"	2x4 over		drop ceiling

SCHOOL:

[illegible]

28-53



Monterey Bay Academy
Plot Plan January 1, 1976

January 1, 1976

Buildings Existing & Proposed

1. Girls' dorm
2. Cafeteria
3. Boys' dorm
4. Art Department
5. Industrial Arts
6. Administration
7. Science & Home Arts
8. Campus Store
9. Multipurpose Bldg.
11. Gymnasium
12. Hanger A - still
13. Swimming Pool
14. Maintenance
15. Firehouse
16. Auto Mech. Shop
17. Bus Storage
18. Auto Repair Garage
19. Towel Hangers
20. Laundry
21. Produce Warehouse
22. Beach Apartments
23. Beach
27. Mill *all still*
28. Version
29. Farm Shop *wood house*
30. Dairy
31. Dair Barn
32. Calf Barn
33. Water Tanks
34. Apartments
35. Maintenance Storage - *poly*
36. M.B.A. Church
37. Tennis Courts
40. Cow corral & hay barn
41. Calf barn
42. Cow corral & hay barn
43. Cow corral & hay barn
44. Horse stall


20. grounds.
21. Audi. (Condensation)
22. rainbow fins
(fiberglass)
45. CB Marina
(pavement)

MONTEREY BAY ACADEMY

ADMINISTRATION & CLASSROOMS.

NORTH WING
SOUTH WING
ASSEMBLY HALL.
MUSIC DEPT.

19468
10800
30268 TOTAL




TOTAL FRONT DISTANCE 314'

MUSIC
DEPT.
HALL


ASSEMBLY
HALL

MONTEREY BAY SDA. ACADEMY
ADMINISTRATION & CLASSROOMS
SOUTH WING

121'



Foyer



157'

TOTAL FRONT DISTANCE 314'

Building: MBA - Administration + Classrooms

Functional Area No. 23-A13-T Location: principals storage

Type of Suspect Material: Surfacing, TSI, ☒ Other

Description: 9x9 tile - same in restroom

Approximate Amount of Material (linear or square ft.): 64

Condition

Percent Damage: 0 %, Localized, Distributed

Type of Damage: Deterioration, Water, Physical

Description: _____

Overall Rating: ☒ Good, Fair, Poor

Potential for Disturbance

Accessibility: ☒ Accessible, Inaccessible

Description: _____

Potential for Contact: High, ☒ Moderate, Low

Description: _____

Influence of Vibration: High, Moderate, ☒ Low

Description: _____

Potential for Air Erosion: High, Moderate, ☒ Low

Description: _____

Located in a Plenum? Yes, ☒ No; Type: _____

Comments: _____

Signed: [Signature] Date: 12-22-88

CERTIFICATE OF ANALYSIS

LAB I.D.: P-74118
 SAMPLE LOCATION: 23-A13-T
 COLLECTED BY: Client
 DATE COLLECTED: Not Given

DATE RECEIVED: December 27, 1988
 DATE STARTED: January 6, 1989
 DATE COMPLETED: January 6, 1989
 DATE REPORTED: January 10, 1989

CLIENT: Eslinger, Herbert
 STREET: 9545 W. Hwy 152
 CITY: Dos Palos
 STATE: CA ZIP: 93620

PURCHASE ORDER: N/A
 OFW #: L0839
 COPY TO: No cc Req.

PLM ANALYSIS

Analyte	Results Volume %	Detect Limit Volume %
ASBESTOS		
CHRYSDOTILE	1-2 %	1. %
AMOSITE	ND	1. %
CROCIDOLITE	ND	1. %
ANTHOPHYLITE	ND	1. %
TREMOLITE-ACTONOLITE	ND	1. %
FIBER GLASS	ND	1. %
MINERAL WOOL	ND	1. %
CELLULOSE	ND	1. %
NON FIBROUS MATERIALS	98-99 %	1. %
COLOR	Brown	

Method: EPA Interim Method for the Determination
 of Asbestos in Bulk Insulation Samples

EPA 600/4-82-020

This report may not be used to
 claim product endorsement by
 NVLAP or any agency of the
 U.S. Government.

APPROVED: Scott Foster

File: CWL.PLM

Building: MBA. : Adm - Classroom
Functional Area No. 23-A16-T Location: Janitors Rm.
Type of Suspect Material: Surfacing, TSI, ✓ Other
Description: 9x9 tiles on floor

Approximate Amount of Material (linear or square ft.): 36 sq/ft.

Condition

Percent Damage: 5 %, Localized, ✓ Distributed
Type of Damage: 1 Deterioration, Water, ✓ Physical
Description:

Overall Rating: Good, ✓ Fair, Poor

Potential for Disturbance

Accessibility: ✓ Accessible, Inaccessible
Description: used by Janitor mainly

Potential for Contact: High, ✓ Moderate, Low
Description: by Janitorial staff

Influence of Vibration: High, Moderate, ✓ Low
Description:

Potential for Air Erosion: High, Moderate, ✓ Low
Description:

Located in a Plenum? Yes, No; Type:

Comments:

Signed: AJE Date: 12-22-88

CERTIFICATE OF ANALYSIS

LAB I.D.: P-74107
 SAMPLE LOCATION: 23-A16-T
 COLLECTED BY: Client
 DATE COLLECTED: Not Given

DATE RECEIVED: December 27, 1988
 DATE STARTED: January 6, 1989
 DATE COMPLETED: January 6, 1989
 DATE REPORTED: January 10, 1989

CLIENT: Eslinger, Herbert
 STREET: 9545 W. Hwy 152
 CITY: Dos Palos
 STATE: CA ZIP: 93620

PURCHASE ORDER: N/A
 OFN #: L0839
 COPY TO: No cc Req.

PLM ANALYSIS

Analyte	Results Volume %	Detect Limit Volume %
ASBESTOS		
CHRYSTILE	1-2 %	1. %
AMOSITE	ND	1. %
CROCIDOLITE	ND	1. %
ANTHOPHYLITE	ND	1. %
TREMOLITE-ACTONOLITE	ND	1. %
FIBER GLASS	ND	1. %
MINERAL WOOL	ND	1. %
CELLULOSE	ND	1. %
NON FIBROUS MATERIALS	98-99 %	1. %
COLOR	Gray	

Method: EPA Interim Method for the Determination
 of Asbestos in Bulk Insulation Samples EPA 600/4-82-020

APPROVED: 

This report may not be used to
 claim product endorsement by
 NVLAP or any agency of the
 U.S. Government.

File: CWL.PLM

Building: MBA - Administration + ClassroomFunctional Area No. 23-A15-T Location: Staircase by waiting roomType of Suspect Material: Surfacing, TSI, ☒ OtherDescription: 9x9 floor tileApproximate Amount of Material (linear or square ft.): 20ConditionPercent Damage: 0 %, Localized, DistributedType of Damage: Deterioration, Water, Physical

Description: _____

Overall Rating: ☒ Good, Fair, PoorPotential for DisturbanceAccessibility: ☒ Accessible, Inaccessible

Description: _____

Potential for Contact: High, ☒ Moderate, Low

Description: _____

Influence of Vibration: High, Moderate, ☒ Low

Description: _____

Potential for Air Erosion: High, Moderate, ☒ Low

Description: _____

Located in a Plenum? Yes, ☒ No; Type: _____

Comments: _____

Signed: gf Date: 12-22-88

CERTIFICATE OF ANALYSIS

LAB I.D.: P-74898
 SAMPLE LOCATION: 23-A15-T
 COLLECTED BY: Client
 DATE COLLECTED: Not Given

DATE RECEIVED: December 27, 1988
 DATE STARTED: January 5, 1989
 DATE COMPLETED: January 5, 1989
 DATE REPORTED: January 10, 1989

CLIENT: Eslinger, Herbert
 STREET: 9545 W. Hwy 152
 CITY: Dos Palos
 STATE: CA ZIP: 93620

PURCHASE ORDER: N/A
 OFW #: L0839
 COPY TO: No cc Req.

P L M ANALYSIS

Analyte	Results Volume %	Detect Limit Volume %
ASBESTOS		
CHRYSDTILE	1-2 %	1. %
AMOSITE	ND	1. %
CROCIDOLITE	ND	1. %
ANTHOPHYLITE	ND	1. %
TREMOLITE-ACTONOLITE	ND	1. %
FIBER GLASS	ND	1. %
MINERAL WOOL	ND	1. %
CELLULOSE	ND	1. %
NON FIBROUS MATERIALS	98-99 %	1. %
COLOR	Green & White	

Method: EPA Interim Method for the Determination
 of Asbestos in Bulk Insulation Samples EPA 680/4-82-020

This report may not be used to
 claim product endorsement by
 NVLAP or any agency of the
 U.S. Government.

File: CHL.PLM

APPROVED: Scott Truster

Building: MBA - Administration + Comm.Functional Area No. 23-A15-11V Location: attic - storageType of Suspect Material: Surfacing, TSI, ☒ OtherDescription: heating vents - every room has 1 or 2 heaters
vents go up in attic to roof. Also in MBA Package "Umbrella
Plant".Approximate Amount of Material (linear or square ft.): 350ConditionPercent Damage: 0 %, Localized, DistributedType of Damage: Deterioration, Water, PhysicalDescription: _____
_____Overall Rating: ☒ Good, Fair, PoorPotential for DisturbanceAccessibility: Accessible, ☒ InaccessibleDescription: _____
_____Potential for Contact: High, Moderate, ☒ LowDescription: _____
_____Influence of Vibration: High, Moderate, ☒ LowDescription: _____
_____Potential for Air Erosion: High, Moderate, ☒ LowDescription: _____
_____Located in a Plenum? Yes, ☒ No; Type: _____

Comments: _____

Signed: gc Date: 12-22-88

CERTIFICATE OF ANALYSIS

LAB I.D.: P-74887
SAMPLE LOCATION: 23-A15-HV
COLLECTED BY: Client
DATE COLLECTED: Not Given

DATE RECEIVED: December 27, 1988
DATE STARTED: January 5, 1989
DATE COMPLETED: January 5, 1989
DATE REPORTED: January 10, 1989

CLIENT: Eslinger, Herbert
STREET: 9545 W. Hwy 152
CITY: Dos Palos
STATE: CA ZIP: 93620

PURCHASE ORDER: N/A
OFW #: L8839
COPY TO: No cc Req.

PLH ANALYSIS

Analyte	Results Volume %	Detect Limit Volume %
ASBESTOS		
CHRYSTILE	40-45 %	1. %
AMOSITE	ND	1. %
CROCIDOLITE	ND	1. %
ANTHOPHYLITE	ND	1. %
TREHDLITE-ACTONOLITE	ND	1. %
FIBER GLASS	ND	1. %
MINERAL WOOL	ND	1. %
CELLULOSE	ND	1. %
NON FIBROUS MATERIALS	55-60 %	1. %
COLOR	Gray	

Method: EPA Interim Method for the Determination
of Asbestos in Bulk Insulation Samples EPA 600/4-82-020

This report may not be used to
claim product endorsement by
NVLAP or any agency of the
U.S. Government.

File: CHL.PLH

APPROVED: 

Building: MBA - Administration - classroomsFunctional Area No. 23-A12-VP Location: principals officeType of Suspect Material: ☒ Surfacing, ☐ TSI, ☐ OtherDescription: vinyl wall paperApproximate Amount of Material (linear or square ft.): 300ConditionPercent Damage: 0 %, ☐ Localized, ☐ DistributedType of Damage: ☐ Deterioration, ☐ Water, ☐ Physical

Description: _____

Overall Rating: ☒ Good, ☐ Fair, ☐ PoorPotential for DisturbanceAccessibility: ☒ Accessible, ☐ Inaccessible

Description: _____

Potential for Contact: ☐ High, ☒ Moderate, ☐ Low

Description: _____

Influence of Vibration: ☐ High, ☐ Moderate, ☒ Low

Description: _____

Potential for Air Erosion: ☐ High, ☐ Moderate, ☒ Low

Description: _____

Located in a Plenum? ☐ Yes, ☒ No; Type: _____

Comments: _____

Signed: ge Date: 12-22-88

CERTIFICATE OF ANALYSIS

LAB I.D.: P-74117
 SAMPLE LOCATION: 23-A12-VP
 COLLECTED BY: Client
 DATE COLLECTED: Not Given

DATE RECEIVED: December 27, 1988
 DATE STARTED: January 6, 1989
 DATE COMPLETED: January 6, 1989
 DATE REPORTED: January 10, 1989

CLIENT: Eslinger, Herbert
 STREET: 9545 W. Hwy 152
 CITY: Dos Palos
 STATE: CA ZIP: 93620

PURCHASE ORDER: N/A
 OFH #: L0839
 COPY TO: No cc Req.

PLH ANALYSIS

Analyte	Results Volume %	Detect Limit Volume %
ASBESTOS		
CHRYSTILE	ND	1. %
AMOSITE	ND	1. %
CROCIDOLITE	ND	1. %
ANTHOPHYLITE	ND	1. %
TREHOLITE-ACTONOLITE	ND	1. %
FIBER GLASS	ND	1. %
MINERAL WOOL	ND	1. %
CELLULOSE	35-40 %	1. %
NON FIBROUS MATERIALS	60-65%	1. %
COLOR	Brown	

Method: EPA Interim Method for the Determination
 of Asbestos in Bulk Insulation Samples EPA 600/4-82-020

APPROVED: 

This report may not be used to
 claim product endorsement by
 NVLAP or any agency of the
 U.S. Government.
 File: CWL.PLM

Building: MBA - Administration & Classrooms
 Functional Area No. 23-A24-T Location: mining room
 Type of Suspect Material: Surfacing, TSI, ☒ Other
 Description: 9x9 floor tile - tile is in all rooms except
hallways. When there is carpet, it's under. (not under of 100)
 Approximate Amount of Material (linear or square ft.): 30000

Condition

Percent Damage: ? %, Localized, Distributed
 Type of Damage: Deterioration, Water, Physical
 Description: most is under carpet - tile that's exposed is
good.
 Overall Rating: ☒ Good, Fair, Poor

Potential for Disturbance

Accessibility: Accessible, ☒ Inaccessible
 Description: majority - because under carpet
 Potential for Contact: High, Moderate, ☒ Low
 Description: _____
 Influence of Vibration: High, Moderate, ☒ Low
 Description: _____
 Potential for Air Erosion: High, Moderate, ☒ Low
 Description: _____

Located in a Plenum? Yes, ☒ No; Type: _____

Comments: _____

Signed: ge Date: 12-22-88

CERTIFICATE OF ANALYSIS

LAB I.D.: P-74357
 SAMPLE LOCATION: 23-A24-T
 COLLECTED BY: Client
 DATE COLLECTED: Not Given

DATE RECEIVED: January 4, 1989
 DATE STARTED: January 9, 1989
 DATE COMPLETED: January 9, 1989
 DATE REPORTED: January 11, 1989

CLIENT: Eslinger, Herbert
 STREET: 9545 W. Hwy 152
 CITY: Dos Palos
 STATE: CA ZIP: 93620

PURCHASE ORDER: N/A
 OFW #: L0884
 COPY TO: No cc Req.

PLM ANALYSIS

Analyte	Results Volume %	Detect Limit Volume %
ASBESTOS		
CHRYSTOTILE	ND	1. %
AMOSITE	ND	1. %
CROCIDOLITE	ND	1. %
ANTHOPHYLITE	ND	1. %
TREMOLITE-ACTONOLITE	ND	1. %
FIBER GLASS	ND	1. %
MINERAL WOOL	ND	1. %
CELLULOSE	ND	1. %
NON FIBROUS MATERIALS	100 %	1. %
COLOR	Gray & Brown	

Method: EPA Interim Method for the Determination
 of Asbestos in Bulk Insulation Samples

EPA 600/4-82-020

report may not be used to
 claim product endorsement by
 VVLAP or any agency of the
 U.S. Government.
 File: CWL.PLM

APPROVED: _____

Scott Foster

Building: MBA - Attic in frame build
 Functional Area No. 23-A15-JC Location: attic
 Type of Suspect Material: ☒ Surfacing, ☐ TSI, ☐ Other
 Description: joint compound

Approximate Amount of Material (linear or square ft.): 3

Condition

Percent Damage: 10 %, ☒ Localized, ☐ Distributed
 Type of Damage: ☒ Deterioration, ☐ Water, ☐ Physical
 Description: _____

Overall Rating: ☐ Good, ☒ Fair, ☐ Poor

Potential for Disturbance

Accessibility: ☐ Accessible, ☒ Inaccessible
 Description: in attic

Potential for Contact: ☐ High, ☐ Moderate, ☒ Low
 Description: away from student, only authorized personnel

Influence of Vibration: ☐ High, ☐ Moderate, ☒ Low
 Description: _____

Potential for Air Erosion: ☐ High, ☐ Moderate, ☒ Low
 Description: _____

Located in a Plenum? ☐ Yes, ☒ No; Type: _____

Comments: _____

Signed: ge Date: 12-22-88

CERTIFICATE OF ANALYSIS

LAB I.D.: P-74103
 SAMPLE LOCATION: 23-A15-JC
 COLLECTED BY: Client
 DATE COLLECTED: Not Given

DATE RECEIVED: December 27, 1988
 DATE STARTED: January 6, 1989
 DATE COMPLETED: January 6, 1989
 DATE REPORTED: January 10, 1989

CLIENT: Eslinger, Herbert
 STREET: 9545 W. Hwy 152
 CITY: Dos Palos
 STATE: CA ZIP: 93620

PURCHASE ORDER: N/A
 OFH #: L0839
 COPY TO: No cc Req.

PLM ANALYSIS

Analyte -----	Results Volume % -----	Detect Limit Volume % -----
ASBESTOS		
CHRYSTOTILE	ND	1. %
AMOSITE	ND	1. %
CROCIDOLITE	ND	1. %
ANTHOPHYLITE	ND	1. %
TRENOLITE-ACTONOLITE	ND	1. %
FIBER GLASS	ND	1. %
MINERAL WOOL	ND	1. %
CELLULOSE	1-2 %	1. %
NON FIBROUS MATERIALS	98-99 %	1. %
COLOR	White	

Method: EPA Interim Method for the Determination
 of Asbestos in Bulk Insulation Samples EPA 600/4-82-020

APPROVED: _____

Scott Trasher

This report may not be used to
 claim product endorsement by
 NVLAP or any agency of the
 U.S. Government.

File: CWL.PLM

Building: MBA. Adm. Classroom

Functional Area No. 23-A23-AS Location: Hallway, ceiling.

Type of Suspect Material: ☒ Surfacing, ☐ TSI, ☐ Other

Description: plastered on material. gritty.

Approximate Amount of Material (linear or square ft.): 3700 sq. ft.

Condition

Percent Damage: 2 %, ☐ Localized, ☒ Distributed

Type of Damage: ☐ Deterioration, ☒ Water, ☐ Physical

Description: Generally in good condition.

Overall Rating: ☒ Good, ☐ Fair, ☐ Poor

Potential for Disturbance

Accessibility: ☐ Accessible, ☒ Inaccessible

Description: Ceiling is too high for normal contact

Potential for Contact: ☐ High, ☐ Moderate, ☒ Low

Description: _____

Influence of Vibration: ☐ High, ☐ Moderate, ☒ Low

Description: _____

Potential for Air Erosion: ☐ High, ☐ Moderate, ☒ Low

Description: _____

Located in a Plenum? ☐ Yes, ☒ No;

Type: _____

Comments: _____

Signed: AE.

Date: 12-22-88

CERTIFICATE OF ANALYSIS

LAB I.D.: P-74182
 SAMPLE LOCATION: 23-A23-AS
 COLLECTED BY: Client
 DATE COLLECTED: Not Given

DATE RECEIVED: December 27, 1988
 DATE STARTED: January 5, 1989
 DATE COMPLETED: January 5, 1989
 DATE REPORTED: January 10, 1989

CLIENT: Eslinger, Herbert
 STREET: 9545 W. Hwy 152
 CITY: Dos Palos
 STATE: CA

ZIP: 93620

PURCHASE ORDER: N/A
 OFW #: L8839
 COPY TO: No cc Req.

PLM ANALYSIS

Analyte	Results Volume %	Detect Limit Volume %
ASBESTOS		
CHRYSTILE	ND	1. %
ANOSITE	ND	1. %
CROCIDOLITE	ND	1. %
ANTHOPHYLITE	ND	1. %
TREMOLITE-ACTONOLITE	ND	1. %
FIBER GLASS	ND	1. %
MINERAL WOOL	ND	1. %
CELLULOSE	1-2 %	1. %
NON FIBROUS MATERIALS	98-99 %	1. %
COLOR	White	

Method: EPA Interim Method for the Determination
 of Asbestos in Bulk Insulation Samples

EPA 600/4-82-020

APPROVED: _____

Scott Foster

This report may not be used to
 claim product endorsement by
 NVLAP or any agency of the

U.S. Government.
 File: CWL.PLM

Building: MBA - adm + classroom

Functional Area No. 23-A5-T Location: business office

Type of Suspect Material: Surfacing, TSI, ☒ Other

Description: 12x12 ceiling tile

Approximate Amount of Material (linear or square ft.): 1000

Condition

Percent Damage: 8 %, Localized, ☒ Distributed

Type of Damage: Deterioration, Water, Physical

Description: tile broken off - water spots

Overall Rating: Good, ☒ Fair, Poor

Potential for Disturbance

Accessibility: Accessible, ☒ Inaccessible

Description: _____

Potential for Contact: High, Moderate, ☒ Low

Description: _____

Influence of Vibration: High, Moderate, ☒ Low

Description: _____

Potential for Air Erosion: High, Moderate, ☒ Low

Description: _____

Located in a Plenum? Yes, ☒ No; Type: _____

Comments: _____

Signed: ge Date: 12-22-88

CERTIFICATE OF ANALYSIS

LAB I.D.: P-74101
 SAMPLE LOCATION: 23-A5-T
 COLLECTED BY: Client
 DATE COLLECTED: Not Given

DATE RECEIVED: December 27, 1988
 DATE STARTED: January 5, 1989
 DATE COMPLETED: January 5, 1989
 DATE REPORTED: January 10, 1989

CLIENT: Eslinger, Herbert
 STREET: 9545 W. Hwy 152
 CITY: Dos Palos
 STATE: CA ZIP: 93620

PURCHASE ORDER: N/A
 OFW #: L0839
 COPY TO: No cc Req.

PLH ANALYSIS

Analyte	Results Volume %	Detect Limit Volume %
ASBESTOS		
CHRYSTOTILE	ND	1. %
AMOSITE	ND	1. %
CROCIDOLITE	ND	1. %
ANTHOPHYLITE	ND	1. %
TREMOLITE-ACTONOLITE	ND	1. %
FIBER GLASS	ND	1. %
MINERAL WOOL	ND	1. %
CELLULOSE	100 %	1. %
NON FIBROUS MATERIALS	ND	1. %
COLOR	Brown	

Method: EPA Interim Method for the Determination
 of Asbestos in Bulk Insulation Samples EPA 600/4-82-020

APPROVED: 

This report may not be used to
 claim product endorsement by
 NVLAP or any agency of the
 U.S. Government.

File: CWL.PLH

Building: MBA - Adm. building
 Functional Area No. 23-A7-T Location: vault

Type of Suspect Material: Surfacing, TSI, ☒ Other

Description: 9x9 floor tile

Approximate Amount of Material (linear or square ft.): 175

Condition

Percent Damage: 0 %, Localized, Distributed

Type of Damage: Deterioration, Water, Physical

Description: _____

Overall Rating: ☒ Good, Fair, Poor

Potential for Disturbance

Accessibility: ☒ Accessible, Inaccessible

Description: _____

Potential for Contact: High, ☒ Moderate, Low

Description: _____

Influence of Vibration: High, Moderate, ☒ Low

Description: _____

Potential for Air Erosion: High, Moderate, ☒ Low

Description: _____

Located in a Plenum? Yes, ☒ No; Type: _____

Comments: _____

Signed: ge Date: 12-22-88

CERTIFICATE OF ANALYSIS

LAB I.D.: P-74100
 SAMPLE LOCATION: 23-A7-T
 COLLECTED BY: Client
 DATE COLLECTED: Not Given

DATE RECEIVED: December 27, 1988
 DATE STARTED: January 5, 1989
 DATE COMPLETED: January 5, 1989
 DATE REPORTED: January 10, 1989

CLIENT: Eslinger, Herbert
 STREET: 9545 W. Hwy 152
 CITY: Dos Palos
 STATE: CA ZIP: 93620

PURCHASE ORDER: N/A
 OFW #: L0839
 COPY TO: No cc Req.

PLM ANALYSIS

Analyte	Results Volume %	Detect Limit, Volume %
ASBESTOS		
CHRYSTILE	ND	1. %
AMOSITE	ND	1. %
CROCIDOLITE	ND	1. %
ANTHOPHYLITE	ND	1. %
TREHOLITE-ACTONOLITE	ND	1. %
FIBER GLASS	ND	1. %
MINERAL WOOL	ND	1. %
CELLULOSE	ND	1. %
NON FIBROUS MATERIALS	100 %	1. %
COLOR	Gray	

Method: EPA Interim Method for the Determination
 of Asbestos in Bulk Insulation Samples

EPA 600/4-82-020

APPROVED: 

This report may not be used to
 claim product endorsement by
 NVLAP or any agency of the

U.S. Government.

File: CHL.PLM

Building: MBA - Administration + Classroom

Functional Area No. 23-A30-VP Location: Classroom #1 office

Type of Suspect Material: ☒ Surfacing, ☐ TSI, ☐ Other

Description: mint wall paper

Approximate Amount of Material (linear or square ft.): 32

Condition

Percent Damage: 0 %, ☐ Localized, ☐ Distributed

Type of Damage: ☐ Deterioration, ☐ Water, ☐ Physical

Description: _____

Overall Rating: ☒ Good, ☐ Fair, ☐ Poor

Potential for Disturbance

Accessibility: ☒ Accessible, ☐ Inaccessible

Description: _____

Potential for Contact: ☐ High, ☒ Moderate, ☐ Low

Description: _____

Influence of Vibration: ☐ High, ☐ Moderate, ☒ Low

Description: _____

Potential for Air Erosion: ☐ High, ☐ Moderate, ☒ Low

Description: _____

Located in a Plenum? ☐ Yes, ☐ No; Type: _____

Comments: _____

Signed: GP Date: 12-22-88

CERTIFICATE OF ANALYSIS

LAB I.D.: P-74088
 SAMPLE LOCATION: 23-A30-VP
 COLLECTED BY: Client
 DATE COLLECTED: Not Given

DATE RECEIVED: December 27, 1988
 DATE STARTED: January 4, 1989
 DATE COMPLETED: January 4, 1989
 DATE REPORTED: January 10, 1989

CLIENT: Eslinger, Herbert
 STREET: 9545 W. Hwy 152
 CITY: Dos Palos
 STATE: CA ZIP: 93620

PURCHASE ORDER: N/A
 OFW #: L0839
 COPY TO: No cc Req.

PLN ANALYSIS

Analyte	Results Volume %	Detect Limit Volume %
ASBESTOS		
CHRYSTILE	ND	1. %
AMOSITE	ND	1. %
CROCIDOLITE	ND	1. %
ANTHOPHYLITE	ND	1. %
TREMOLITE-ACTONOLITE	ND	1. %
FIBER GLASS	ND	1. %
MINERAL WOOL	ND	1. %
CELLULOSE	70-75 %	1. %
NON FIBROUS MATERIALS	25-30 %	1. %
COLOR	Brown & White	

Method: EPA Interim Method for the Determination
 of Asbestos in Bulk Insulation Samples EPA 600/4-82-020

This report may not be used to
 claim product endorsement by
 IVLAP or any agency of the
 U.S. Government.

File: CHL.PLM

APPROVED: 

SCHOOL:

MBA. Music behind chapel.

ROOM #	ROOM NAME	FLOOR COVERING	WALL TEXTURE	CEILING TEXTURE	MISC. COVERING	REMARKS
6	mm. R.R.	cr. tile	SR	SR		
29	Studio 3	opt over 9x9	brng w/p SR	12x12		sample
22	hallway	"	plas.	plas.?		sample?
28	studio 3 storage	9x9	SR	SR		same as 17th fl tile
5	rehearsal rm.	opt over 9x9	SK & 12x12	12x12	(sample 9x9)	(sm. holes) sample
13	practice 8	"	masonry & 12x12	12x12		sample
8	" 12	"	"	"		
9	" 11	"	"	"		
10	" 10	"	"	"		
11	" 9	"	"	"		
12	dark piano	"	panel & 12x12	12x12		12x12 tile has been painted
14	practice 17	"	masonry & 12x12	12x12		and seems to have sealed the
15	" 6	"	"	"		fibers in tile
16	" 5	"	"	"		found loose being released.
17	" 4	"	"	"		
18	" 3	"	"	"		
19	" 2	"	"	"		
20	" 1	"	"	"		
21	women's R.R.	ceram tile	SR	SR		
23	instrumental music	opt over 9x9	SR	12x12		
24	Jamton	9x9	"	SR		dark brown, sample
26	keyboard (Kemp) / Music	opt over 9x9	plas.	12x12		
30	Choir - voice	opt	SR.	"		
27	" storage	vinyl	wood	wood		sample

South wing

NO. 1 wing

ASSEMBLY HALL ①

MONTEREY BAY SDA ACADEMY

ADMINISTRATIVE BLDG

MUSIC DEPT.


PART EXTENDED FROM FRONTAL BLDG

15. 9,900 sqft
Plus. 900 upstairs.

10,800 TOTAL

OPEN RASTER

CHOIR REHEARSAL UPSTAIRS ③



Building: M T - Music Dept.
Functional Area No. 23-M5-T Location: rehearsal room
Type of Suspect Material: Surfacing, TSI, ☒ Other
Description: 9x9 tile - green - carpet over tile.
Same as utility in girls dorm, all practice rooms,
office of Umbrella Plant, Industrial Art, wood shop office.
Approximate Amount of Material (linear or square ft.): 450

Condition

Percent Damage: ? %, Localized, Distributed
Type of Damage: Deterioration, Water, Physical
Description: nails have been nailed through to lay the
carpet
Overall Rating: Good, Fair, Poor

Potential for Disturbance

Accessibility: Accessible, ☒ Inaccessible
Description: under carpet
Potential for Contact: High, Moderate, ☒ Low
Description:
Influence of Vibration: High, Moderate, ☒ Low
Description:
Potential for Air Erosion: High, Moderate, ☒ Low
Description:

Located in a Plenum? Yes, ☒ No; Type:

Comments:

Signed: ge Date: 12-22-88

CERTIFICATE OF ANALYSIS

LAB I.D.: P-74104
 SAMPLE LOCATION: 23-M5-T
 COLLECTED BY: Client
 DATE COLLECTED: Not Given

DATE RECEIVED: December 27, 1988
 DATE STARTED: January 6, 1989
 DATE COMPLETED: January 6, 1989
 DATE REPORTED: January 10, 1989

CLIENT: Eslinger, Herbert
 STREET: 9545 W. Hwy 152
 CITY: Dos Palos
 STATE: CA

ZIP: 93620

PURCHASE ORDER: N/A
 OFW #: L0839
 COPY TO: No cc Req.

PLM ANALYSIS

Analyte	Results Volume %	Detect Limit Volume %
ASBESTOS		
CHRYSTILE	1-2 %	1. %
AMOSITE	ND	1. %
CROCIDOLITE	ND	1. %
ANTHOPHYLITE	ND	1. %
TREMOLITE-ACTONOLITE	ND	1. %
FIBER GLASS	ND	1. %
MINERAL WOOL	ND	1. %
CELLULOSE	ND	1. %
NON FIBROUS MATERIALS	98-99 %	1. %
COLOR	Green	

Method: EPA Interim Method for the Determination
 of Asbestos in Bulk Insulation Samples EPA 600/4-82-020

APPROVED: 

This report may not be used to
 claim product endorsement by
 NVLAP or any agency of the

U.S. Government.
 File: CHL.PLM

Building: NBS A - MainFunctional Area No. 23-M24-V Location: JanitorType of Suspect Material: Surfacing, TSI, ☒ OtherDescription: 9x9 tileApproximate Amount of Material (linear or square ft.): 64ConditionPercent Damage: 2 %, ☒ Localized, DistributedType of Damage: Deterioration, Water, ☒ Physical

Description: _____

Overall Rating: ☒ Good, Fair, PoorPotential for DisturbanceAccessibility: ☒ Accessible, Inaccessible

Description: _____

Potential for Contact: High, Moderate, ☒ LowDescription: authorized personnelInfluence of Vibration: High, Moderate, ☒ Low

Description: _____

Potential for Air Erosion: High, Moderate, ☒ Low

Description: _____

Located in a Plenum? Yes, ☒ No; Type: _____

Comments: _____

Signed: JK Date: 12-22-88

CERTIFICATE OF ANALYSIS

LAB I.D.: P-74888
 SAMPLE LOCATION: 23-M24-V
 COLLECTED BY: Client
 DATE COLLECTED: Not Given

DATE RECEIVED: December 27, 1988
 DATE STARTED: January 5, 1989
 DATE COMPLETED: January 5, 1989
 DATE REPORTED: January 10, 1989

CLIENT: Eslinger, Herbert
 STREET: 9545 W. Hwy 152
 CITY: Dos Palos
 STATE: CA ZIP: 93620

PURCHASE ORDER: N/A
 OFW #: L0839
 COPY TO: No cc Req.

PLH ANALYSIS

Analyte	Results Volume %	Detect Limit Volume %
ASBESTOS		
CHRYSTOTILE	1-2 %	1. %
AMOSITE	ND	1. %
CROCIDOLITE	ND	1. %
ANTHOPHYLITE	ND	1. %
TRENDLITE-ACTONOLITE	ND	1. %
FIBER GLASS	ND	1. %
MINERAL WOOL	ND	1. %
CELLULOSE	ND	1. %
NON FIBROUS MATERIALS	98-99 %	1. %
COLOR	Brown	

Method: EPA Interim Method for the Determination
 of Asbestos in Bulk Insulation Samples EPA 600/4-82-020

This report may not be used to
 claim product endorsement by
 NVLAP or any agency of the
 U.S. Government.
 File: CWL.PLM

APPROVED: 

Building: 3A - Music Dept.
Functional Area No. 23-M28-T Location: Studio 3 storage
Type of Suspect Material: Surfacing, TSI, ☒ Other
Description: 9x9 tile - same as in the vault. - white/green

Approximate Amount of Material (linear or square ft.): 120

Condition

Percent Damage: 0 %, Localized, Distributed
Type of Damage: Deterioration, Water, Physical
Description: _____

Overall Rating: ☒ Good, Fair, Poor

Potential for Disturbance

Accessibility: ☒ Accessible, Inaccessible

Description: _____

Potential for Contact: High, ☒ Moderate, Low

Description: _____

Influence of Vibration: High, Moderate, ☒ Low

Description: _____

Potential for Air Erosion: High, Moderate, ☒ Low

Description: _____

Located in a Plenum? Yes, ☒ No; Type: _____

Comments: _____

Signed: [Signature] Date: 12-22-88

CERTIFICATE OF ANALYSIS

LAB I.D.: P-74108
SAMPLE LOCATION: 23-M28-T
COLLECTED BY: Client
DATE COLLECTED: Not Given

DATE RECEIVED: December 27, 1988
DATE STARTED: January 6, 1989
DATE COMPLETED: January 6, 1989
DATE REPORTED: January 10, 1989

CLIENT: Eslinger, Herbert
STREET: 9545 W. Hwy 152
CITY: Dos Palos
STATE: CA ZIP: 93620

PURCHASE ORDER: N/A
OFW #: L8839
COPY TO: No cc Req.

PLM ANALYSIS

Analyte -----	Results Volume % -----	Detect Limit Volume % -----
ASBESTOS		
CHRYSTOLITE	ND	1. %
AMOSITE	ND	1. %
CROCIDOLITE	ND	1. %
ANTHOPHYLITE	ND	1. %
TREMOLITE-ACTONOLITE	ND	1. %
FIBER GLASS	ND	1. %
MINERAL WOOL	ND	1. %
CELLULOSE	ND	1. %
NON FIBROUS MATERIALS	100 %	1. %
COLOR	Gray	

Method: EPA Interim Method for the Determination
of Asbestos in Bulk Insulation Samples EPA 600/4-82-020

APPROVED: 

This report may not be used to
claim product endorsement by
NVLAP or any agency of the
U.S. Government.

File: CWL.PLM

Building: TBA - Music dept.

Functional Area No. 23-M22-A5 Location: hallway

Type of Suspect Material: ☒ Surfacing, ☐ TSI, ☐ Other

Description: sprayed on plaster-like material

Approximate Amount of Material (linear or square ft.): 900

Condition

Percent Damage: 2 %, ☐ Localized, ☒ Distributed

Type of Damage: ☒ Deterioration, ☐ Water, ☐ Physical

Description: _____

Overall Rating: ☒ Good, ☐ Fair, ☐ Poor

Potential for Disturbance

Accessibility: ☒ Accessible, ☐ Inaccessible

Description: weathered its 8 ft up - student likes to jump and hit it.

Potential for Contact: ☐ High, ☒ Moderate, ☐ Low

Description: _____

Influence of Vibration: ☐ High, ☐ Moderate, ☒ Low

Description: _____

Potential for Air Erosion: ☐ High, ☐ Moderate, ☒ Low

Description: _____

Located in a Plenum? ☐ Yes, ☒ No; Type: _____

Comments: _____

Signed: ge Date: 12-22-88

CERTIFICATE OF ANALYSIS

LAB I.D.: P-74106
SAMPLE LOCATION: 23-M22-AS
COLLECTED BY: Client
DATE COLLECTED: Not Given

DATE RECEIVED: December 27, 1988
DATE STARTED: January 6, 1989
DATE COMPLETED: January 6, 1989
DATE REPORTED: January 10, 1989

CLIENT: Eslinger, Herbert
STREET: 9545 N. Hwy 152
CITY: Dos Palos
STATE: CA ZIP: 93620

PURCHASE ORDER: N/A
OFN #: L8839
COPY TO: No cc Req.

PLM ANALYSIS

Analyte	Results Volume %	Detect Limit Volume %
ASBESTOS		
CHRYSTILE	ND	1. %
AMOSITE	ND	1. %
CROCIDOLITE	ND	1. %
ANTHOPHYLITE	ND	1. %
TREMOLITE-ACTONOLITE	ND	1. %
FIBER GLASS	ND	1. %
MINERAL WOOL	ND	1. %
CELLULOSE	ND	1. %
NON FIBROUS MATERIALS	100 %	1. %
COLOR	White	

Method: EPA Interim Method for the Determination
of Asbestos in Bulk Insulation Samples EPA 600/4-82-020

This report may not be used to
claim product endorsement by
NVLAP or any agency of the
U.S. Government.

File: CWL.PLM

APPROVED: Scott Foster

MBA - Computer Rm. (doublewide trailer)

[illegible]

Building: MBA - Industrial Arts
Functional Area No. 23-I4-T Location: woodshop office
Type of Suspect Material: Surfacing, TSI, ☒ Other
Description: 9x9 floor tile - green - same tile in
office of MRR Package, utility rm. in girls dorm.
Approximate Amount of Material (linear or square ft.): 505

Condition

Percent Damage: 2 %, ☒ Localized, Distributed
Type of Damage: Deterioration, Water, ☒ Physical
Description:

Overall Rating: ☒ Good, Fair, Poor

Potential for Disturbance

Accessibility: ☒ Accessible, Inaccessible

Description:

Potential for Contact: High, ☒ Moderate, Low

Description:

Influence of Vibration: High, Moderate, ☒ Low

Description:

Potential for Air Erosions: High, Moderate, ☒ Low

Description:

Located in a Plenum? Yes, ☒ No; Type:

Comments:

Signed: gf Date: 12-22-88

CERTIFICATE OF ANALYSIS

LAB I.D.: P-74098
SAMPLE LOCATION: 23-14-7
COLLECTED BY: Client
DATE COLLECTED: Not Given

DATE RECEIVED: December 27, 1988
DATE STARTED: January 5, 1989
DATE COMPLETED: January 5, 1989
DATE REPORTED: January 10, 1989

CLIENT: Eslinger, Herbert
STREET: 9545 W. Hwy 152
CITY: Dos Palos
STATE: CA ZIP: 93620

PURCHASE ORDER: N/A
OFW #: L8839
COPY TO: No cc Req.

PLN ANALYSIS

Analyte	Results Volume %	Detect Limit Volume %
ASBESTOS		
CHRYSTILE	1-2 %	1. %
AMOSITE	ND	1. %
CROCIDOLITE	ND	1. %
ANTHOPHYLITE	ND	1. %
TREMOLITE-ACTONOLITE	ND	1. %
FIBER GLASS	ND	1. %
MINERAL WOOL	ND	1. %
CELLULOSE	ND	1. %
NON FIBROUS MATERIALS	98-99 %	1. %
COLOR	Green	

Method: EPA Interim Method for the Determination
of Asbestos in Bulk Insulation Samples

EPA 600/4-82-020

APPROVED: 

This report may not be used to
claim product endorsement by
NVLAP or any agency of the
U.S. Government.

File: CHL.PLM

Building: MBA - Industrial Arts
Functional Area No. 23-13-T Location: photograph
Type of Suspect Material: Surfacing, TSI, ☒ Other
Description: 9x9 floor tile, also in dark room
- Tan w/ brown stripes
Approximate Amount of Material (linear or square ft.): 450

Condition

Percent Damage: 2 %, ☒ Localized, Distributed
Type of Damage: Deterioration, Water, ☒ Physical
Description: _____

Overall Rating: ☒ Good, Fair, Poor

Potential for Disturbance

Accessibility: ☒ Accessible, Inaccessible

Description: _____

Potential for Contact: High, ☒ Moderate, Low

Description: _____

Influence of Vibration: High, Moderate, ☒ Low

Description: _____

Potential for Air Erosion: High, Moderate, ☒ Low

Description: _____

Located in a Plenum? Yes, ☒ No; Type: _____

Comments: _____

Signed: gc Date: 12-22-88

CERTIFICATE OF ANALYSIS

LAB I.D.: P-74093
 SAMPLE LOCATION: 23-13-T
 COLLECTED BY: Client
 DATE COLLECTED: Not Given

DATE RECEIVED: December 27, 1988
 DATE STARTED: January 5, 1989
 DATE COMPLETED: January 5, 1989
 DATE REPORTED: January 10, 1989

CLIENT: Eslinger, Herbert
 STREET: 9545 W. Hwy 152
 CITY: Dos Palos
 STATE: CA

ZIP: 93620

PURCHASE ORDER: N/A
 OFW #: L8839
 COPY TO: No cc Req.

PLM ANALYSIS

Analyte	Results Volume %	Detect Limit Volume %
ASBESTOS		
CHRYSTILE	ND	1. %
AMOSITE	ND	1. %
CROCIDOLITE	ND	1. %
ANTHOPHYLITE	ND	1. %
TRENOLITE-ACTONOLITE	ND	1. %
FIBER GLASS	ND	1. %
MINERAL WOOL	ND	1. %
CELLULOSE	ND	1. %
NON FIBROUS MATERIALS	100 %	1. %
COLOR	Gray	

Method: EPA Interim Method for the Determination
 of Asbestos in Bulk Insulation Samples

EPA 600/4-82-020


report may not be used to
 claim product endorsement by
 IVLAP or any agency of the
 U.S. Government.
 File: CWL.PLM

APPROVED: 

SCHOOL:

MBA Pictoria

ROOM #	ROOM NAME	FLOOR COVERING	WALL TEXTURE	CEILING TEXTURE	MISC. COVERING	REMARKS
1	dining hall	crpt + 12x12 tile	plas + SR Vinyl W.P.	SR		sample - w.p.
17	swimming area	6x6 cer. tile	SR, + W.P.	12x12	sample (2) (boys end)	fair - few holes. worse than girl's. diff. 12x12
8	kitchen	" + troyel	6x6 cer. tile SR	SR		
12	store area	troyel	plas.	plas.	asbestos p.c. &	ends are bad - few 145 lin. bad nich. need repair ft.
10	refrigerator by back exit	"	plas.	plas.	pipe covering	sample
9	dairy rid.	troyel	plas.	plas.	"	6 spot to repair (has been painted) good condit. 45 lin. ft. (23 m. l. eq.)
7	kitchen storage	conc.	SR	SR	P.C.	kept locked
6	baking - ice room	9x9 tile (2)	SR vinyl W.P.	SR	P.C.	ends need sealed & sample w.p.
	9x9 tile around ice machine					is very poor & need repaired
5	kitchen office	crpt over 9x9	plas. + SR	SR		
4	office (storage)	9x9	plas.	plas.		brown tile
2	girls entrance (N)	12x12	plas.	12x12		
3	" RR.	cer. tile	SR	SR		
16	main entrance (S)	12x12	plas.	12x12		ceiling poor
	roof has	asbestos	slates	shingles		- assumed.



Monterey Bay Academy
Cafeteria
sq. ft. 12,510

Building: IBA - Cafeteria

Functional Area No. 23-C4-T Location: office storage

Type of Suspect Material: Surfacing, TSI, ☒ Other

Description: 9x9 floor tile - brown

same as tile in Janitor's Rm. in Music Dept.

Approximate Amount of Material (linear or square ft.): 18

Condition

Percent Damage: 2 %, Localized, ☒ Distributed

Type of Damage: Deterioration, Water, ☒ Physical

Description: _____

Overall Rating: ☒ Good, Fair, Poor

Potential for Disturbance

Accessibility: ☒ Accessible, Inaccessible

Description: _____

Potential for Contact: High, ☒ Moderate, Low

Description: _____

Influence of Vibration: High, Moderate, ☒ Low

Description: _____

Potential for Air Erosion: High, Moderate, ☒ Low

Description: _____

Located in a Plenum? Yes, ☒ No; Type: _____

Comments: _____

Signed: ge Date: 12-22-88

CERTIFICATE OF ANALYSIS

LAB I.D.: P-74086
 SAMPLE LOCATION: 23-C4-T
 COLLECTED BY: Client
 DATE COLLECTED: Not Given

DATE RECEIVED: December 27, 1988
 DATE STARTED: January 5, 1989
 DATE COMPLETED: January 5, 1989
 DATE REPORTED: January 10, 1989

CLIENT: Eslinger, Herbert
 STREET: 9545 W. Hwy 152
 CITY: Dos Palos
 STATE: CA
 ZIP: 93620

PURCHASE ORDER: N/A
 OFW #: L0839
 COPY TO: No cc Req.

PLM ANALYSIS

Analyte	Results Volume %	Detect Limit Volume %
ASBESTOS		
CHRYSTILE	1-2 %	1. %
ANOSITE	ND	1. %
CROCIDOLITE	ND	1. %
ANTHOPHYLITE	ND	1. %
TREMOLITE-ACTONOLITE	ND	1. %
FIBER GLASS	ND	1. %
MINERAL WOOL	ND	1. %
CELLULOSE	ND	1. %
NON FIBROUS MATERIALS	98-99 %	1. %
COLOR	Brown	

Method: EPA Interim Method for the Determination
 of Asbestos in Bulk Insulation Samples EPA 600/4-82-028

Report may not be used to
 claim product endorsement by
 NVLAP or any agency of the
 U.S. Government.

APPROVED: *Scott Foster*

File: CHL.PLM

Building: MBA - Cafeteria
 Functional Area No. 23-C1-V Location: Dining Room in Cafeteria
 Type of Suspect Material: ☒ Surfacing, ☐ TSI, ☐ Other
 Description: vinyl wall paper - red brick -

Approximate Amount of Material (linear or square ft.): 200

Condition

Percent Damage: 0 %, ☐ Localized, ☐ Distributed
 Type of Damage: ☐ Deterioration, ☐ Water, ☐ Physical
 Description: _____

Overall Rating: ☒ Good, ☐ Fair, ☐ Poor

Potential for Disturbance

Accessibility: ☒ Accessible, ☐ Inaccessible
 Description: _____

Potential for Contact: ☐ High, ☒ Moderate, ☐ Low
 Description: _____

Influence of Vibration: ☐ High, ☐ Moderate, ☒ Low
 Description: _____

Potential for Air Erosion: ☐ High, ☐ Moderate, ☒ Low
 Description: _____

Located in a Plenum? ☐ Yes, ☒ No; Type: _____

Comments: _____

Signed: ge Date: 12-22-88

CERTIFICATE OF ANALYSIS

LAB I.D.: P-74105
 SAMPLE LOCATION: 23-C1-V
 COLLECTED BY: Client
 DATE COLLECTED: Not Given

DATE RECEIVED: December 27, 1988
 DATE STARTED: January 6, 1989
 DATE COMPLETED: January 6, 1989
 DATE REPORTED: January 10, 1989

CLIENT: Eslinger, Herbert
 STREET: 9545 W. Hwy 152
 CITY: Dos Palos
 STATE: CA

ZIP: 93620

PURCHASE ORDER: N/A
 OFW #: L8839
 COPY TO: No cc Req.

PLH ANALYSIS

Analyte	Results Volume %	Detect Limit Volume %
ASBESTOS		
CHRYSTOLITE	3-5 %	1. %
AMOSITE	ND	1. %
CROCIDOLITE	ND	1. %
ANTHOPHYLITE	ND	1. %
TREMOLITE-ACTONOLITE	ND	1. %
FIBER GLASS	ND	1. %
MINERAL WOOL	ND	1. %
CELLULOSE	ND	1. %
NON FIBROUS MATERIALS	95-97 %	1. %
COLOR	Brown & White	

Method: EPA Interim Method for the Determination
 of Asbestos in Bulk Insulation Samples

EPA 600/4-82-020

APPROVED: 

This report may not be used to
 claim product endorsement by
 NVLAP or any agency of the
 U.S. Government.

File: CWL.PLM

Building: MBA - CafeteriaFunctional Area No. 23-C12-PT Location: store area in CafeteriaType of Suspect Material: Surfacing, ☒ TSI, OtherDescription: pipe covering - also in kitchen back exit, kitchen storage, hallway,Approximate Amount of Material (linear or square ft.): 110ConditionPercent Damage: 2 %, ☒ Localized, DistributedType of Damage: ☒ Deterioration, Water, PhysicalDescription: these localized areas need patched & sealed. all areas should be sealed.Overall Rating: ☒ Good, Fair, PoorPotential for DisturbanceAccessibility: ☒ Accessible, InaccessibleDescription: some of the insulation has been nicked, could have been by boxes.Potential for Contact: High, ☒ Moderate, LowDescription: Influence of Vibration: High, ☒ Moderate, LowDescription: when system runs - kicks on & off.Potential for Air Erosion: High, ☒ Moderate, LowDescription: fans circulating the air.Located in a Plenum? Yes, No; Type: Comments: Signed: gf Date: 12-22-88

CERTIFICATE OF ANALYSIS

LAB I.D.: P-74099
 SAMPLE LOCATION: 23-C12-P1
 COLLECTED BY: Client
 DATE COLLECTED: Not Given

DATE RECEIVED: December 27, 1988
 DATE STARTED: January 5, 1989
 DATE COMPLETED: January 5, 1989
 DATE REPORTED: January 10, 1989

CLIENT: Eslinger, Herbert
 STREET: 9545 W. Hwy 152
 CITY: Dos Palos
 STATE: CA ZIP: 93620

PURCHASE ORDER: N/A
 OFW #: L0839
 COPY TO: No cc Req.

PLM ANALYSIS

Analyte -----	Results Volume % -----	Detect Limit Volume % -----
ASBESTOS		
CHRYSTOLITE	70-75 %	1. %
AMOSITE	ND	1. %
CROCIDOLITE	ND	1. %
ANTHOPHYLITE	ND	1. %
TREHOLITE-ACTONOLITE	ND	1. %
FIBER GLASS	ND	1. %
MINERAL WOOL	ND	1. %
CELLULOSE	ND	1. %
NON FIBROUS MATERIALS	25-30 %	1. %
COLOR	White	

Method: EPA Interim Method for the Determination
 of Asbestos in Bulk Insulation Samples

EPA 600/4-82-020

This report may not be used to
 claim product endorsement by
 NVLAP or any agency of the
 U.S. Government.

File: CWL.PLM

APPROVED: 

Building: MBA - Cafeteria
 Functional Area No. 23-C17-T Location: Cafeteria service area (men's side)
 Type of Suspect Material: Surfacing TSI ☒ Other
 Description: 12x12 ceiling tile - same as men's entrance

Approximate Amount of Material (linear or square ft.): 270

Condition

Percent Damage: 10 %, Localized ☒ Distributed
 Type of Damage: Deterioration Water ☒ Physical
 Description: Tiles breaking, students disturbing with sharp & blunt objects. - some are breaking loose.
 Overall Rating: Good Fair ☒ Poor

Potential for Disturbance

Accessibility: ☒ Accessible, Inaccessible
 Description: _____

Potential for Contact: High ☒ Moderate, Low
 Description: Students are reaching the ceiling with objects.

Influence of Vibration: High ☒ Moderate, Low
 Description: _____

Potential for Air Eruption: High ☒ Moderate, Low
 Description: fans are circulating the air.

Located in a Plenum? Yes ☒ No; Type: _____

Comments: _____

Signed: gc Date: 12-22-88

CERTIFICATE OF ANALYSIS

LAB I.D.: P-74002
 SAMPLE LOCATION: 23-C17-T
 COLLECTED BY: Client
 DATE COLLECTED: Not Given

DATE RECEIVED: December 27, 1988
 DATE STARTED: January 4, 1989
 DATE COMPLETED: January 4, 1989
 DATE REPORTED: January 10, 1989

CLIENT: Eslinger, Herbert
 STREET: 9545 W. Hwy 152
 CITY: Dos Palos
 STATE: CA ZIP: 93620

PURCHASE ORDER: N/A
 OFN #: L0839
 COPY TO: No cc Req.

PLM ANALYSIS

Analyte	Results Volume %	Detect Limit Volume %
ASBESTOS		
CHRYSTOTILE	ND	1. %
ANOSITE	ND	1. %
CROCIDOLITE	ND	1. %
ANTHOPHYLITE	ND	1. %
TRENOLITE-ACTONOLITE	ND	1. %
FIBER GLASS	ND	1. %
MINERAL WOOL	ND	1. %
CELLULOSE	ND	1. %
NON FIBROUS MATERIALS	100 %	1. %
COLOR	White	

Method: EPA Interia Method for the Determination
 of Asbestos in Bulk Insulation Samples

EPA 600/4-82-020

This report may not be used to
 claim product endorsement by
 NVLAP or any agency of the
 U.S. Government.

File: CHL.PLM

APPROVED: _____

[Signature]

Building: MBA - Cafeteria
 Functional Area No. 23-C6-T Location: pantry - ice room
 Type of Suspect Material: Surfacing, TSI, ☒ Other
 Description: 9x9 floor tile - grey

Approximate Amount of Material (linear or square ft.): 420

Condition

Percent Damage: 30%, ☒ Localized, Distributed
 Type of Damage: ☒ Deterioration, Water, ☒ Physical
 Description: tiles missing + broken + loose

Overall Rating: Good, Fair, ☒ Poor

Potential for Disturbance

Accessibility: ☒ Accessible, Inaccessible
 Description: _____

Potential for Contact: High, ☒ Moderate, Low
 Description: _____

Influence of Vibration: High, ☒ Moderate, Low
 Description: tiles loose

Potential for Air Erosion: High, Moderate, ☒ Low
 Description: _____

Located in a Plenum? Yes, ☒ No; Type: _____

Comments: _____

Signed: g Date: 12-22-88

CERTIFICATE OF ANALYSIS

LAB I.D.: P-74096
 SAMPLE LOCATION: 23-C6-T
 COLLECTED BY: Client
 DATE COLLECTED: Not Given

DATE RECEIVED: December 27, 1988
 DATE STARTED: January 5, 1989
 DATE COMPLETED: January 5, 1989
 DATE REPORTED: January 10, 1989

CLIENT: Eslinger, Herbert
 STREET: 9545 W. Hwy 152
 CITY: Dos Palos
 STATE: CA

ZIP: 93620

PURCHASE ORDER: N/A
 OFW #: L0839
 COPY TO: No cc Req.

P.L.H. ANALYSIS

Analyte	Results Volume %	Detect Limit Volume %
ASBESTOS		
CHRYSTOLE	ND	1. %
AMOSITE	ND	1. %
CROCIDOLITE	ND	1. %
ANTHOPHYLITE	ND	1. %
TREMOLITE-ACTONDLITE	ND	1. %
FIBER GLASS	ND	1. %
MINERAL WOOL	ND	1. %
CELLULOSE	ND	1. %
NON FIBROUS MATERIALS	100 %	1. %
COLOR	Gray	

Method: EPA Interim Method for the Determination
 of Asbestos in Bulk Insulation Samples

EPA 600/4-82-020

APPROVED: 

This report may not be used to
 claim product endorsement by
 NVLAP or any agency of the
 U.S. Government.

File: CHL.PLM

Building: MBA - Cafeteria
Functional Area No. 23-C17-T1 Location: Serving area in Cafeteria
Type of Suspect Material: Surfacing, TSI, Other
Description: 12x12 ceiling tile

Approximate Amount of Material (linear or square ft.): 170

Condition

Percent Damage: 2 %, Localized, ✓ Distributed
Type of Damage: Deterioration, ✓ Water, Physical
Description: _____

Overall Rating: ✓ Good, Fair, Poor

Potential for Disturbance

Accessibility: ✓ Accessible, Inaccessible
Description: girls aren't destroying tiles like boys did

Potential for Contact: High, ✓ Moderate, Low
Description: _____

Influence of Vibration: High, Moderate, ✓ Low
Description: _____

Potential for Air Erosion: High, ✓ Moderate, Low
Description: fans

Located in a Plenum? Yes, ✓ No; Type: _____

Comments: _____

Signed: ge Date: 12-22-88

CERTIFICATE OF ANALYSIS

LAB I.D.: P-74095
 SAMPLE LOCATION: 23-C17-T1
 COLLECTED BY: Client
 DATE COLLECTED: Not Given

DATE RECEIVED: December 27, 1988
 DATE STARTED: January 5, 1989
 DATE COMPLETED: January 5, 1989
 DATE REPORTED: January 10, 1989

CLIENT: Eslinger, Herbert
 STREET: 9545 W. Hwy 152
 CITY: Dos Palos
 STATE: CA

ZIP: 93620

PURCHASE ORDER: N/A
 OFN #: L0839
 COPY TO: No cc Req.

PLM ANALYSIS

Analyte	Results Volume %	Detect Limit Volume %
ASBESTOS		
CHRYSTILE	ND	1. %
AMOSITE	ND	1. %
CROCIDOLITE	ND	1. %
ANTHOPHYLITE	ND	1. %
TREMOLITE-ACTONOLITE	ND	1. %
FIBER GLASS	ND	1. %
MINERAL WOOL	ND	1. %
CELLULOSE	98-99 %	1. %
NON FIBROUS MATERIALS	1-2 %	1. %
COLOR	Brown & White	

Method: EPA Interim Method for the Determination
 of Asbestos in Bulk Insulation Samples

EPA 600/4-82-020

... report may not be used to
 claim product endorsement by
 VLAP or any agency of the
 U.S. Government.
 File: CHL.PLM

APPROVED: 

Building: 11 A - Cafeteria
Functional Area No. 23-C10-B Location: refrigerator (walk-in)
Type of Suspect Material: Surfacing, TSI, Other
Description: large 8" pipe covering

Approximate Amount of Material (linear or square ft.): 10

Condition

Percent Damage: 2%, ✓ Localized, Distributed
Type of Damage: Deterioration, Water, ✓ Physical
Description:

Overall Rating: ✓ Good, Fair, Poor

Potential for Disturbance

Accessibility: ✓ Accessible, Inaccessible
Description:

Potential for Contact: High, ✓ Moderate, Low
Description:

Influence of Vibration: High, Moderate, ✓ Low
Description:

Potential for Air Erosion: High, Moderate, ✓ Low
Description:

Located in a Plenum? Yes, ✓ No; Type:

Comments:

Signed: ge Date: 12-22-88

CERTIFICATE OF ANALYSIS

LAB I.D.: P-74094
 SAMPLE LOCATION: 23-C10-P1
 COLLECTED BY: Client
 DATE COLLECTED: Not Given

DATE RECEIVED: December 27, 1988
 DATE STARTED: January 5, 1989
 DATE COMPLETED: January 5, 1989
 DATE REPORTED: January 10, 1989

CLIENT: Eslinger, Herbert
 STREET: 9545 W. Hwy 152
 CITY: Dos Palos
 STATE: CA

ZIP: 93620

PURCHASE ORDER: N/A
 OFW #: L8839
 COPY TO: No cc Req.

PLM ANALYSIS

Analyte	Results Volume %	Detect Limit Volume %
ASBESTOS		
CHRYSTILE	ND	1. %
AMOSITE	ND	1. %
CROCIDOLITE	ND	1. %
ANTHOPHYLITE	ND	1. %
TREHOLITE-ACTONOLITE	ND	1. %
FIBER GLASS	ND	1. %
MINERAL WOOL	ND	1. %
CELLULOSE	ND	1. %
NON FIBROUS MATERIALS	100 %	1. %
COLOR	Brown & White	

Method: EPA Interim Method for the Determination
 of Asbestos in Bulk Insulation Samples

EPA 600/4-82-020

This report may not be used to
 claim product endorsement by
 NVLAP or any agency of the
 U.S. Government.

File: CWL.PLH

APPROVED: 

Building: BA - Capstone
Functional Area No. 23-C17-V Location: Serving area
Type of Suspect Material: ☒ Surfacing, ☐ TSI, ☐ Other
Description: Vinyl wall paper - brown wheat

Approximate Amount of Material (linear or square ft.): 200

Condition

Percent Damage: 0 %, ☐ Localized, ☐ Distributed
Type of Damage: ☐ Deterioration, ☐ Water, ☐ Physical
Description: _____

Overall Rating: ☒ Good, ☐ Fair, ☐ Poor

Potential for Disturbance

Accessibility: ☒ Accessible, ☐ Inaccessible

Description: _____

Potential for Contact: ☐ High, ☒ Moderate, ☐ Low

Description: _____

Influence of Vibration: ☐ High, ☐ Moderate, ☒ Low

Description: _____

Potential for Air Erosion: ☐ High, ☐ Moderate, ☒ Low

Description: _____

Located in a Plenum? ☐ Yes, ☒ No; Type: _____

Comments: _____

Signed: ge Date: 12-22-88

CERTIFICATE OF ANALYSIS

LAB I.D.: P-74116
SAMPLE LOCATION: 23-C17-V
COLLECTED BY: Client
DATE COLLECTED: Not Given

DATE RECEIVED: December 27, 1988
DATE STARTED: January 6, 1989
DATE COMPLETED: January 6, 1989
DATE REPORTED: January 10, 1989

CLIENT: Eslinger, Herbert
STREET: 9545 W. Hwy 152
CITY: Dos Palos
STATE: CA
ZIP: 93620

PURCHASE ORDER: N/A
OFW #: L0039
COPY TO: No cc Req.

PLM ANALYSIS

Analyte	Results Volume %	Detect Limit Volume %
ASBESTOS		
CHRYSDOTILE	ND	1. %
AMOSITE	ND	1. %
CROCIDOLITE	ND	1. %
ANTHOPHYLITE	ND	1. %
TREMOLITE-ACTONOLITE	ND	1. %
FIBER GLASS	ND	1. %
MINERAL WOOL	ND	1. %
CELLULOSE	30-35 %	1. %
NON FIBROUS MATERIALS	65-70 %	1. %
COLOR	Brown & White.	

Method: EPA Interim Method for the Determination
of Asbestos in Bulk Insulation Samples

EPA 600/4-82-020

This report may not be used to
claim product endorsement by
NVLAP or any agency of the
U.S. Government.

File: CNL.PLM

APPROVED: 

Building: MBA - CatatoniaFunctional Area No. 23-C6-T1 Location: factory - ice roomType of Suspect Material: Surfacing, TSI, ☒ OtherDescription: 9x9 floor tile - blue/whiteApproximate Amount of Material (linear or square ft.): 10ConditionPercent Damage: 5 %, Localized, ☒ DistributedType of Damage: Deterioration, Water, ☒ Physical

Description: _____

Overall Rating: ☒ Good, Fair, PoorPotential for DisturbanceAccessibility: ☒ Accessible, Inaccessible

Description: _____

Potential for Contact: High, ☒ Moderate, Low

Description: _____

Influence of Vibration: High, Moderate, ☒ Low

Description: _____

Potential for Air Erosion: High, Moderate, ☒ Low

Description: _____

Located in a Plenum? Yes, ☒ No; Type: _____

Comments: _____

Signed: ge Date: 12-22-88

CERTIFICATE OF ANALYSIS

LAB I.D.: P-74115
 SAMPLE LOCATION: 23-C6-T1
 COLLECTED BY: Client
 DATE COLLECTED: Not Given

DATE RECEIVED: December 27, 1988
 DATE STARTED: January 6, 1989
 DATE COMPLETED: January 6, 1989
 DATE REPORTED: January 10, 1989

CLIENT: Eslinger, Herbert
 STREET: 9545 W. Hwy 152
 CITY: Dos Palos
 STATE: CA

ZIP: 93620

PURCHASE ORDER: N/A
 OFW #: L0839
 COPY TO: No cc Req.

PLM ANALYSIS

Analyte	Results Volume %	Detect Limit Volume %
ASBESTOS		
CHRYSTOTILE	ND	1. %
AMOSITE	ND	1. %
CROCIDOLITE	ND	1. %
ANTHOPHYLITE	ND	1. %
TREMOLITE-ACTONOLITE	ND	1. %
FIBER GLASS	ND	1. %
MINERAL WOOL	ND	1. %
CELLULOSE	ND	1. %
NON FIBROUS MATERIALS	100 %	1. %
COLOR	Gray	

Method: EPA Interim Method for the Determination
 of Asbestos in Bulk Insulation Samples

EPA 600/4-82-020

This report may not be used to
 claim product endorsement by
 NVLAP or any agency of the
 U.S. Government.

File: CHL.PLM



APPROVED: 

SCHOOL: MBA - Maintenance


[illegible]

MBA



ROOM #	ROOM NAME	FLOOR COVERING	WALL TEXTURE	CEILING TEXTURE	MISC. COVERING	REMARKS
1	Gym	wood	brick	stucco like	4x8 shd.	
	Office & lobby	crst	brick/sr	"		
1	Auto Mechanics	con.	wood	wood.	welding curtain	sample
	Office	con.	"	SR		
	Storage building	con.	"	SR		
	Garage	con.	wood/sr	wood.		
	" Office	con.	panel	12x12		
7	Quonset	con.	SR/metal	metal		
1	Office	crst	SR	SR		
2	Storage	crst	SR/panel		pl. of brackets	
					ragging around some pipe & sample	
6	Boiler Rm				pipes & tanks / fiberglass	




M.B.A. FIRE DEPT.
ARTS.
4465 sqft.




3360 sq ft.
MAINTENANCE DEPT.




2352 sq ft.



2352 sq ft.





2352 sq ft.



LAUNDRY

12834 sq ft.
25-35 students.





MBA. Gym.
15,000 sq. ft.

Building: 111 BA - Auto MechanicsFunctional Area No. 23-AM1-C Location: Shop areaType of Suspect Material: Surfacing, TSI, ☒ OtherDescription: welding curtainApproximate Amount of Material (linear or square ft.): 32ConditionPercent Damage: 0 %, Localized, DistributedType of Damage: Deterioration, Water, Physical

Description: _____

Overall Rating: ☒ Good, Fair, PoorPotential for DisturbanceAccessibility: ☒ Accessible, Inaccessible

Description: _____

Potential for Contact: ☒ High, Moderate, Low

Description: _____

Influence of Vibration: High, ☒ Moderate, Low

Description: _____

Potential for Air Erosion: High, Moderate, ☒ Low

Description: _____

Located in a Plenum? Yes, ☒ No; Type: _____

Comments: _____

Signed: ge Date: 12-26-88

CERTIFICATE OF ANALYSIS

LAB I.D.: P-74884
 SAMPLE LOCATION: 23-AH1-C
 COLLECTED BY: Client
 DATE COLLECTED: Not Given

DATE RECEIVED: December 27, 1988
 DATE STARTED: January 5, 1989
 DATE COMPLETED: January 5, 1989
 DATE REPORTED: January 18, 1989

CLIENT: Eslinger, Herbert
 STREET: 9545 W. Hwy 152
 CITY: Dos Palos
 STATE: CA

ZIP: 93620

PURCHASE ORDER: N/A
 OFN #: L0839
 COPY TO: No cc Req.

PLM ANALYSIS

Analyte	Results Volume %	Detect Limit Volume %
ASBESTOS		
CHRYSTOLITE	90-95 %	1. %
AMOSITE	ND	1. %
CROCIDOLITE	ND	1. %
ANTHOPHYLITE	ND	1. %
TREHOLITE-ACTONDLITE	ND	1. %
FIBER GLASS	ND	1. %
MINERAL WOOL	ND	1. %
CELLULOSE	ND	1. %
NON FIBROUS MATERIALS	5-10 %	1. %
COLOR	White	

Method: EPA Interim Method for the Determination
 of Asbestos in Bulk Insulation Samples

EPA 600/4-82-020

APPROVED: 

This report may not be used to
 claim product endorsement by
 NVLAP or any agency of the
 U.S. Government.

File: CHL.PLM

Building: MBA - Maintenance dept.
Functional Area No. 23-M8-AS Location: office
Type of Suspect Material: ☒ Surfacing, ☐ TSI, ☐ Other
Description: acoustical sprayed ceiling

Approximate Amount of Material (linear or square ft.): 200

Condition

Percent Damage: 0 %, ☐ Localized, ☐ Distributed
Type of Damage: ☐ Deterioration, ☐ Water, ☐ Physical
Description: _____

Overall Rating: ☒ Good, ☐ Fair, ☐ Poor

Potential for Disturbance

Accessibility: ☒ Accessible, ☐ Inaccessible

Description: _____

Potential for Contact: ☐ High, ☐ Moderate, ☒ Low

Description: _____

Influence of Vibration: ☐ High, ☐ Moderate, ☒ Low

Description: _____

Potential for Air Erosion: ☐ High, ☐ Moderate, ☒ Low

Description: _____

Located in a Plenum? ☐ Yes, ☒ No; Type: _____

Comments: _____

Signed: ge Date: 12-26-88

CERTIFICATE OF ANALYSIS

LAB I.D.: P-74063
 SAMPLE LOCATION: 23-M8-AS
 COLLECTED BY: Client
 DATE COLLECTED: Not Given

DATE RECEIVED: December 27, 1988
 DATE STARTED: January 3, 1989
 DATE COMPLETED: January 3, 1989
 DATE REPORTED: January 10, 1989

CLIENT: Eslinger, Herbert
 STREET: 9545 W. Hwy 152
 CITY: Dos Palos
 STATE: CA

ZIP: 93620

PURCHASE ORDER: N/A
 OFW #: L0839
 COPY TO: No cc Req.

PLM ANALYSIS

Analyte	Results Volume %	Detect Limit Volume %
ASBESTOS		
CHRYSDTILE	3-5 %	1. %
AMOSITE	ND	1. %
CROCIDOLITE	ND	1. %
ANTHOPHYLITE	ND	1. %
TRENDOLITE-ACTONOLITE	ND	1. %
FIBER GLASS	ND	1. %
MINERAL WOOL	ND	1. %
CELLULOSE	ND	1. %
NON FIBROUS MATERIALS	95-97 %	1. %
COLOR	White	

Method: EPA Interim Method for the Determination
 of Asbestos in Bulk Insulation Samples EPA 600/4-82-020

report may not be used to
 product endorsement by
 VLAP or any agency of the
 U.S. Government.
 File: CHL.PLM

APPROVED: _____

Scott Foster

Building: MBA - MaintenanceFunctional Area No. 13-MV5-V Location: restroomsType of Suspect Material: Surfacing, TSI, ☒ OtherDescription: wings floor tileApproximate Amount of Material (linear or square ft.): 64ConditionPercent Damage: 0 %, Localized, DistributedType of Damage: Deterioration, Water, Physical

Description: _____

Overall Rating: ☒ Good, Fair, PoorPotential for DisturbanceAccessibility: ☒ Accessible, Inaccessible

Description: _____

Potential for Contact: High, ☒ Moderate, Low

Description: _____

Influence of Vibration: High, Moderate, ☒ Low

Description: _____

Potential for Air Erosion: High, Moderate, ☒ Low

Description: _____

Located in a Plenum? Yes, ☒ No; Type: _____

Comments: _____

Signed: gr Date: 12-26-88

Building: 1113A - Laundry
Functional Area No. 23-L7-Pc Location: washing machines
Type of Suspect Material: Surfacing, ☒ TSI, Other
Description: pipe rapping

Approximate Amount of Material (linear or square ft.): 6

Condition 23-L7-Pc 23-L7-Pc
Percent Damage: 2 %, ☒ Localized, Distributed
Type of Damage: Deterioration, Water, ☒ Physical
Description: some is loose and not rapped tightly

Overall Rating: Good, ☒ Fair, Poor

Potential for Disturbance

Accessibility: ☒ Accessible, Inaccessible

Description: _____

Potential for Contact: High, Moderate, ☒ Low

Description: _____

Influence of Vibration: High, ☒ Moderate, Low

Description: _____

Potential for Air Erosion: High, Moderate, ☒ Low

Description: _____

Located in a Plenum? Yes, ☒ No; Type: _____


Comments: _____

Signed: ge Date: 12-26-88


CATTLE YARD.

FEEDER TROUGHS.

1/8" = 1'



M.B.A. DAIRY
 Con. Block Bldg.
 Attached Side
 2000. sq ft.



Building: MBA - dairy
Functional Area No. 23-D6-5 Location: West wall of dairy farm.
Type of Suspect Material: ☒ Surfacing, ☐ TSI, ☐ Other
Description: slate shingle material

Approximate Amount of Material (linear or square ft.): 320

Condition

Percent Damage: 8 %, ☐ Localized, ☒ Distributed
Type of Damage: ☒ Deterioration, ☐ Water, ☒ Physical
Description: _____

Overall Rating: ☐ Good, ☒ Fair, ☐ Poor

Potential for Disturbance

Accessibility: ☒ Accessible, ☐ Inaccessible

Description: _____

Potential for Contact: ☐ High, ☒ Moderate, ☐ Low
Description: _____

Influence of Vibration: ☐ High, ☐ Moderate, ☒ Low
Description: _____

Potential for Air Erosion: ☐ High, ☐ Moderate, ☒ Low
Description: _____

Located in a Plenum? ☐ Yes, ☒ No; Type: _____

Comments: _____

Signed: ge Date: 12-22-88

CERTIFICATE OF ANALYSIS

LAB I.D.: P-74865
 SAMPLE LOCATION: 23-D6-5
 COLLECTED BY: Client
 DATE COLLECTED: Not Given

DATE RECEIVED: December 27, 1988
 DATE STARTED: January 3, 1989
 DATE COMPLETED: January 3, 1989
 DATE REPORTED: January 10, 1989

CLIENT: Eslinger, Herbert
 STREET: 9545 W. Hwy 152
 CITY: Dos Palos
 STATE: CA

ZIP: 93620

PURCHASE ORDER: N/A
 OFH #: L0839
 COPY TO: No cc Req.

PLM ANALYSIS

Analyte	Results Volume %	Detect Limit Volume %
ASBESTOS		
CHRYSTILE	5-10 %	1. %
AMOSITE	ND	1. %
CROCIDOLITE	ND	1. %
ANTHOPHYLITE	ND	1. %
TREHOLITE-ACTONOLITE	ND	1. %
FIBER GLASS	ND	1. %
MINERAL WOOL	ND	1. %
CELLULOSE	ND	1. %
NON FIBROUS MATERIALS	90-95 %	1. %
COLOR	Gray	

Method: EPA Interim Method for the Determination
 of Asbestos in Bulk Insulation Samples

EPA 600/4-82-020

APPROVED: _____


[Signature]

report may not be used to
 product endorsement by
 NVLAP or any agency of the
 U.S. Government.


File: CWL.PLM

SCHOOL: MBA - long class

[illegible]



Boys DORMITORY
Monterey Bay SDA ACADEMY
1st FLOOR
19548 sq. ft.



Building: MBA - Boys DormFunctional Area No. 23-BD10-P Location: Boiler RoomType of Suspect Material: Surfacing, ☒ TSI, OtherDescription: pipe crowdingApproximate Amount of Material (linear or square ft.): 15 linConditionPercent Damage: 30 %, Localized, ☒ DistributedType of Damage: ☒ Deterioration, Water, PhysicalDescription: some areas have been removed - still patches remain.Overall Rating: Good, Fair, ☒ PoorPotential for DisturbanceAccessibility: Accessible, ☒ InaccessibleDescription: majority is in a plenum.Potential for Contact: High, Moderate, ☒ LowDescription: only authorized personnelInfluence of Vibration: High, ☒ Moderate, LowDescription: when system runsPotential for Air Erosion: High, ☒ Moderate, LowDescription: heat waves + air circulationLocated in a Plenum? ☒ Yes, No; Type: concreteComments: Signed: ge Date: 12-26-88

CERTIFICATE OF ANALYSIS

LAB I.D.: P-74058
 SAMPLE LOCATION: 23-BD10-P1
 COLLECTED BY: Client
 DATE COLLECTED: Not Given

DATE RECEIVED: December 27, 1988
 DATE STARTED: January 3, 1989
 DATE COMPLETED: January 3, 1989
 DATE REPORTED: January 10, 1989

CLIENT: Eslinger, Herbert
 STREET: 9545 W. Hwy 152
 CITY: Dos Palos
 STATE: CA

ZIP: 93620

PURCHASE ORDER: N/A
 OFW #: L0839
 COPY TO: No cc Req.

PLM ANALYSIS

Analyte	Results Volume %	Detect Limit Volume %
ASBESTOS		
CHRYSTOLE	ND	1. %
AMOSITE	35-40 %	1. %
CROCIDOLITE	ND	1. %
ANTHOPHYLITE	ND	1. %
TREHOLITE-ACTONOLITE	ND	1. %
FIBER GLASS	ND	1. %
MINERAL WOOL	ND	1. %
CELLULOSE	3-5 %	1. %
NON FIBROUS MATERIALS	55-62 %	1. %
COLOR	Brown & White	

Method: EPA Interim Method for the Determination
 of Asbestos in Bulk Insulation Samples EPA 600/4-82-020

APPROVED: 

This report may not be used to
 claim product endorsement by
 NVLAP or any agency of the
 U.S. Government.
 File: CWL.PLM

Building: MBA Brn Dorn
Functional Area No. 23-BD4-V Location: north restroom 1st floor
Type of Suspect Material: Surfacing, TSI, ☒ Other
Description: wing floor tile

Approximate Amount of Material (linear or square ft.): 168

Condition

Percent Damage: 0 %, Localized, Distributed
Type of Damage: Deterioration, Water, Physical
Description: _____

Overall Rating: ☒ Good, Fair, Poor

Potential for Disturbance

Accessibility: ☒ Accessible, Inaccessible

Description: _____

Potential for Contact: High, ☒ Moderate, Low

Description: _____

Influence of Vibration: High, Moderate, ☒ Low

Description: _____

Potential for Air Erosion: High, Moderate, ☒ Low

Description: _____

Located in a Plenum? Yes, ☒ No; Type: _____

Comments: _____

Signed: gr Date: 12-26-88

CERTIFICATE OF ANALYSIS

LAB I.D.: P-74073
 SAMPLE LOCATION: 23-B04-V
 COLLECTED BY: Client
 DATE COLLECTED: Not Given

DATE RECEIVED: December 27, 1988
 DATE STARTED: January 4, 1989
 DATE COMPLETED: January 4, 1989
 DATE REPORTED: January 10, 1989

CLIENT: Eslinger, Herbert
 STREET: 9545 W. Hwy 152
 CITY: Dos Palos
 STATE: CA ZIP: 93620

PURCHASE ORDER: N/A
 OFW #: L0839
 COPY TO: No cc Req.

PLM ANALYSIS

Analyte	Results Volume %	Detect Limit Volume %
ASBESTOS		
CHRYSTOTILE	2-3 %	1. %
AMOSITE	ND	1. %
CROCIDOLITE	ND	1. %
ANTHOPHYLITE	ND	1. %
TREMOLITE-ACTONDLITE	ND	1. %
FIBER GLASS	ND	1. %
MINERAL WOOL	ND	1. %
CELLULOSE	2-3 %	1. %
NON FIBROUS MATERIALS	94-96 %	1. %
COLOR	Brown & White	

Method: EPA Interim Method for the Determination
 of Asbestos in Bulk Insulation Samples

EPA 600/4-82-020

This report may not be used to
 claim product endorsement by
 NVLAP or any agency of the
 U.S. Government.
 File: CWL.PLM

APPROVED: 

SCHOOL:

[illegible]

Building: MBA Boys Dorm - New wing
Functional Area No. 23-BD1-15 Location: Chapel
Type of Suspect Material: ☒ Surfacing, ☐ TSI, ☐ Other
Description: acoustical spray

Approximate Amount of Material (linear or square ft.): 300

Condition

Percent Damage: 0 %, ☐ Localized, ☐ Distributed
Type of Damage: ☐ Deterioration, ☐ Water, ☐ Physical
Description: _____

Overall Rating: ☒ Good, ☐ Fair, ☐ Poor

Potential for Disturbance

Accessibility: ☐ Accessible, ☒ Inaccessible

Description: Tall ceiling

Potential for Contact: ☐ High, ☐ Moderate, ☒ Low
Description: _____

Influence of Vibration: ☐ High, ☐ Moderate, ☒ Low
Description: _____

Potential for Air Erosion: ☐ High, ☐ Moderate, ☒ Low
Description: _____

Located in a Plenum? ☐ Yes, ☒ No; Type: _____

Comments: _____

Signed: JP Date: 12-26-88

CERTIFICATE OF ANALYSIS

LAB I.D.: P-74071
 SAMPLE LOCATION: 23-BD1-AS
 COLLECTED BY: Client
 DATE COLLECTED: Not Given

DATE RECEIVED: December 27, 1988
 DATE STARTED: January 4, 1989
 DATE COMPLETED: January 4, 1989
 DATE REPORTED: January 10, 1989

CLIENT: Eslinger, Herbert
 STREET: 9545 W. Hwy 152
 CITY: Dos Palos
 STATE: CA
 ZIP: 93620

PURCHASE ORDER: N/A
 QFW #: L8839
 COPY TO: No cc Req.

PLH ANALYSIS

Analyte	Results Volume %	Detect Limit Volume %
ASBESTOS		
CHRYSTILE	3-5 %	1. %
AMOSITE	ND	1. %
CROCIDOLITE	ND	1. %
ANTHOPHYLITE	ND	1. %
TREMOLITE-ACTONOLITE	ND	1. %
FIBER GLASS	ND	1. %
MINERAL WOOL	ND	1. %
CELLULOSE	ND	1. %
NON FIBROUS MATERIALS	95-97 %	1. %
COLOR	White	

Method: EPA Interim Method for the Determination
 of Asbestos in Bulk Insulation Samples EPA 600/4-82-020

APPROVED: 

This report may not be used to
 claim product endorsement by
 NVLAP or any agency of the
 U.S. Government.
 File: CWL.PLM

Building: MBA - Boys DormFunctional Area No. 23-BD9-V Location: guest bathroomType of Suspect Material: Surfacing, TSI, ☒ OtherDescription: vinyl floor - same as girls - 4' square
South RR first floor.Approximate Amount of Material (linear or square ft.): 64Condition 23-BD9-V 23-BD9-VPercent Damage: 0%, Localized, DistributedType of Damage: Deterioration, Water, Physical

Description: _____

Overall Rating: ☒ Good, Fair, PoorPotential for DisturbanceAccessibility: ☒ Accessible, Inaccessible

Description: _____

Potential for Contact: High, ☒ Moderate, Low

Description: _____

Influence of Vibration: High, Moderate, ☒ Low

Description: _____

Potential for Air Erosion: High, Moderate, ☒ Low

Description: _____

Located in a Plenum? Yes, ☒ No; Type: _____

Comments: _____

Signed: gc Date: 12-26-88

Building: MBA Boys DownFunctional Area No. 23-BDS-5 Location: hallwayType of Suspect Material: ☒ Surfacing, ☐ TSI, ☐ OtherDescription: small patch23-BDS-5 23-BDS-5Approximate Amount of Material (linear or square ft.): 3200ConditionPercent Damage: 2 %, ☒ Localized, ☐ DistributedType of Damage: ☐ Deterioration, ☐ Water, ☒ Physical

Description: _____

Overall Rating: ☒ Good, ☐ Fair, ☐ PoorPotential for DisturbanceAccessibility: ☒ Accessible, ☐ Inaccessible

Description: _____

Potential for Contact: ☐ High, ☒ Moderate, ☐ Low

Description: _____

Influence of Vibration: ☐ High, ☒ Moderate, ☐ Low

Description: _____

Potential for Air Erosion: ☐ High, ☐ Moderate, ☒ Low

Description: _____

Located in a Plenum? ☐ Yes, ☒ No; Type: _____

Comments: _____

Signed: gr Date: 12-26-88

Building: MBA - Boys DormFunctional Area No. 23-B07-T Location: janitorsType of Suspect Material: Surfacing, TSI, ☒ OtherDescription: 9x9 floor tile - same in restroom storageApproximate Amount of Material (linear or square ft.): 120ConditionPercent Damage: 2 %, Localized, ☒ DistributedType of Damage: Deterioration, Water, ☒ Physical

Description: _____

Overall Rating: Good, ☒ Fair, PoorPotential for DisturbanceAccessibility: ☒ Accessible, Inaccessible

Description: _____

Potential for Contact: High, ☒ Moderate, Low

Description: _____

Influence of Vibration: High, Moderate, ☒ Low

Description: _____

Potential for Air Erosion: High, Moderate, ☒ Low

Description: _____

Located in a Plenum? Yes, ☒ No; Type: _____

Comments: _____

Signed: ge Date: 12-26-88

CERTIFICATE OF ANALYSIS

LAB I.D.: P-74874
 SAMPLE LOCATION: 23-BD7-T
 COLLECTED BY: Client
 DATE COLLECTED: Not Given

DATE RECEIVED: December 27, 1988
 DATE STARTED: January 4, 1989
 DATE COMPLETED: January 4, 1989
 DATE REPORTED: January 10, 1989

CLIENT: Eslinger, Herbert
 STREET: 9545 W. Hwy 152
 CITY: Dos Palos
 STATE: CA ZIP: 93620

PURCHASE ORDER: N/A
 OFW #: L0839
 COPY TO: No cc Req.

PLM ANALYSIS

Analyte	Results Volume %	Detect Limit Volume %
ASBESTOS		
CHRYSTILE	ND	1. %
AMOSITE	ND	1. %
CROCIDOLITE	ND	1. %
ANTHOPHYLITE	ND	1. %
TREMOLITE-ACTONOLITE	ND	1. %
FIBER GLASS	ND	1. %
MINERAL WOOL	ND	1. %
CELLULOSE	ND	1. %
NON FIBROUS MATERIALS	100 %	1. %
COLOR	Brown	

Method: EPA Interim Method for the Determination
 of Asbestos in Bulk Insulation Samples EPA 600/4-82-020

A report may not be used to
 claim product endorsement by
 NVLAP or any agency of the
 U.S. Government.

File: CHL.PLM

APPROVED: 

Building: MBA - Boys Dorm - old wingsFunctional Area No. 23-B03-V Location: South restroomType of Suspect Material: Surfacing, TSI, ✓ OtherDescription: vinyl floor tile - same as north + south
restroom on 2nd floor.Approximate Amount of Material (linear or square ft.): 500ConditionPercent Damage: 0 %, Localized, DistributedType of Damage: Deterioration, Water, PhysicalDescription:
 Overall Rating: ✓ Good, Fair, PoorPotential for DisturbanceAccessibility: ✓ Accessible, InaccessibleDescription:
 Potential for Contact: High, ✓ Moderate, LowDescription:
 Influence of Vibration: High, Moderate, ✓ LowDescription:
 Potential for Air Erosion: High, Moderate, ✓ LowDescription:
 Located in a Plenum? Yes, ✓ No; Type: Comments:
 Signed: ge Date: 12-26-88

CERTIFICATE OF ANALYSIS

LAB I.D.: P-74872
 SAMPLE LOCATION: 23-803-V
 COLLECTED BY: Client
 DATE COLLECTED: Not Given

DATE RECEIVED: December 27, 1988
 DATE STARTED: January 4, 1989
 DATE COMPLETED: January 4, 1989
 DATE REPORTED: January 10, 1989

CLIENT: Eslinger, Herbert
 STREET: 9545 W. Hwy 152
 CITY: Dos Palos
 STATE: CA ZIP: 93620

PURCHASE ORDER: N/A
 OFW #: L0839
 COPY TO: No cc Req.

PLM ANALYSIS

Analyte	Results Volume %	Detect Limit Volume %
ASBESTOS		
CHRYSTILE	ND	1. %
AMOSITE	ND	1. %
CROCIDOLITE	ND	1. %
ANTHOPHYLITE	ND	1. %
TREMOLITE-ACTONOLITE	ND	1. %
FIBER GLASS	ND	1. %
MINERAL WOOL	ND	1. %
CELLULOSE	15-20 %	1. %
NON FIBROUS MATERIALS	80-85 %	1. %
COLOR	Brown & White	

Method: EPA Interim Method for the Determination
 of Asbestos in Bulk Insulation Samples EPA 600/4-82-020

APPROVED: 

This report may not be used to
 claim product endorsement by
 NVLAP or any agency of the
 U.S. Government.

File: CHL.PLM

Building:

MBA - Boys DormFunctional Area No. 23-BD2-TLocation: New Wing 1st + 2nd floor

Type of Suspect Material:

Surfacing,

TSI,

☒ Other

Description:

9x9 floor tile - all dorm rooms,
most rooms have carpet thrown over tile. (light brown)

Approximate Amount of Material (linear or square ft.):

9000ConditionPercent Damage: 5 %,☐ Localized,☒ Distributed

Type of Damage:

☐ Deterioration,☐ Water,☒ Physical

Description:

Overall Rating:

☐ Good,☒ Fair,☐ PoorPotential for Disturbance

Accessibility:

☒ Accessible,☐ Inaccessible

Description:

Potential for Contact:

☐ High,☒ Moderate,☐ Low

Description:

Some has carpet on

Influence of Vibration:

☐ High,☐ Moderate,☒ Low

Description:

Potential for Air Erosion:

☐ High,☐ Moderate,☒ Low

Description:

Located in a Plenum?☐ Yes,☒ No;

Type:

Comments:

Signed:

GE

Date:

12-26-88

CERTIFICATE OF ANALYSIS

LAB I.D.: P-74070
 SAMPLE LOCATION: 23-B06-V
 COLLECTED BY: Client
 DATE COLLECTED: Not Given

DATE RECEIVED: December 27, 1988
 DATE STARTED: January 3, 1989
 DATE COMPLETED: January 3, 1989
 DATE REPORTED: January 10, 1989

CLIENT: Eslinger, Herbert
 STREET: 9545 W. Hwy 152
 CITY: Dos Palos
 STATE: CA ZIP: 93620

PURCHASE ORDER: N/A
 OFH #: L0839
 COPY TO: No cc Req.

PLM ANALYSIS

Analyte	Results Volume %	Detect Limit Volume %
ASBESTOS		
CHRYSDILE	ND	1. %
AMOSITE	ND	1. %
CROCIDOLITE	ND	1. %
ANTHOPHYLITE	ND	1. %
TRENOLITE-ACTONOLITE	ND	1. %
FIBER GLASS	ND	1. %
MINERAL WOOL	ND	1. %
CELLULOSE	3-5 %	1. %
NON FIBROUS MATERIALS	95-97 %	1. %
COLOR	Brown	

Method: EPA Interim Method for the Determination
 of Asbestos in Bulk Insulation Samples EPA 600/4-82-020

APPROVED: _____

This report may not be used to
 claim product endorsement by
 NRELAP or any agency of the
 U.S. Government.
 File: CNL.PLN

Building: MVA - Page Dome
Functional Area No. 23-BD11-VP Location: 2nd floor lobby (new wing)
Type of Suspect Material: ☒ Surfacing, ☐ TSI, ☐ Other
Description: vinyl w.p.

Approximate Amount of Material (linear or square ft.): 140

Condition

Percent Damage: 0 %, ☐ Localized, ☐ Distributed
Type of Damage: ☐ Deterioration, ☐ Water, ☐ Physical
Description: _____

Overall Rating: ☒ Good, ☐ Fair, ☐ Poor

Potential for Disturbance

Accessibility: ☒ Accessible, ☐ Inaccessible
Description: _____

Potential for Contact: ☐ High, ☒ Moderate, ☐ Low
Description: _____

Influence of Vibration: ☐ High, ☐ Moderate, ☒ Low
Description: _____

Potential for Air Erosion: ☐ High, ☐ Moderate, ☒ Low
Description: _____

Located in a Plenum? ☐ Yes, ☒ No; Type: _____

Comments: _____

Signed: ge Date: 12-26-88

CERTIFICATE OF ANALYSIS

LAB I.D.: P-74864
 SAMPLE LOCATION: 23-BD11-VP
 COLLECTED BY: Client
 DATE COLLECTED: Not Given

DATE RECEIVED: December 27, 1988
 DATE STARTED: January 3, 1989
 DATE COMPLETED: January 3, 1989
 DATE REPORTED: January 10, 1989

CLIENT: Eslinger, Herbert
 STREET: 9545 W. Hwy 152
 CITY: Dos Palos
 STATE: CA

ZIP: 93620

PURCHASE ORDER: N/A
 OFW #: L8839
 COPY TO: No cc Req.

PLM ANALYSIS

Analyte	Results Volume %	Detect Limit Volume %
ASBESTOS		
CHRYSTILE	ND	1. %
AMOSITE	ND	1. %
CROCIDOLITE	ND	1. %
ANTHOPHYLITE	ND	1. %
TREMOLITE-ACTONOLITE	ND	1. %
FIBER GLASS	ND	1. %
MINERAL WOOL	ND	1. %
CELLULOSE	3-5 %	1. %
NON FIBROUS MATERIALS	95-97 %	1. %
COLOR	White	

Method: EPA Interim Method for the Determination
 of Asbestos in Bulk Insulation Samples

EPA 680/4-82-020

... report may not be used to
 claim product endorsement by
 VLAP or any agency of the
 U.S. Government.
 File: CWL.PLM


APPROVED: 


SCHOOL: MBA - Girl Dorm.

ROOM #	ROOM NAME	FLOOR COVERING	WALL TEXTURE	CEILING TEXTURE	MISC. COVERING	REMARKS
	Lobby + hallway	carpt	plas	AS		sample
	dorm. rooms	carpt/wd	plas	plas		
	restrooms	vinyl	cer. tile wip. plas	plas		sample
	restrooms (janitor)	9x9	plas	plas		green
	boiler rm.	concr.	plas	plas	P.C.	60 lin ft
	(on ceiling + floor + open under walk - pool)				(plenum conc.)	sample
	roof base	asbestos	slat.	shingles - assumed		
	Northwest	vinyl	W.P. (floor 3rd)	SR/plas		
	West Wing					
	clinic	vinyl	plas.	plas.		
	janitor / in room	vinyl	plas	plas		sample
	rooms	wd	SR	SR		
	showers	cer. tile	cer. tile	cer. tile		
	bathroom	vinyl/cer. tile	SK	SK		
	storage	concr.	wd	wd	P.C. 60 lin ft	sample
	hallway has	acoustical spray containing asbestos				
	enclosed	with 4x8 sheets of sheet rock				
	chapel	carpt	wd/AS	12x12		sample
	2nd floor R12	vinyl (same as 1st)	W.P. blue denim	AS		
	South " " "	"	W.P.	AS		sample / floor + W.P.

upper tubing thru conc.

MBR. GIRLS DORMITORY
2nd Floor
18488 sq. ft.





Building: MDA - Girls Arm
Functional Area No. 23-608-T Location: storage - janitors
Type of Suspect Material: Surfacing, TSI, ✓ Other
Description: 9x9 green

Approximate Amount of Material (linear or square ft.): 64

Condition

Percent Damage: 6 %, Localized, ✓ Distributed
Type of Damage: Deterioration, Water, ✓ Physical
Description:

Overall Rating: Good, ✓ Fair, Poor

Potential for Disturbance

Accessibility: ✓ Accessible, Inaccessible

Description:

Potential for Contact: High, ✓ Moderate, Low

Description:

Influence of Vibration: High, Moderate, ✓ Low

Description:

Potential for Air Erosion: High, Moderate, ✓ Low

Description:

Located in a Plenum? Yes, ✓ No; Type:

Comments:

Signed: GP Date: 12-26-88

CERTIFICATE OF ANALYSIS

LAB I.D.: P-74079
 SAMPLE LOCATION: 23-608-T
 COLLECTED BY: Client
 DATE COLLECTED: Not Given

DATE RECEIVED: December 27, 1988
 DATE STARTED: January 4, 1989
 DATE COMPLETED: January 4, 1989
 DATE REPORTED: January 10, 1989

CLIENT: Eslinger, Herbert
 STREET: 9545 W. Hwy 152
 CITY: Dos Palos
 STATE: CA

ZIP: 93620

PURCHASE ORDER: N/A
 OFW #: L0839
 COPY TO: No cc Req.

PLH ANALYSIS

Analyte	Results Volume %	Detect Limit Volume %
ASBESTOS		
CHRYSDOTILE	1-2 %	1. %
AMOSITE	ND	1. %
CROCIDOLITE	ND	1. %
ANTHOPHYLITE	ND	1. %
TREMOLITE-ACTONOLITE	ND	1. %
FIBER GLASS	ND	1. %
MINERAL WOOL	ND	1. %
CELLULOSE	5-10 %	1. %
NON FIBROUS MATERIALS	88-94 %	1. %
COLOR	Green & Brown	

Method: EPA Interim Method for the Determination
 of Asbestos in Bulk Insulation Samples EPA 600/4-82-020

APPROVED: *Scott Foster*

This report may not be used to
 claim product endorsement by
 NVLAP or any agency of the
 U.S. Government.

File: CHL.PLM

Building: MBA - Girl ArmFunctional Area No. B-G02-V Location: restroomsType of Suspect Material: Surfacing, TSI, ☒ OtherDescription: rough floor coveringApproximate Amount of Material (linear or square ft.): 80 x 4 320ConditionPercent Damage: 0 %, Localized, DistributedType of Damage: Deterioration, Water, Physical

Description: _____

Overall Rating: ☒ Good, Fair, PoorPotential for DisturbanceAccessibility: ☒ Accessible, Inaccessible

Description: _____

Potential for Contact: High, ☒ Moderate, Low

Description: _____

Influence of Vibration: High, Moderate, ☒ Low

Description: _____

Potential for Air Erosion: High, Moderate, ☒ Low

Description: _____

Located in a Plenum? Yes, ☒ No; Type: _____

Comments: _____

Signed: gl Date: 12-26-88

CERTIFICATE OF ANALYSIS

LAB I.D.: P-74061
 SAMPLE LOCATION: 23-G02-V
 COLLECTED BY: Client
 DATE COLLECTED: Not Given

DATE RECEIVED: December 27, 1988
 DATE STARTED: January 3, 1989
 DATE COMPLETED: January 3, 1989
 DATE REPORTED: January 10, 1989

CLIENT: Eslinger, Herbert
 STREET: 9545 W. Hwy 152
 CITY: Dos Palos
 STATE: CA ZIP: 93620

PURCHASE ORDER: N/A
 OFH #: L8839
 COPY TO: No cc Req.

PLM ANALYSIS

Analyte -----	Results Volume % -----	Detect Limit Volume % -----
ASBESTOS		
CHRYSTILE	5-10 %	1. %
AMOSITE	ND	1. %
CROCIDOLITE	ND	1. %
ANTHOPHYLITE	ND	1. %
TREMOLITE-ACTONOLITE	ND	1. %
FIBER GLASS	ND	1. %
MINERAL WOOL	ND	1. %
CELLULOSE	ND	1. %
NON FIBROUS MATERIALS	90-95 %	1. %
COLOR	White	

Method: EPA Interim Method for the Determination
 of Asbestos in Bulk Insulation Samples EPA 600/4-82-020

APPROVED: Scott Foster

Report may not be used to
 claim product endorsement by
 NVLAP or any agency of the
 U.S. Government.
 File: CNL.PLM

Building: M-1A - Girls Down
Functional Area No. 23-GD7-V Location: girls - restroom (shower)
Type of Suspect Material: Surfacing, TSI, ☒ Other
Description: bruyt floor

Approximate Amount of Material (linear or square ft.): 150

Condition

Percent Damage: 0 %, Localized, Distributed
Type of Damage: Deterioration, Water, Physical
Description: _____

Overall Rating: ☒ Good, Fair, Poor

Potential for Disturbance

Accessibility: ☒ Accessible, Inaccessible

Description: _____

Potential for Contact: High, ☒ Moderate, Low

Description: _____

Influence of Vibration: High, Moderate, ☒ Low

Description: _____

Potential for Air Erosion: High, Moderate, ☒ Low

Description: _____

Located in a Plenum? Yes, ☒ No; Type: _____

Comments: _____

Signed: ge Date: 12-26-88

CERTIFICATE OF ANALYSIS

LAB I.D.: P-74060
 SAMPLE LOCATION: 23-GB7-V
 COLLECTED BY: Client
 DATE COLLECTED: Not Given

DATE RECEIVED: December 27, 1988
 DATE STARTED: January 3, 1989
 DATE COMPLETED: January 3, 1989
 DATE REPORTED: January 10, 1989

CLIENT: Eslinger, Herbert
 STREET: 9545 W. Hwy 152
 CITY: Dos Palos
 STATE: CA ZIP: 93620

PURCHASE ORDER: N/A
 OFW #: L8839
 COPY TO: No cc Req.

P L H A N A L Y S I S

Analyte	Results Volume %	Detect Limit Volume %
ASBESTOS		
CHRYSTOTILE	ND	1. %
AMOSITE	ND	1. %
CROCIDOLITE	ND	1. %
ANTHOPHYLITE	ND	1. %
TREHOLITE-ACTONOLITE	ND	1. %
FIBER GLASS	3-5 %	1. %
MINERAL WOOL	ND	1. %
CELLULOSE	3-5 %	1. %
NON FIBROUS MATERIALS	90-94 %	1. %
COLOR	Gray & White	

Method: EPA Interim Method for the Determination
 of Asbestos in Bulk Insulation Samples EPA 600/4-82-020

APPROVED: _____

Scott Frost

This report may not be used to
 claim product endorsement by
 NVLAP or any agency of the
 U.S. Government.
 File: CHL.PLM

Building: MBA Birds Room
Functional Area No 23-GD4-P1 Location: Storage - end of new wing
Type of Suspect Material: Surfacing, ☒ TSI, Other
Description: paper covering

Approximate Amount of Material (linear or square ft.): 60

Condition

Percent Damage: 2 %, ☒ Localized, Distributed
Type of Damage: Deterioration, Water, ☒ Physical
Description: _____

Overall Rating: ☒ Good, Fair, Poor

Potential for Disturbance

Accessibility: ☒ Accessible, Inaccessible

Description: items are stored in this area

Potential for Contact: High, Moderate, ☒ Low

Description: only when occupied which is not routine

Influence of Vibration: High, ☒ Moderate, Low

Description: when system runs

Potential for Air Erosion: High, Moderate, ☒ Low

Description: _____

Located in a Plenum? Yes, ☒ No; Type: _____

Comments: _____

Signed: ge Date: 12-26-88

CERTIFICATE OF ANALYSIS

LAB I.D.: P-74078
SAMPLE LOCATION: 23-G04-P1
COLLECTED BY: Client
DATE COLLECTED: Not Given

DATE RECEIVED: December 27, 1988
DATE STARTED: January 4, 1989
DATE COMPLETED: January 4, 1989
DATE REPORTED: January 10, 1989

CLIENT: Eslinger, Herbert
STREET: 9545 W. Hwy 152
CITY: Dos Palos
STATE: CA

ZIP: 93620

PURCHASE ORDER: N/A
OFW #: L0839
COPY TO: No cc Req.

PLH ANALYSIS

Analyte	Results Volume %	Detect Limit Volume %
ASBESTOS		
CHRYSDOTILE	15-20 %	1. %
AMOSITE	ND	1. %
CROCIDOLITE	ND	1. %
ANTHOPHYLITE	ND	1. %
TREMOLITE-ACTONOLITE	ND	1. %
FIBER GLASS	ND	1. %
MINERAL WOOL	ND	1. %
CELLULOSE	5-10 %	1. %
NON FIBROUS MATERIALS	70-80 %	1. %
COLOR	Gray	

Method: EPA Interim Method for the Determination
of Asbestos in Bulk Insulation Samples

EPA 600/4-82-020

APPROVED: 

This report may not be used to
claim product endorsement by
NVLAP or any agency of the
U.S. Government.

File: CML.PLM

Building: MBR Girls Dorm.Functional Area No. 23-GD3-P1 Location: Boiler Rm.Type of Suspect Material: Surfacing, ☒ TSI, OtherDescription: pipe coveringApproximate Amount of Material (linear or square ft.): 60ConditionPercent Damage: 10 %, Localized, ☒ DistributedType of Damage: ☒ Deterioration, Water, PhysicalDescription: pipes on ceiling are in better condition than those in the plenum.Overall Rating: Good, Fair, ☒ PoorPotential for DisturbanceAccessibility: ☒ Accessible, Inaccessible

Description: _____

Potential for Contact: High, Moderate, ☒ Low

Description: _____

Influence of Vibration: High, ☒ Moderate, Low

Description: _____

Potential for Air Erosion: High, ☒ Moderate, LowDescription: heat waves in boiler room plus air outside.Located in a Plenum? ☒ Yes, No; Type: concreteComments: 20 linear ft - remaining 40 not in plenumSigned: gp Date: 12-26-88

CERTIFICATE OF ANALYSIS

LAB I.D.: P-74068
 SAMPLE LOCATION: 23-GD3-P1
 COLLECTED BY: Client
 DATE COLLECTED: Not Given

DATE RECEIVED: December 27, 1988
 DATE STARTED: January 3, 1989
 DATE COMPLETED: January 3, 1989
 DATE REPORTED: January 10, 1989

CLIENT: Eslinger, Herbert
 STREET: 9545 W. Hwy 152
 CITY: Dos Palos
 STATE: CA ZIP: 93620

PURCHASE ORDER: N/A
 OFH #: LB839
 COPY TO: No cc Req.

PLM ANALYSIS

Analyte	Results Volume %	Detect Limit Volume %
ASBESTOS		
CHRYSTILE	ND	1. %
AMOSITE	40-45 %	1. %
CROCIDOLITE	ND	1. %
ANTHOPHYLITE	ND	1. %
TREHOLITE-ACTONOLITE	ND	1. %
FIBER GLASS	ND	1. %
MINERAL WOOL	ND	1. %
CELLULOSE	ND	1. %
NON FIBROUS MATERIALS	55-60 %	1. %
COLOR	White	

Method: EPA Interim Method for the Determination
 of Asbestos in Bulk Insulation Samples EPA 600/4-82-020

APPROVED: 

Report may not be used to
 product endorsement by
 NVLAP or any agency of the
 U.S. Government.

File: CHL.PLM

Building: MBA - Boys Laundry
Functional Area No. 23-BD6-V Location: Laundry room
Type of Suspect Material: Surfacing, TSI, ☒ Other
Description: Wing floor

Approximate Amount of Material (linear or square ft.): 350

Condition

Percent Damage: 0 %, Localized, Distributed
Type of Damage: Deterioration, Water, Physical
Description: _____

Overall Rating: ☒ Good, Fair, Poor

Potential for Disturbance

Accessibility: ☒ Accessible, Inaccessible

Description: _____

Potential for Contact: High, ☒ Moderate, Low

Description: _____

Influence of Vibration: High, Moderate, ☒ Low

Description: _____

Potential for Air Erosion: High, Moderate, ☒ Low

Description: _____

Located in a Plenum? Yes, ☒ No; Type: _____

Comments: _____

Signed: gf Date: 12-26-88

CERTIFICATE OF ANALYSIS

LAB I.D.: P-74069
 SAMPLE LOCATION: 23-BD2-T
 COLLECTED BY: Client
 DATE COLLECTED: Not Given

DATE RECEIVED: December 27, 1988
 DATE STARTED: January 3, 1989
 DATE COMPLETED: January 3, 1989
 DATE REPORTED: January 10, 1989

CLIENT: Eslinger, Herbert
 STREET: 9545 W. Hwy 152
 CITY: Dos Palos
 STATE: CA

ZIP: 93620

PURCHASE ORDER: N/A
 OFW #: L0839
 COPY TO: No cc Req.

PLM ANALYSIS

Analyte	Results Volume %	Detect Limit Volume %
ASBESTOS		
CHRYSTOTILE	ND	1. %
AMOSITE	ND	1. %
CROCIDOLITE	ND	1. %
ANTHOPHYLITE	ND	1. %
TRENOLITE-ACTONOLITE	ND	1. %
FIBER GLASS	ND	1. %
MINERAL WOOL	ND	1. %
CELLULOSE	ND	1. %
NON FIBROUS MATERIALS	100 %	1. %
COLOR	Brown	

Method: EPA Interim Method for the Determination
 of Asbestos in Bulk Insulation Samples

EPA 600/4-82-020

APPROVED: _____

Scott Foster

This report may not be used to
 as a product endorsement by
 NVLAP or any agency of the
 U.S. Government.

File: CHL.PLM

Building: MBA - Girls Dorm.Functional Area No. 23-GDS-A Location: chapel - back wallType of Suspect Material: ☒ Surfacing, ☐ TSI, ☐ OtherDescription: acoustical sprayApproximate Amount of Material (linear or square ft.): 300ConditionPercent Damage: 0 %, ☐ Localized, ☐ DistributedType of Damage: ☐ Deterioration, ☐ Water, ☐ Physical

Description: _____

Overall Rating: ☒ Good, ☐ Fair, ☐ PoorPotential for DisturbanceAccessibility: ☐ Accessible, ☒ InaccessibleDescription: up on back wallPotential for Contact: ☐ High, ☐ Moderate, ☒ Low

Description: _____

Influence of Vibration: ☐ High, ☐ Moderate, ☒ Low

Description: _____

Potential for Air Erosion: ☐ High, ☐ Moderate, ☒ Low

Description: _____

Located in a Plenum? ☐ Yes, ☒ No; Type: _____

Comments: _____

Signed: ge Date: 12-26-88

CERTIFICATE OF ANALYSIS

LAB I.D.: P-74866
SAMPLE LOCATION: 23-G05-AS
COLLECTED BY: Client
DATE COLLECTED: Not Given

DATE RECEIVED: December 27, 1988
DATE STARTED: January 3, 1989
DATE COMPLETED: January 3, 1989
DATE REPORTED: January 10, 1989

CLIENT: Eslinger, Herbert
STREET: 9545 W. Hwy 152
CITY: Dos Palos
STATE: CA

ZIP: 93620

PURCHASE ORDER: N/A
OFW #: L8839
COPY TO: No cc Req.

PLM ANALYSIS

Analyte	Results Volume %	Detect Limit Volume %
ASBESTOS		
CHRYSDOTILE	2-3 %	1. %
AMOSITE	ND	1. %
CROCIDOLITE	ND	1. %
ANTHOPHYLITE	ND	1. %
TREMOLITE-ACTONOLITE	ND	1. %
FIBER GLASS	ND	1. %
MINERAL WOOL	ND	1. %
CELLULOSE	ND	1. %
NON FIBROUS MATERIALS	97-98 %	1. %
COLOR	Brown	

Method: EPA Interim Method for the Determination
of Asbestos in Bulk Insulation Samples EPA 600/4-82-020

This report may not be used to
claim product endorsement by
NVLAP or any agency of the
U.S. Government.
File: CWL.PLM

APPROVED: 

Building: MBA - Girls Dorm -
Functional Area No. 23-GD6-V Location: restroom laundry
Type of Suspect Material: Surfacing, TSI, ✓ Other
Description: rough floor

Approximate Amount of Material (linear or square ft.): 160

Condition

Percent Damage: D %, Localized, Distributed
Type of Damage: Deterioration, Water, Physical
Description:

Overall Rating: ✓ Good, Fair, Poor

Potential for Disturbance

Accessibility: ✓ Accessible, Inaccessible

Description:

Potential for Contact: High, ✓ Moderate, Low

Description:

Influence of Vibration: High, Moderate, ✓ Low

Description:

Potential for Air Erosion: High, Moderate, ✓ Low

Description:

Located in a Plenum? Yes, ✓ No; Type:

Comments:

Signed: ge Date: 12-26-88

CERTIFICATE OF ANALYSIS

LAB I.D.: P-74119
 SAMPLE LOCATION: 23-GD6-V
 COLLECTED BY: Client
 DATE COLLECTED: Not Given

DATE RECEIVED: December 27, 1988
 DATE STARTED: January 6, 1989
 DATE COMPLETED: January 6, 1989
 DATE REPORTED: January 10, 1989

CLIENT: Eslinger, Herbert
 STREET: 9545 W. Hwy 152
 CITY: Dos Palos
 STATE: CA

ZIP: 93620

PURCHASE ORDER: N/A
 OFW #: L0839
 COPY TO: No cc Req.

PLM ANALYSIS

Analyte	Results Volume %	Detect Limit Volume %
ASBESTOS		
CHRYSTILE	ND	1. %
AMOSITE	ND	1. %
CROCIDOLITE	ND	1. %
ANTHOPHYLITE	ND	1. %
TREMOLITE-ACTONOLITE	ND	1. %
FIBER GLASS	ND	1. %
MINERAL WOOL	ND	1. %
CELLULOSE	15-28 %	1. %
NON FIBROUS MATERIALS	80-85 %	1. %
COLOR	White	

Method: EPA Interim Method for the Determination
 of Asbestos in Bulk Insulation Samples

EPA 600/4-82-020

This report may not be used to
 claim product endorsement by
 NVLAP or any agency of the
 U.S. Government.

File: CWL.PLM

APPROVED: 

Building: MBA Girls DormFunctional Area No. B-G06-AS Location: restroomType of Suspect Material: ☒ Surfacing, ☐ TSI, ☐ OtherDescription: acoustical sprayApproximate Amount of Material (linear or square ft.): 140ConditionPercent Damage: 25 %, ☒ Localized, ☐ DistributedType of Damage: ☒ Deterioration, ☐ Water, ☒ Physical

Description: _____

Overall Rating: ☐ Good, ☐ Fair, ☒ PoorPotential for DisturbanceAccessibility: ☒ Accessible, ☐ Inaccessible

Description: _____

Potential for Contact: ☐ High, ☐ Moderate, ☒ Low

Description: _____

Influence of Vibration: ☐ High, ☐ Moderate, ☒ Low

Description: _____

Potential for Air Erosion: ☐ High, ☐ Moderate, ☒ Low

Description: _____

Located in a Plenum? ☐ Yes, ☒ No; Type: _____

Comments: _____

Signed: ge Date: 12-26-88

CERTIFICATE OF ANALYSIS

LAB I.D.: P-74120
 SAMPLE LOCATION: 23-GD6-~~45~~
 COLLECTED BY: Client
 DATE COLLECTED: Not Given

DATE RECEIVED: December 27, 1988
 DATE STARTED: January 6, 1989
 DATE COMPLETED: January 6, 1989
 DATE REPORTED: January 10, 1989

CLIENT: Eslinger, Herbert
 STREET: 9545 W. Hwy 152
 CITY: Dos Palos
 STATE: CA ZIP: 93620

PURCHASE ORDER: N/A
 OFW #: L0839
 COPY TO: No cc Req.

PLM ANALYSIS

Analyte	Results Volume %	Detect Limit Volume %
ASBESTOS		
CHRYSTILE	ND	1. %
AMOSITE	ND	1. %
CROCIDOLITE	ND	1. %
ANTHOPHYLITE	ND	1. %
TREMOLITE-ACTONOLITE	ND	1. %
FIBER GLASS	ND	1. %
MINERAL WOOL	ND	1. %
CELLULOSE	45-50 %	1. %
NON FIBROUS MATERIALS	50-55 %	1. %
COLOR	Brown & White	

Method: EPA Interim Method for the Determination
 of Asbestos in Bulk Insulation Samples EPA 600/4-82-020

APPROVED: Scott Foster

This report may not be used to
 claim product endorsement by
 NVLAP or any agency of the
 U.S. Government.

File: CWL.PLM

Building: MBA - Gil DownFunctional Area No. 23-CD6-VP Location: restroomType of Suspect Material: ☒ Surfacing, ☐ TSI, ☐ OtherDescription: Vinyl wall paperApproximate Amount of Material (linear or square ft.): 80ConditionPercent Damage: 0 %, ☐ Localized, ☐ DistributedType of Damage: ☐ Deterioration, ☐ Water, ☐ Physical

Description: _____

Overall Rating: ☒ Good, ☐ Fair, ☐ PoorPotential for DisturbanceAccessibility: ☒ Accessible, ☐ Inaccessible

Description: _____

Potential for Contact: ☐ High, ☒ Moderate, ☐ Low

Description: _____

Influence of Vibration: ☐ High, ☐ Moderate, ☒ Low

Description: _____

Potential for Air Erosion: ☐ High, ☐ Moderate, ☒ Low

Description: _____

Located in a Plenum? ☐ Yes, ☒ No; Type: _____

Comments: _____

Signed: ge Date: 12-26-88

CERTIFICATE OF ANALYSIS

LAB I.D.: P-74885
 SAMPLE LOCATION: 23-6D6-VP
 COLLECTED BY: Client
 DATE COLLECTED: Not Given

DATE RECEIVED: December 27, 1988
 DATE STARTED: January 5, 1989
 DATE COMPLETED: January 5, 1989
 DATE REPORTED: January 18, 1989

CLIENT: Eslinger, Herbert
 STREET: 9545 W. Hwy 152
 CITY: Dos Palos
 STATE: CA

ZIP: 93620

PURCHASE ORDER: N/A
 OFW #: L8839
 COPY TO: No cc Req.

PLM ANALYSIS

Analyte	Results Volume %	Detect Limit Volume %
ASBESTOS		
CHRYSDTILE	ND	1. %
AMOSITE	ND	1. %
CROCIDOLITE	ND	1. %
ANTHOPHYLITE	ND	1. %
TREMOLITE-ACTONOLITE	ND	1. %
FIBER GLASS	ND	1. %
MINERAL WOOL	ND	1. %
CELLULOSE	70-75 %	1. %
NON FIBROUS MATERIALS	25-30 %	1. %
COLOR	Brown & White	

Method: EPA Interim Method for the Determination
 of Asbestos in Bulk Insulation Samples

EPA 600/4-82-020

This report may not be used to
 claim product endorsement by
 NVLAP or any agency of the
 U.S. Government.

APPROVED: 

File: CWL.PLM

Building: MBA - Girls DormFunctional Area No. 23-GD-AS Location: lobbyType of Suspect Material: ☒ Surfacing, ☐ TSI, ☐ OtherDescription: acoustical spray - also in hallwayApproximate Amount of Material (linear or square ft.): 3000ConditionPercent Damage: 2 %, ☒ Localized, ☐ DistributedType of Damage: ☐ Deterioration, ☐ Water, ☒ Physical

Description: _____

Overall Rating: ☒ Good, ☐ Fair, ☐ PoorPotential for DisturbanceAccessibility: ☒ Accessible, ☐ Inaccessible

Description: _____

Potential for Contact: ☐ High, ☐ Moderate, ☒ Low

Description: _____

Influence of Vibration: ☐ High, ☒ Moderate, ☐ LowDescription: second floor is abovePotential for Air Erosion: ☐ High, ☐ Moderate, ☒ Low

Description: _____

Located in a Plenum? ☐ Yes, ☒ No; Type: _____

Comments: _____

Signed: GL Date: 12-26-88

CERTIFICATE OF ANALYSIS

LAB I.D.: P-74883
 SAMPLE LOCATION: 23-GD1-AS
 COLLECTED BY: Client
 DATE COLLECTED: Not Given

DATE RECEIVED: December 27, 1988
 DATE STARTED: January 4, 1989
 DATE COMPLETED: January 4, 1989
 DATE REPORTED: January 10, 1989

CLIENT: Eslinger, Herbert
 STREET: 9545 W. Hwy 152
 CITY: Dos Palos
 STATE: CA

ZIP: 93620

PURCHASE ORDER: N/A
 OFW #: L0839
 COPY TO: No cc Req.

PLM ANALYSIS

Analyte	Results Volume %	Detect Limit Volume %
ASBESTOS		
CHRYSDOTILE	ND	1. %
AMOSITE	ND	1. %
CROCIDOLITE	ND	1. %
ANTHOPHYLITE	ND	1. %
TREMOLITE-ACTONOLITE	ND	1. %
FIBER GLASS	ND	1. %
MINERAL WOOL	ND	1. %
CELLULOSE	ND	1. %
NON FIBROUS MATERIALS	100 %	1. %
COLOR	White	

Method: EPA Interim Method for the Determination
 of Asbestos in Bulk Insulation Samples EPA 680/4-82-020

This report may not be used to
 claim product endorsement by
 NVLAP or any agency of the
 U.S. Government.

APPROVED: 

File: CWL.PLM

Building: MBA — Girls Dorm
 Functional Area No. 23-609-VP Location: Restroom 2nd floor
 Type of Suspect Material: ☒ Surfacing, ☐ TSI, ☐ Other
 Description: mirrored wall paper

Approximate Amount of Material (linear or square ft.): 150

Condition

Percent Damage: 0 %, ☐ Localized, ☐ Distributed
 Type of Damage: ☐ Deterioration, ☐ Water, ☐ Physical
 Description: _____

Overall Rating: ☒ Good, ☐ Fair, ☐ Poor

Potential for Disturbance

Accessibility: ☒ Accessible, ☐ Inaccessible

Description: _____

Potential for Contact: ☐ High, ☒ Moderate, ☐ Low

Description: _____

Influence of Vibration: ☐ High, ☐ Moderate, ☒ Low

Description: _____

Potential for Air Erosion: ☐ High, ☐ Moderate, ☒ Low

Description: _____

Located in a Plenum? ☐ Yes, ☒ No; Type: _____

Comments: _____

Signed: gf Date: 12-26-88

CERTIFICATE OF ANALYSIS

LAB I.D.: P-74881
 SAMPLE LOCATION: 23-GD9-VP
 COLLECTED BY: Client
 DATE COLLECTED: Not Given

DATE RECEIVED: December 27, 1988
 DATE STARTED: January 4, 1989
 DATE COMPLETED: January 4, 1989
 DATE REPORTED: January 18, 1989

CLIENT: Eslinger, Herbert
 STREET: 9545 W. Hwy 152
 CITY: Dos Palos
 STATE: CA ZIP: 93628

PURCHASE ORDER: N/A
 OFW #: L8839
 COPY TO: No cc Req.

PLM ANALYSIS

Analyte	Results Volume %	Detect Limit Volume %
ASBESTOS		
CHRYSTILE	ND	1. %
AMOSITE	ND	1. %
CROCIDOLITE	ND	1. %
ANTHOPHYLITE	ND	1. %
TREMOLITE-ACTONOLITE	ND	1. %
FIBER GLASS	ND	1. %
MINERAL WOOL	ND	1. %
CELLULOSE	70-75 %	1. %
NON FIBROUS MATERIALS	25-30 %	1. %
COLOR	Green, Pink, White & Blue	

Method: EPA Interim Method for the Determination
 of Asbestos in Bulk Insulation Samples

EPA 600/4-82-020

This report may not be used to
 claim product endorsement by
 NVLAP or any agency of the
 U.S. Government.
 File: CWL.PLM

APPROVED: Scott Foster

EXHIBIT 13-10 RECORDING FORM FOR ASSESSMENT DATA

Building: MBA - Girl Down.Functional Area No. B3-602-V Location: Ice roomType of Suspect Material: ☒ Surfacing, ☐ TSI, ☐ OtherDescription: Wing floor.Approximate Amount of Material (linear or square ft.): 175ConditionPercent Damage: 2 %, ☐ Localized, ☒ DistributedType of Damage: ☐ Deterioration, ☐ Water, ☒ Physical

Description: _____

Overall Rating: ☒ Good, ☐ Fair, ☐ PoorPotential for DisturbanceAccessibility: ☒ Accessible, ☐ Inaccessible

Description: _____

Potential for Contact: ☐ High, ☒ Moderate, ☐ Low

Description: _____

Influence of Vibration: ☐ High, ☐ Moderate, ☒ Low

Description: _____

Potential for Air Erosion: ☐ High, ☐ Moderate, ☒ Low

Description: _____

Located in a Plenum? ☐ Yes, ☒ No; Type: _____

Comments: _____

Signed: ge Date: 12-26-88

CERTIFICATE OF ANALYSIS

LAB I.D.: P-74877
 SAMPLE LOCATION: 23-GD12-V
 COLLECTED BY: Client
 DATE COLLECTED: Not Given

DATE RECEIVED: December 27, 1988
 DATE STARTED: January 4, 1989
 DATE COMPLETED: January 4, 1989
 DATE REPORTED: January 10, 1989

CLIENT: Eslinger, Herbert
 STREET: 9545 W. Hwy 152
 CITY: Dos Palos
 STATE: CA

ZIP: 93620

PURCHASE ORDER: N/A
 OFW #: L8839
 COPY TO: No cc Req.

PLM ANALYSIS

Analyte	Results Volume %	Detect Limit Volume %
ASBESTOS		
CHRYSDOTILE	ND	1. %
AMOSITE	ND	1. %
CROCIDOLITE	ND	1. %
ANTHOPHYLITE	ND	1. %
TREMOLITE-ACTONOLITE	ND	1. %
FIBER GLASS	ND	1. %
MINERAL WOOL	ND	1. %
CELLULOSE	60-65 %	1. %
NON FIBROUS MATERIALS	35-65 %	1. %
COLOR	Brown & Gray	

Method: EPA Interim Method for the Determination
 of Asbestos in Bulk Insulation Samples EPA 600/4-82-020

APPROVED: 

This report may not be used to
 claim product endorsement by
 NVLAP or any agency of the
 U.S. Government.

File: CWL.PLM

Building: MBA - Girls Dorm
Functional Area No. 23CD11-VP Location: 2nd floor RR. (south)
Type of Suspect Material: ☒ Surfacing, ☐ TSI, ☐ Other
Description: Worn wall paper

Approximate Amount of Material (~~linear~~ or square ft.): 45

Condition

Percent Damage: 0 %, ☐ Localized, ☐ Distributed
Type of Damage: ☐ Deterioration, ☐ Water, ☐ Physical
Description: _____

Overall Rating: ☒ Good, ☐ Fair, ☐ Poor

Potential for Disturbance

Accessibility: ☒ Accessible, ☐ Inaccessible

Description: _____

Potential for Contact: ☐ High, ☒ Moderate, ☐ Low

Description: _____

Influence of Vibration: ☐ High, ☐ Moderate, ☒ Low

Description: _____

Potential for Air Erosion: ☐ High, ☐ Moderate, ☒ Low

Description: _____

Located in a Plenum? ☐ Yes, ☒ No; Type: _____

Comments: _____

Signed: [Signature] Date: 12-26-88

CERTIFICATE OF ANALYSIS

LAB I.D.: P-74076
 SAMPLE LOCATION: 23-GD11-VP
 COLLECTED BY: Client
 DATE COLLECTED: Not Given

DATE RECEIVED: December 27, 1988
 DATE STARTED: January 4, 1989
 DATE COMPLETED: January 4, 1989
 DATE REPORTED: January 10, 1989

CLIENT: Eslinger, Herbert
 STREET: 9545 W. Hwy 152
 CITY: Dos Palos
 STATE: CA

ZIP: 93628

PURCHASE ORDER: N/A
 OFW #: L0839
 COPY TO: No cc Req.

PLM ANALYSIS

Analyte	Results Volume %	Detect Limit Volume %
ASBESTOS		
CHRYSTOTILE	ND	1. %
ANOSITE	ND	1. %
CROCIDOLITE	ND	1. %
ANTHOPHYLITE	ND	1. %
TREMOLITE-ACTONOLITE	ND	1. %
FIBER GLASS	ND	1. %
MINERAL WOOL	ND	1. %
CELLULOSE	55-60 %	1. %
NON FIBROUS MATERIALS	40-45 %	1. %
COLOR	White	

Method: EPA Interim Method for the Determination
 of Asbestos in Bulk Insulation Samples EPA 600/4-82-028

APPROVED: 

This report may not be used to
 claim product endorsement by
 NVLAP or any agency of the
 U.S. Government.

File: CWL.PLM

Building: MBA - Girl Room
Functional Area No. B-6D10-V Location: 2nd floor south RLC
Type of Suspect Material: Surfacing, TSI, ☒ Other
Description: vinyl floor

Approximate Amount of Material (linear or square ft.): 90

Condition

Percent Damage: 0 %, Localized, Distributed
Type of Damage: Deterioration, Water, Physical
Description:

Overall Rating: ☒ Good, Fair, Poor

Potential for Disturbance

Accessibility: ☒ Accessible, Inaccessible

Description:

Potential for Contact: High, ☒ Moderate, Low

Description:

Influence of Vibration: High, Moderate, ☒ Low

Description:

Potential for Air Erosion: High, Moderate, ☒ Low

Description:

Located in a Plenum? Yes, ☒ No; Type:

Comments:

Signed:  Date: 12-26-88

CERTIFICATE OF ANALYSIS

LAB I.D.: P-74075
 SAMPLE LOCATION: 23-6D10-V
 COLLECTED BY: Client
 DATE COLLECTED: Not Given

DATE RECEIVED: December 27, 1988
 DATE STARTED: January 4, 1989
 DATE COMPLETED: January 4, 1989
 DATE REPORTED: January 10, 1989

CLIENT: Eslinger, Herbert
 STREET: 9545 W. Hwy 152
 CITY: Dos Palos
 STATE: CA

ZIP: 93620

PURCHASE ORDER: N/A
 OFW #: L8839
 COPY TO: No cc Req.

PLM ANALYSIS

Analyte	Results Volume %	Detect Limit Volume %
ASBESTOS		
CHRYSTOTILE	ND	1. %
AMOSITE	ND	1. %
CROCIDOLITE	ND	1. %
ANTHOPHYLITE	ND	1. %
TREMOLITE-ACTONOLITE	ND	1. %
FIBER GLASS	ND	1. %
MINERAL WOOL	ND	1. %
CELLULOSE	3-5 %	1. %
NON FIBROUS MATERIALS	95-97 %	1. %
COLOR	White	

Method: EPA Interim Method for the Determination
 of Asbestos in Bulk Insulation Samples

EPA 600/4-82-020

This report may not be used to
 claim product endorsement by
 NVLAP or any agency of the
 U.S. Government.

File: CHL.PLM



APPROVED:

Scott Foster

SCHOOL:

MBA - Church + Store.

ROOM #	ROOM NAME	FLOOR COVERING	WALL TEXTURE	CEILING TEXTURE	MISC. COVERING	REMARKS
4	Nadleroll	Cret	brick + SR	AS		
6	Men R.R.	12x12 Spanish til.	SR	SR		
3	Kindergarten	cret.	brick + SR	AS		
2	Primary	"	"	"		
1	Junior	"	"	"		
10	Sanctuary	"	"	6"tg		
7	Museum	"	"	AS		
8	Lobby	"	"	"		
	All other compartment	"	"	SR		
5	Ladies R.R.	12x12 Spanish til.	SR	SR		
2	STORE	vinyl	SR	SR		
1	" Storage	vinyl	fiberglass	SR		symmetric



23-Cu4-AS

MONTEREY BAY SDA ACADEMY CHURCH.
Built 1989
15,960 sq ft total.

Building: MBA - church.

Functional Area No. 23-Cu4-A5 Location: chadle room

Type of Suspect Material: ☒ Surfacing, ☐ TSI, ☐ Other

Description: acoustical suspended ceiling, also in kindergarten primary, junior, nursery, church lobby.

Approximate Amount of Material (linear or square ft.): 5325

Condition

Percent Damage: 0 %, ☐ Localized, ☐ Distributed

Type of Damage: ☐ Deterioration, ☐ Water, ☐ Physical

Description: _____

Overall Rating: ☒ Good, ☐ Fair, ☐ Poor

Potential for Disturbance

Accessibility: ☐ Accessible, ☒ Inaccessible

Description: 8 ft up.

Potential for Contact: ☐ High, ☐ Moderate, ☒ Low

Description: the atmosphere doesn't lend itself to throwing things at the ceiling

Influence of Vibration: ☐ High, ☐ Moderate, ☒ Low

Description: _____

Potential for Air Erosion: ☐ High, ☐ Moderate, ☒ Low

Description: _____

Located in a Plenum? ☐ Yes, ☒ No; Type: _____

Comments: _____

Signed: gc Date: 12-22-88

CERTIFICATE OF ANALYSIS

LAB I.D.: P-74109
 SAMPLE LOCATION: 23-094-AS
 COLLECTED BY: Client
 DATE COLLECTED: Not Given

DATE RECEIVED: December 27, 1988
 DATE STARTED: January 6, 1989
 DATE COMPLETED: January 6, 1989
 DATE REPORTED: January 10, 1989

CLIENT: Eslinger, Herbert
 STREET: 9545 W. Hwy 152
 CITY: Dos Palos
 STATE: CA

ZIP: 93620

PURCHASE ORDER: N/A
 OFW #: L0839
 COPY TO: No cc Req.

PLM ANALYSIS

Analyte	Results Volume %	Detect Limit Volume %
ASBESTOS		
CHRYSTILE	3-5 %	1. %
AMOSITE	ND	1. %
CROCIDOLITE	ND	1. %
ANTHOPHYLITE	ND	1. %
TREMOLITE-ACTONOLITE	ND	1. %
FIBER GLASS	ND	1. %
MINERAL WOOL	ND	1. %
CELLULOSE	ND	1. %
NON FIBROUS MATERIALS	95-97 %	1. %
COLOR	White	

Method: EPA Interim Method for the Determination
 of Asbestos in Bulk Insulation Samples

EPA 600/4-82-020


This report may not be used to
 claim product endorsement by
 NVLAP or any agency of the

U.S. Government.

File: CWL.PLM

APPROVED: 

GROCERY STORE,
MonteRey Bay Academy
1300 sq ft.



Building: MBA - store

Functional Area No. ^{STI-V} 23-ST-V Location: store storage

Type of Suspect Material: Surfacing, TSI, ☒ Other

Description: vinyl floor

Approximate Amount of Material (linear or square ft.): 1300

Condition

Percent Damage: 2 %, Localized, ☒ Distributed

Type of Damage: Deterioration, Water, ☒ Physical

Description: _____

Overall Rating: Good, ☒ Fair, Poor

Potential for Disturbance

Accessibility: ☒ Accessible, Inaccessible

Description: _____

Potential for Contact: High, ☒ Moderate, Low

Description: _____

Influence of Vibration: High, Moderate, ☒ Low

Description: _____

Potential for Air Erosion: High, Moderate, ☒ Low

Description: _____

Located in a Plenum? Yes, ☒ No; Type: _____

Comments: _____

Signed: gf Date: 12-22-88

CERTIFICATE OF ANALYSIS

LAB I.D.: P-74112
 SAMPLE LOCATION: 23-ST1-V
 COLLECTED BY: Client
 DATE COLLECTED: Not Given

DATE RECEIVED: December 27, 1988
 DATE STARTED: January 6, 1989
 DATE COMPLETED: January 6, 1989
 DATE REPORTED: January 10, 1989

CLIENT: Eslinger, Herbert
 STREET: 9545 W. Hwy 152
 CITY: Dos Palos
 STATE: CA

ZIP: 93628

PURCHASE ORDER: N/A
 OFW #: L8839
 COPY TO: No cc Req.

PLM ANALYSIS

Analyte	Results Volume %	Detect Limit Volume %
ASBESTOS		
CHRYSTOTILE	ND	1. %
AMOSITE	ND	1. %
CROCIDOLITE	ND	1. %
ANTHOPHYLITE	ND	1. %
TREMOLITE-ACTONOLITE	ND	1. %
FIBER GLASS	ND	1. %
MINERAL WOOL	ND	1. %
CELLULOSE	5-18 %	1. %
NON FIBROUS MATERIALS	90-95 %	1. %
COLOR	Black	

Method: EPA Interim Method for the Determination
 of Asbestos in Bulk Insulation Samples EPA 600/4-82-020

This report may not be used to
 claim product endorsement by
 NVLAP or any agency of the
 U.S. Government.


APPROVED: 

File: CWL.PLM

SCHOOL:


MBA - Little Lake Ind

ROOM #	ROOM NAME	FLOOR COVERING	WALL TEXTURE	CEILING TEXTURE	MISC. COVERING	REMARKS
1	office	vinyl/crpt	SR/wd panel	SR		sample
5	entrance to shop	12x12	SR	SR		
	shop	conc	metal	metal	heating ducts?	
	<u>MBA PACKAGE</u>		umbrella plant			
1	shop	conc.	wood	wood		
2	office	9x9	SR	SR	heating vent asbestos?	green tile same wood shop office
	<u>DAIRY</u>					
2	milk barn	conc.	brick	wd/plas		
6	west side of shop		slate			sample
	<u>Rainbow Building</u>					
4	office	vinyl/crpt	wd/SR	SR		sample
5, 7, 11	shop	crpt/conc	SR	SR		
	<u>Pili Farm</u>					
	shop	conc	wd	wd		
	<u>Boat Manufacture</u>					
	shop	conc	wd	wd		
	<u>Sheet Metal Building</u>					
	shop	conc	wd	wd		



8316 sq ft.

CB MARINA
PRIVATE INDUSTRY
- APPROX. 8 STUDENTS



3028. sq ft.

RAINBOW INDUSTRIES.
APPROX 10 STUDENTS

EXHIBIT 13-10 RECORDING FORM FOR ASSESSMENT DATA

Building: MBA - Rainbow Trns

Functional Area No. 23-R4-V Location: Office

Type of Suspect Material: Surfacing, TSI, ☒ Other

Description: Single floor covering

Approximate Amount of Material (linear or square ft.): 32

Condition

Percent Damage: 0 %, Localized, Distributed

Type of Damage: Deterioration, Water, Physical

Description: _____

Overall Rating: ☒ Good, Fair, Poor

Potential for Disturbance

Accessibility: ☒ Accessible, Inaccessible

Description: _____

Potential for Contact: High, ☒ Moderate, Low

Description: _____

Influence of Vibration: High, Moderate, ☒ Low

Description: _____

Potential for Air Erosion: High, Moderate, ☒ Low

Description: _____

Located in a Plenum? Yes, ☒ No; Type: _____

Comments: _____

Signed: ge Date: 12-26-88

CERTIFICATE OF ANALYSIS

LAB I.D.: P-74867
 SAMPLE LOCATION: 23-R4-V
 COLLECTED BY: Client
 DATE COLLECTED: Not Given

DATE RECEIVED: December 27, 1988
 DATE STARTED: January 3, 1989
 DATE COMPLETED: January 3, 1989
 DATE REPORTED: January 18, 1989

CLIENT: Eslinger, Herbert
 STREET: 9545 W. Hwy 152
 CITY: Dos Palos
 STATE: CA ZIP: 93620

PURCHASE ORDER: N/A
 OFW #: L8839
 COPY TO: No cc Req.

PLM ANALYSIS



Analyte	Results Volume %	Detect Limit Volume %
ASBESTOS		
CHRYSTOLE	2-3 %	1. %
AMOSITE	ND	1. %
CROCIDOLITE	ND	1. %
ANTHOPHYLITE	ND	1. %
TREMOLITE-ACTONOLITE	ND	1. %
FIBER GLASS	ND	1. %
MINERAL WOOL	ND	1. %
CELLULOSE	ND	1. %
NON FIBROUS MATERIALS	97-98 %	1. %
COLOR	Brown	

Method: EPA Interim Method for the Determination
 of Asbestos in Bulk Insulation Samples EPA 680/4-82-820

This report may not be used to
 claim product endorsement by
 NVLAP or any agency of the
 U.S. Government.

File: CWL.PLM

APPROVED: Scott Foster



Building: MBA - Little Lake Ind.Functional Area No. 23-441-V Location: OfficeType of Suspect Material: Surfacing, TSI, ☒ OtherDescription: vinyl floor coveringApproximate Amount of Material (linear or square ft.): 64ConditionPercent Damage: 0 %, Localized, DistributedType of Damage: Deterioration, Water, Physical

Description: _____

Overall Rating: ☒ Good, Fair, PoorPotential for DisturbanceAccessibility: ☒ Accessible, Inaccessible

Description: _____

Potential for Contact: High, ☒ Moderate, Low

Description: _____

Influence of Vibration: High, Moderate, ☒ Low

Description: _____

Potential for Air Erosion: High, Moderate, ☒ Low

Description: _____

Located in a Plenum? Yes, ☒ No; Type: _____

Comments: _____

Signed: ge Date: 12-26-88

CERTIFICATE OF ANALYSIS

LAB I.D.: P-74059
 SAMPLE LOCATION: 23-LL1-V
 COLLECTED BY: Client
 DATE COLLECTED: Not Given

DATE RECEIVED: December 27, 1988
 DATE STARTED: January 3, 1989
 DATE COMPLETED: January 3, 1989
 DATE REPORTED: January 10, 1989

CLIENT: Eslinger, Herbert
 STREET: 9545 W. Hwy 152
 CITY: Dos Palos
 STATE: CA

ZIP: 93620

PURCHASE ORDER: N/A
 OFW #: L0839
 COPY TO: No cc Req.

PLM ANALYSIS

Analyte	Results Volume %	Detect Limit Volume %
ASBESTOS		
CHRYSTOTILE	ND	1. %
AMOSITE	ND	1. %
CROCIDOLITE	ND	1. %
ANTHOPHYLITE	ND	1. %
TREMOLITE-ACTONOLITE	ND	1. %
FIBER GLASS	3-5 %	1. %
MINERAL WOOL	ND	1. %
CELLULOSE	3-5 %	1. %
NON FIBROUS MATERIALS	98-94 %	1. %
COLOR	Brown & White	

Method: EPA Interim Method for the Determination
 of Asbestos in Bulk Insulation Samples

EPA 600/4-82-020



APPROVED: 

This report may not be used to
 claim product endorsement by
 NVLAP or any agency of the
 U.S. Government.

File: CWL.PLM



SCHOOL: MBA Grounds

[illegible]



SCHOOL: MBA - Science

[illegible]



Building: MBA - Science DeptFunctional Area No. 23-512-YPI Location: room-ec.Type of Suspect Material: ☒ Surfacing, ☐ TSI, ☐ OtherDescription: cracked wall paperApproximate Amount of Material (linear or square ft.): 240ConditionPercent Damage: 10 %, ☐ Localized, ☐ DistributedType of Damage: ☐ Deterioration, ☐ Water, ☐ Physical

Description: _____

Overall Rating: ☒ Good, ☐ Fair, ☐ PoorPotential for DisturbanceAccessibility: ☒ Accessible, ☐ Inaccessible

Description: _____

Potential for Contact: ☐ High, ☒ Moderate, ☐ Low

Description: _____

Influence of Vibration: ☐ High, ☐ Moderate, ☒ Low

Description: _____

Potential for Air Erosion: ☐ High, ☐ Moderate, ☒ Low

Description: _____

Located in a Plenum? ☐ Yes, ☒ No; Type: _____

Comments: _____

Signed: ge Date: 12-22-88

CERTIFICATE OF ANALYSIS

LAB I.D.: P-74897
 SAMPLE LOCATION: 23-S12-VP1
 COLLECTED BY: Client
 DATE COLLECTED: Not Given

DATE RECEIVED: December 27, 1988
 DATE STARTED: January 5, 1989
 DATE COMPLETED: January 5, 1989
 DATE REPORTED: January 10, 1989

CLIENT: Eslinger, Herbert
 STREET: 9545 W. Hwy 152
 CITY: Dos Palos
 STATE: CA ZIP: 93620

PURCHASE ORDER: N/A
 OFW #: L0839
 COPY TO: No cc Req.

PLM ANALYSIS

Analyte	Results Volume %	Detect Limit Volume %
ASBESTOS		
CHRYSDOTILE	ND	1. %
AMOSITE	ND	1. %
CROCIDOLITE	ND	1. %
ANTHOPHYLITE	ND	1. %
TREMOLITE-ACTONOLITE	ND	1. %
FIBER GLASS	ND	1. %
MINERAL WOOL	ND	1. %
CELLULOSE	55-60 %	1. %
NON FIBROUS MATERIALS	40-45 %	1. %
COLOR	Pink & White	

Method: EPA Interim Method for the Determination
 of Asbestos in Bulk Insulation Samples EPA 600/4-82-020

APPROVED: 

This report may not be used to
 claim product endorsement by
 NVLAP or any agency of the
 U.S. Government.

File: CWL.PLM

Building: MBA - Science Dept
Functional Area No. 23-512-VP Location: conference room, kitchen
Type of Suspect Material: ☒ Surfacing, ☐ TSI, ☐ Other
Description: rough wall paper

Approximate Amount of Material (linear or square ft.): 240

Condition

Percent Damage: ☒ %, ☐ Localized, ☐ Distributed
Type of Damage: ☐ Deterioration, ☐ Water, ☐ Physical
Description: _____

Overall Rating: ☒ Good, ☐ Fair, ☐ Poor

Potential for Disturbance

Accessibility: ☒ Accessible, ☐ Inaccessible

Description: _____

Potential for Contact: ☐ High, ☒ Moderate, ☐ Low

Description: _____

Influence of Vibration: ☐ High, ☐ Moderate, ☒ Low

Description: _____

Potential for Air Erosion: ☐ High, ☐ Moderate, ☒ Low

Description: _____

Located in a Plenum? ☐ Yes, ☒ No; Type: _____

Comments: _____

Signed: gpc Date: 12-22-86

CERTIFICATE OF ANALYSIS

LAB I.D.: P-74114
 SAMPLE LOCATION: 23-S12-VP
 COLLECTED BY: Client
 DATE COLLECTED: Not Given

DATE RECEIVED: December 27, 1988
 DATE STARTED: January 6, 1989
 DATE COMPLETED: January 6, 1989
 DATE REPORTED: January 10, 1989

CLIENT: Eslinger, Herbert
 STREET: 9545 W. Hwy 152
 CITY: Dos Palos
 STATE: CA

ZIP: 93620

PURCHASE ORDER: N/A.
 OFW #: L0839
 COPY TO: No cc Req.

PLM ANALYSIS

Analyte	Results Volume %	Detect Limit Volume %
ASBESTOS		
CHRYSDOTILE	ND	1. %
AMOSITE	ND	1. %
CROCIDOLITE	ND	1. %
ANTHOPHYLITE	ND	1. %
TREMOLITE-ACTONOLITE	ND	1. %
FIBER GLASS	ND	1. %
MINERAL WOOL	ND	1. %
CELLULOSE	30-35 %	1. %
NON FIBROUS MATERIALS	65-70 %	1. %
COLOR	Brown & White	

Method: EPA Interim Method for the Determination
 of Asbestos in Bulk Insulation Samples EPA 600/4-82-020

This report may not be used to
 claim product endorsement by
 NVLAP or any agency of the
 U.S. Government.

File: CNL.PLM

APPROVED: 

Building: MBA - ScienceFunctional Area No. 23-512-V Location: Area 6cType of Suspect Material: Surfacing, TSI, ☒ OtherDescription: 9x9 tile - through-out science bldg.Approximate Amount of Material (linear or square ft.): 5000ConditionPercent Damage: 2 %, ☒ Localized, DistributedType of Damage: Deterioration, Water, ☒ Physical

Description: _____

Overall Rating: ☒ Good, Fair, PoorPotential for DisturbanceAccessibility: ☒ Accessible, Inaccessible

Description: _____

Potential for Contact: High, ☒ Moderate, LowDescription: most under carpetInfluence of Vibration: High, Moderate, ☒ Low

Description: _____

Potential for Air Erosion: High, Moderate, ☒ Low

Description: _____

Located in a Plenum? Yes, ☒ No; Type: _____

Comments: _____

Signed: [Signature] Date: 12-22-88

CERTIFICATE OF ANALYSIS

LAB I.D.: P-74113
 SAMPLE LOCATION: 23-S12-V
 COLLECTED BY: Client
 DATE COLLECTED: Not Given

DATE RECEIVED: December 27, 1988
 DATE STARTED: January 6, 1989
 DATE COMPLETED: January 6, 1989
 DATE REPORTED: January 10, 1989

CLIENT: Eslinger, Herbert
 STREET: 9545 W. Hwy 152
 CITY: Dos Palos
 STATE: CA ZIP: 93620

PURCHASE ORDER: N/A
 OFW #: L0839
 COPY TO: No cc Req.

PLM ANALYSIS

Analyte	Results Volume %	Detect Limit Volume %
ASBESTOS		
CHRYSTOTILE	ND	1. %
AMOSITE	ND	1. %
CROCIDOLITE	ND	1. %
ANTHOPHYLITE	ND	1. %
TREMOLITE-ACTONOLITE	ND	1. %
FIBER GLASS	ND	1. %
MINERAL WOOL	ND	1. %
CELLULOSE	ND	1. %
NON FIBROUS MATERIALS	100 %	1. %
COLOR	Gray	

Method: EPA Interim Method for the Determination
 of Asbestos in Bulk Insulation Samples EPA 600/4-82-020

APPROVED: 

This report may not be used to
 claim product endorsement by
 NVLAP or any agency of the
 U.S. Government.

File: CHL.PLM

EXHIBIT 13-10 RECORDING FORM FOR ASSESSMENT DATA

Building: MBA - Science dept
 Functional Area No. 23-512-CT Location: home economics, teacher

Type of Suspect Material: Surfacing, TSI, ☒ Other
 Description: 1 1/2 x 3 ceiling tile - through school, adm. classrooms, science,

Approximate Amount of Material (linear or square ft.): 30,000

Condition

Percent Damage: 2 %, ☒ Localized, Distributed
 Type of Damage: ☒ Deterioration, Water, Physical
 Description: _____

Overall Rating: ☒ Good, Fair, Poor

Potential for Disturbance

Accessibility: Accessible, ☒ Inaccessible
 Description: _____

Potential for Contact: High, Moderate, ☒ Low
 Description: _____

Influence of Vibration: High, Moderate, ☒ Low
 Description: _____

Potential for Air Erosions: High, Moderate, ☒ Low
 Description: _____

Located in a Plenum? Yes, ☒ No; Type: _____

Comments: _____

Signed: GR Date: 12-22-88

CERTIFICATE OF ANALYSIS

LAB I.D.: P-74111
 SAMPLE LOCATION: 23-S12-CT
 COLLECTED BY: Client
 DATE COLLECTED: Not Given

DATE RECEIVED: December 27, 1988
 DATE STARTED: January 6, 1989
 DATE COMPLETED: January 6, 1989
 DATE REPORTED: January 10, 1989

CLIENT: Eslinger, Herbert
 STREET: 9545 W. Hwy 152
 CITY: Dos Palos
 STATE: CA ZIP: 93620

PURCHASE ORDER: N/A
 OFW #: L8839
 COPY TO: No cc Req.

PLM ANALYSIS

Analyte	Results Volume %	Detect- Limit Volume %
ASBESTOS		
CHRYSTOTILE	ND	1. %
AMOSITE	ND	1. %
CROCIDOLITE	ND	1. %
ANTHOPHYLITE	ND	1. %
TREMOLITE-ACTONOLITE	ND	1. %
FIBER GLASS	ND	1. %
MINERAL WOOL	ND	1. %
CELLULOSE	100 %	1. %
NON FIBROUS MATERIALS	ND	1. %
COLOR	Brown	

Method: EPA Interim Method for the Determination
 of Asbestos in Bulk Insulation Samples EPA 600/4-82-020

This report may not be used to
 claim product endorsement by
 NVLAP or any agency of the
 U.S. Government.

APPROVED: 

File: CWL.PLM

Building: MBA - ScienceFunctional Area No. 23-55-fb Location: Biology officeType of Suspect Material: ☒ Surfacing, ☐ TSI, ☐ OtherDescription: 4x8 sheets - fiber board w/ strawlike material - same as gym ceiling.Approximate Amount of Material (linear or square ft.): 15000ConditionPercent Damage: 0 %, ☐ Localized, ☐ DistributedType of Damage: ☐ Deterioration, ☐ Water, ☐ Physical

Description: _____

Overall Rating: ☒ Good, ☐ Fair, ☐ PoorPotential for DisturbanceAccessibility: ☐ Accessible, ☒ InaccessibleDescription: majority is out of reachPotential for Contact: ☐ High, ☐ Moderate, ☒ Low

Description: _____

Influence of Vibration: ☐ High, ☐ Moderate, ☒ Low

Description: _____

Potential for Air Erosion: ☐ High, ☐ Moderate, ☒ Low

Description: _____

Located in a Plenum? ☐ Yes, ☒ No; Type: _____

Comments: _____

Signed: gf Date: 12-22-88

CERTIFICATE OF ANALYSIS

LAB I.D.: P-74358
 SAMPLE LOCATION: 23-S5-FB
 COLLECTED BY: Client
 DATE COLLECTED: Not Given

DATE RECEIVED: January 4, 1989
 DATE STARTED: January 9, 1989
 DATE COMPLETED: January 9, 1989
 DATE REPORTED: January 11, 1989

CLIENT: Eslinger, Herbert
 STREET: 9545 W. Hwy 152
 CITY: Dos Palos
 STATE: CA ZIP: 93620

PURCHASE ORDER: N/A
 OFW #: L8884
 COPY TO: No cc Req.

PLM ANALYSIS

Analyte	Results Volume %	Detect Limit Volume %
ASBESTOS		
CHRYSTOTILE	ND	1. %
AMOSITE	ND	1. %
CROCIDOLITE	ND	1. %
ANTHOPHYLITE	ND	1. %
TREMOLITE-ACTONOLITE	ND	1. %
FIBER GLASS	ND	1. %
MINERAL WOOL	ND	1. %
CELLULOSE	65-70 %	1. %
NON FIBROUS MATERIALS	30-35 %	1. %
COLOR	Tan, White & Black	

Method: EPA Interim Method for the Determination
 of Asbestos in Bulk Insulation Samples EPA 600/4-82-020

APPROVED: 

This report may not be used to
 claim product endorsement by
 NVLAP or any agency of the
 U.S. Government.
 File: CWL.PLM

Building: MBA - Science dept.Functional Area No. 23-52-T Location: JanitorType of Suspect Material: Surfacing, TSI, ☒ Other
Description: 9x9 tile (light brown) same throughout
science dept.Approximate Amount of Material (linear or square ft.): 5300ConditionPercent Damage: 2 %, Localized, DistributedType of Damage: Deterioration, Water, ☒ Physical

Description: _____

Overall Rating: ☒ Good, Fair, PoorPotential for DisturbanceAccessibility: ☒ Accessible, InaccessibleDescription: Some is under carpetPotential for Contact: High, ☒ Moderate, Low

Description: _____

Influence of Vibration: High, Moderate, ☒ Low

Description: _____

Potential for Air Erosion: High, Moderate, ☒ Low

Description: _____

Located in a Plenum? Yes, ☒ No; Type: _____

Comments: _____

Signed: gf Date: 12-22-88

CERTIFICATE OF ANALYSIS

LAB I.D.: P-74110
 SAMPLE LOCATION: 23-52-T
 COLLECTED BY: Client
 DATE COLLECTED: Not Given

DATE RECEIVED: December 27, 1988
 DATE STARTED: January 6, 1989
 DATE COMPLETED: January 6, 1989
 DATE REPORTED: January 10, 1989

CLIENT: Eslinger, Herbert
 STREET: 9545 W. Hwy 152
 CITY: Dos Palos
 STATE: CA

ZIP: 93620

PURCHASE ORDER: N/A
 OFW #: L0839
 COPY TO: No cc Req.

PLM ANALYSIS

Analyte	Results Volume %	Detect Limit Volume %
ASBESTOS		
CHRYSTILE	ND	1. %
AMOSITE	ND	1. %
CROCIDOLITE	ND	1. %
ANTHOPHYLITE	ND	1. %
TRENOLITE-ACTONOLITE	ND	1. %
FIBER GLASS	ND	1. %
MINERAL WOOL	ND	1. %
CELLULOSE	ND	1. %
NON FIBROUS MATERIALS	100 %	1. %
COLOR	Brown	

Method: EPA Interim Method for the Determination
 of Asbestos in Bulk Insulation Samples

EPA 600/4-82-020

This report may not be used to
 claim product endorsement by
 NVLAP or any agency of the
 U.S. Government.

APPROVED: 

File: CWL.PLM

PHYSICAL AND HAZARD ASSESSMENT OF FRIABLE
ACBM OR FRIABLE ASSUMED ACBM (Form C)
(SEC. 763.93)

				CDS CODE 44-69799-6940787	
SCHOOL Monterey Bay Academy				School Phone # (408)728-1481	
ADDRESS		(NUMBER) 783 San Andreas Road	(CITY) La Selva Beach	(ZIP CODE) 95076-1907	
BUILDING NAME Cafeteria				INSPECTION DATE 12-22-88	
FUNCTIONAL SPACE Store Area - #12 (23-C12-PI)			INDICATE LINE # FROM FORM B 10		
TYPE OF FRIABLE ACBM	SURFACING	<input checked="" type="checkbox"/> TSI	MISCELLANEOUS		
1. CONDITION OF ACBM (OVERALL RATING)					
<input checked="" type="checkbox"/> GOOD <input type="checkbox"/> DAMAGED <input type="checkbox"/> SIGNIFICANTLY DAMAGED					
2. POTENTIAL FOR DISTURBANCE (Overall Rating)					
<input type="checkbox"/> LOW <input checked="" type="checkbox"/> MODERATE <input type="checkbox"/> HIGH					
3. HAZARD ASSESSMENT (Combine ratings from items 1 and 2 and check appropriate box)					
CONDITION OF ACBM			Potential for Disturbance		
			LOW	MODERATE	HIGH
GOOD				X	
DAMAGED					
SIGNIFICANTLY DAMAGED					
4. RECOMMENDED RESPONSE ACTION(S) AND COST(S)			Estimated Costs		
<input checked="" type="checkbox"/> A. OPERATION AND MAINTENANCE			\$ 350.00		
<input checked="" type="checkbox"/> B. REPAIR			\$ 150.00		
<input checked="" type="checkbox"/> C. ENCAPSULATION			\$ 550.00		
<input type="checkbox"/> D. ENCLOSURE			\$		
<input type="checkbox"/> E. REMOVAL			\$		
TOTAL			\$ 1050.00		

5. NARRATIVE OF RECOMMENDED RESPONSE ACTIONS

Schedule

	start	complete
Since this pipe insulation is in the store room of the cafeteria we have placed it in a high priority category. Form D will explain the operation and maintenance in detail. There are a few areas in the pipe insulation that need repair before encapsulation takes place. Use an asbestos free compound to seal and repair all nicks and places that are showing deterioration. The pipe insulation is in good condition at present and removal is not pertinent at the moment but we recommend encapsulating the material with ABS-100 sealant, or equivalent, to seal all asbestos fibers from being released into the area.	7-9-89	12-31-89

PHYSICAL AND HAZARD ASSESSMENT OF FRIABLE
ACBM OR FRIABLE ASSUMED ACBM (Form C)
(SEC. 763.93)

C0

				CDS CODE 44-69799-6940787	
SCHOOL Monterey Bay Academy				School Phone # (408) 728-1481	
ADDRESS		(NUMBER) 783 San Andreas Road	(CITY) La Selva Beach	(ZIP CODE) 95076-1907	
BUILDING NAME Auto Mechanics				INSPECTION DATE 12-22-88	
FUNCTIONAL SPACE Shop area - #1 (23-AM1-C)			INDICATE LINE # FROM FORM B 12		
TYPE OF FRIABLE ACBM	SURFACING	TSI	X	MISCELLANEOUS	
1. CONDITION OF ACBM (OVERALL RATING)					
<input checked="" type="checkbox"/> GOOD <input type="checkbox"/> DAMAGED <input type="checkbox"/> SIGNIFICANTLY DAMAGED					
2. POTENTIAL FOR DISTURBANCE (Overall Rating)					
<input type="checkbox"/> LOW <input checked="" type="checkbox"/> MODERATE <input type="checkbox"/> HIGH					
3. HAZARD ASSESSMENT (Combine ratings from items 1 and 2 and check appropriate box)					
CONDITION OF ACBM			Potential for Disturbance		
			LOW	MODERATE	HIGH
GOOD				X	
DAMAGED					
SIGNIFICANTLY DAMAGED					
4. RECOMMENDED RESPONSE ACTION(S) AND COST(S)				Estimated Costs	
<input type="checkbox"/> A. OPERATION AND MAINTENANCE				\$	
<input type="checkbox"/> B. REPAIR				\$	
<input type="checkbox"/> C. ENCAPSULATION				\$	
<input type="checkbox"/> D. ENCLOSURE				\$	
<input checked="" type="checkbox"/> E. REMOVAL				\$ 45.00	
TOTAL				\$ 45.00	

5. NARRATIVE OF RECOMMENDED RESPONSE ACTIONS	Schedule	
	start	complete
	7-9-89	12-31-89

This curtain contains 90% to 95% chrysotile which is a form of asbestos. Even though it is in good condition we recommend you dispose of it and replace it with a product which doesn't contain asbestos. This will release you of any continue operation and maintenance program for this product.

PHYSICAL AND HAZARD ASSESSMENT OF FRIABLE
ACBM OR FRIABLE ASSUMED ACBM (Form C)
(SEC. 763.93)

C1

				CDS CODE 44-69799-6940787	
SCHOOL Monterey Bay Academy				School Phone # (408)728-1481	
ADDRESS		(NUMBER) 783 San Andreas Road	(CITY) La Selva Beach	(ZIP CODE) 95076-1907	
BUILDING NAME Maintenance Dept.				INSPECTION DATE 12-22-88	
FUNCTIONAL SPACE Office - #8 (23-M8-AS)			INDICATE LINE # FROM FORM B 13		
TYPE OF FRIABLE ACBM	<input checked="" type="checkbox"/> SURFACING	<input type="checkbox"/> TSI	<input type="checkbox"/> MISCELLANEOUS		
1. CONDITION OF ACBM (OVERALL RATING)					
<input checked="" type="checkbox"/> GOOD <input type="checkbox"/> DAMAGED <input type="checkbox"/> SIGNIFICANTLY DAMAGED					
2. POTENTIAL FOR DISTURBANCE (Overall Rating)					
<input checked="" type="checkbox"/> LOW <input type="checkbox"/> MODERATE <input type="checkbox"/> HIGH					
3. HAZARD ASSESSMENT (Combine ratings from items 1 and 2 and check appropriate box)					
CONDITION OF ACBM			Potential for Disturbance		
			LOW	MODERATE	HIGH
GOOD			X		
DAMAGED					
SIGNIFICANTLY DAMAGED					
4. RECOMMENDED RESPONSE ACTION(S) AND COST(S)					
			Estimated Costs		
<input checked="" type="checkbox"/> A. OPERATION AND MAINTENANCE			\$ 100.00		
<input type="checkbox"/> B. REPAIR			\$		
<input checked="" type="checkbox"/> C. ENCAPSULATION			\$ 1350.00		
<input type="checkbox"/> D. ENCLOSURE			\$		
<input type="checkbox"/> E. REMOVAL			\$		
TOTAL			\$ 1450.00		

5. NARRATIVE OF RECOMMENDED RESPONSE ACTIONS	Schedule	
	start	complete
	7-9-89	7-9-92

The operation and maintenance will be discussed in form D in more detail. Since this ceiling was sprayed on just a few years ago the condition is fairly good. Removal is not necessary at this time but we do recommend encapsulating with ABS-100 sealant, or equivalent. Removal would cost anywhere from \$1000.00 to \$5000.00. We don't recommend enclosure because this expense is greater than encapsulation and the ACBM would still be in the building and would have to be monitored at each inspection just like the girls dormitory ceiling. Whenever someone exposes this layer by drilling or in any other way, this person will have to have had the 16hr. training and take full measures to protect him or herself. If you decide on removal at this time you will have saved the encapsulation cost because sooner or later ACBM is to be removed from the schools.

PHYSICAL AND HAZARD ASSESSMENT OF FRIABLE
ACBM OR FRIABLE ASSUMED ACBM (Form C)
(SEC. 763.93)

C2

CDS CODE
44-69799-6940787

SCHOOL
Monterey Bay Academy

School Phone #
(408)728-1481

ADDRESS (NUMBER)
783 San Andreas Road

(CITY)
La Selva Beach

(ZIP CODE)
95076-1907

BUILDING NAME
Boys Dormitory

INSPECTION DATE
12-22-88

FUNCTIONAL SPACE
Boiler Room - #10 (23-BD10-PI)

INDICATE LINE # FROM FORM B
15

TYPE OF FRIABLE ACBM

SURFACING

☒ TSI

MISCELLANEOUS

1. CONDITION OF ACBM (OVERALL RATING)

☐ GOOD

☐ DAMAGED

☒ SIGNIFICANTLY DAMAGED

2. POTENTIAL FOR DISTURBANCE (Overall Rating)

☒ LOW

☐ MODERATE

☐ HIGH

3. HAZARD ASSESSMENT (Combine ratings from items 1 and 2 and check appropriate box)

CONDITION OF ACBM	Potential for Disturbance		
	LOW	MODERATE	HIGH
GOOD			
DAMAGED			
SIGNIFICANTLY DAMAGED	X		

4. RECOMMENDED RESPONSE ACTION(S) AND COST(S)

Estimated Costs

☒ A. OPERATION AND MAINTENANCE \$ 165.00

☐ B. REPAIR \$

☒ C. ENCAPSULATION \$ 1632.00

☐ D. ENCLOSURE \$

☒ E. REMOVAL \$ 525.00

TOTAL \$ 2322.00

5. NARRATIVE OF RECOMMENDED RESPONSE ACTIONS

Schedule

	start	complete
	7-9-89	7-9-92

The operation and maintenance will be discussed on form D more in detail. The pipe insulation under the dormitory is in good condition and out of reach to the general public. Therefore at this time we recommend encapsulating with ABS-100 sealant, or equivalent. The pipe insulation in the boiler room on the other hand, and leading under the dormitory, is in poor condition and should be removed.

PHYSICAL AND HAZARD ASSESSMENT OF FRIABLE
ACBM OR FRIABLE ASSUMED ACBM (Form C)
(SEC. 763.93)

C3

				CDS CODE 44-69799-6940787	
SCHOOL Monterey Bay Academy				School Phone # (408)728-1481	
ADDRESS		(NUMBER) 783 San Andreas Road	(CITY) La Selva Beach	(ZIP CODE) 95076-1907	
BUILDING NAME Boys Dormitory				INSPECTION DATE 12-22-88	
FUNCTIONAL SPACE Chapel - #1 (23-BD1-AS)			INDICATE LINE # FROM FORM B 17		
TYPE OF FRIABLE ACBM	<input checked="" type="checkbox"/> SURFACING	<input type="checkbox"/> TSI	<input type="checkbox"/> MISCELLANEOUS		
1. CONDITION OF ACBM (OVERALL RATING)					
<input checked="" type="checkbox"/> GOOD <input type="checkbox"/> DAMAGED <input type="checkbox"/> SIGNIFICANTLY DAMAGED					
2. POTENTIAL FOR DISTURBANCE (Overall Rating)					
<input checked="" type="checkbox"/> LOW <input type="checkbox"/> MODERATE <input type="checkbox"/> HIGH					
3. HAZARD ASSESSMENT (Combine ratings from items 1 and 2 and check appropriate box)					
CONDITION OF ACBM			Potential for Disturbance		
			LOW	MODERATE	HIGH
GOOD			X		
DAMAGED					
SIGNIFICANTLY DAMAGED					
4. RECOMMENDED RESPONSE ACTION(S) AND COST(S)			Estimated Costs		
<input checked="" type="checkbox"/> A. OPERATION AND MAINTENANCE			\$ 800.00		
<input type="checkbox"/> B. REPAIR			\$		
<input checked="" type="checkbox"/> C. ENCAPSULATION			\$ 4000.00		
<input type="checkbox"/> D. ENCLOSURE			\$		
<input type="checkbox"/> E. REMOVAL			\$		
TOTAL			\$ 4800.00		

5. NARRATIVE OF RECOMMENDED RESPONSE ACTIONS	Schedule	
	start	complete
	7-9-89	7-9-94

The operation and maintenance will be discussed on form D more in detail. The acoustical sprayed ceiling and wall in the chapel is ACBM. The condition is good so we recommend encapsulating with ABS-100 sealant, or equivalent. Removal is an option that would cost anywhere from \$6600.00 to \$26000.00. The good thing about removal is that there is no longer the ongoing operation and maintenance cost or the encapsulation cost.

PHYSICAL AND HAZARD ASSESSMENT OF FRIABLE
ACBM OR FRIABLE ASSUMED ACBM (Form C)
(SEC. 763.93)

C4

				CDS CODE 44-69799-6940787	
SCHOOL Monterey Bay Academy				School Phone # (408)728-1481	
ADDRESS		(NUMBER) 783 San Andreas Road	(CITY) La Selva Beach	(ZIP CODE) 95076-1907	
BUILDING NAME Girls Dormitory				INSPECTION DATE 12-22-88	
FUNCTIONAL SPACE Storage - #4 (23-GD4-PI)			INDICATE LINE # FROM FORM B 21		
TYPE OF FRIABLE ACBM	SURFACING	<input checked="" type="checkbox"/> TSI	MISCELLANEOUS		
1. CONDITION OF ACBM (OVERALL RATING)					
<input checked="" type="checkbox"/> GOOD <input type="checkbox"/> DAMAGED <input type="checkbox"/> SIGNIFICANTLY DAMAGED					
2. POTENTIAL FOR DISTURBANCE (Overall Rating)					
<input checked="" type="checkbox"/> LOW <input type="checkbox"/> MODERATE <input type="checkbox"/> HIGH					
3. HAZARD ASSESSMENT (Combine ratings from items 1 and 2 and check appropriate box)					
CONDITION OF ACBM			Potential for Disturbance		
			LOW	MODERATE	HIGH
GOOD			X		
DAMAGED					
SIGNIFICANTLY DAMAGED					
4. RECOMMENDED RESPONSE ACTION(S) AND COST(S)			Estimated Costs		
<input checked="" type="checkbox"/> A. OPERATION AND MAINTENANCE			\$ 285.00		
<input type="checkbox"/> B. REPAIR			\$		
<input checked="" type="checkbox"/> C. ENCAPSULATION			\$ 300.00		
<input type="checkbox"/> D. ENCLOSURE			\$		
<input type="checkbox"/> E. REMOVAL			\$		
TOTAL			\$ 585.00		

5. NARRATIVE OF RECOMMENDED RESPONSE ACTIONS

Schedule

	start	complete
	7-9-89	7-9-92
<p>The operation and maintenance will be discussed on form D more in detail. The pipe insulation in the storage is in good condition and need not be removed at this time. We recommend encapsulating with ABS-100 sealant, or equivalent. Removal is an option though that could cost anywhere from \$1000.00 to \$2000.00.</p>		

PHYSICAL AND HAZARD ASSESSMENT OF FRIABLE
ACBM OR FRIABLE ASSUMED ACBM (Form C)
(SEC. 763.93)

C5

CDS CODE
44-69799-6940787

SCHOOL
Monterey Bay Academy

School Phone #
(408) 728-1481

ADDRESS (NUMBER)
783 San Andreas Road

(CITY)
La Selva Beach

(ZIP CODE)
95076-1907

BUILDING NAME
Girls Dormitory

INSPECTION DATE
12-22-88

FUNCTIONAL SPACE
Boiler Room - #3 (23-GD3-PI)

INDICATE LINE # FROM FORM B
22

TYPE OF FRIABLE ACBM

SURFACING

☒ TSI

MISCELLANEOUS

1. CONDITION OF ACBM (OVERALL RATING)

☐ GOOD

☐ DAMAGED

☒ SIGNIFICANTLY DAMAGED

2. POTENTIAL FOR DISTURBANCE (Overall Rating)

☒ LOW

☐ MODERATE

☐ HIGH

3. HAZARD ASSESSMENT (Combine ratings from items 1 and 2 and check appropriate box)

CONDITION OF ACBM	Potential for Disturbance		
	LOW	MODERATE	HIGH
GOOD			
DAMAGED			
SIGNIFICANTLY DAMAGED	X		

4. RECOMMENDED RESPONSE ACTION(S) AND COST(S)

Estimated Costs

<input checked="" type="checkbox"/> A. OPERATION AND MAINTENANCE	\$ 250.00
<input type="checkbox"/> B. REPAIR	\$
<input checked="" type="checkbox"/> C. ENCAPSULATION	\$ 1632.00
<input type="checkbox"/> D. ENCLOSURE	\$
<input checked="" type="checkbox"/> E. REMOVAL	\$ 2100.00
TOTAL	\$ 3982.00

5. NARRATIVE OF RECOMMENDED RESPONSE ACTIONS

Schedule

	start	complete
	7-9-89	7-9-92

The operation and maintenance will be discussed on form D more in detail. The pipe insulation under the dormitory is in good condition and out of reach to the general public. Therefore at this time we recommend encapsulating with ABS-100 sealant, or equivalent. The pipe insulation in the boiler room on the other hand, and leading under the dormitory, is in poor condition and should be removed.

PHYSICAL AND HAZARD ASSESSMENT OF FRIABLE
ACBM OR FRIABLE ASSUMED ACBM (Form C)
(SEC. 763.93)

C6

				CDS CODE 44-69799-6940787	
SCHOOL Monterey Bay Academy				School Phone # (408)728-1481	
ADDRESS		(NUMBER) 783 San Andreas Road	(CITY) La Selva Beach	(ZIP CODE) 95076-1907	
BUILDING NAME Girls Dormitory				INSPECTION DATE 12-22-88	
FUNCTIONAL SPACE Chapel - #5 (23-GD5-AS)			INDICATE LINE # FROM FORM B 23		
TYPE OF FRIABLE ACBM	<input checked="" type="checkbox"/> SURFACING	<input type="checkbox"/> TSI	<input type="checkbox"/> MISCELLANEOUS		
1. CONDITION OF ACBM (OVERALL RATING)					
<input checked="" type="checkbox"/> GOOD <input type="checkbox"/> DAMAGED <input type="checkbox"/> SIGNIFICANTLY DAMAGED					
2. POTENTIAL FOR DISTURBANCE (Overall Rating)					
<input checked="" type="checkbox"/> LOW <input type="checkbox"/> MODERATE <input type="checkbox"/> HIGH					
3. HAZARD ASSESSMENT (Combine ratings from items 1 and 2 and check appropriate box)					
CONDITION OF ACBM			Potential for Disturbance		
			LOW	MODERATE	HIGH
GOOD			X		
DAMAGED					
SIGNIFICANTLY DAMAGED					
4. RECOMMENDED RESPONSE ACTION(S) AND COST(S)			Estimated Costs		
<input checked="" type="checkbox"/> A. OPERATION AND MAINTENANCE			\$ 950.00		
<input type="checkbox"/> B. REPAIR			\$		
<input checked="" type="checkbox"/> C. ENCAPSULATION			\$ 1665.00		
<input type="checkbox"/> D. ENCLOSURE			\$		
<input type="checkbox"/> E. REMOVAL			\$		
TOTAL			\$ 2615.00		

5. NARRATIVE OF RECOMMENDED RESPONSE ACTIONS	Schedule	
	start	complete
	7-9-89	7-9-94

The operation and maintenance will be discussed on form D in more detail. The acoustical spray is on the back wall of the chapel and is in good condition. Encapsulate with ABS-100 sealant, or equivalent. Removal is also an option and would cost anywhere from \$2700.00 to \$6000.00.

PHYSICAL AND HAZARD ASSESSMENT OF FRIABLE
ACBM OR FRIABLE ASSUMED ACBM (Form C)
(SEC. 763.93)

C7

		CDS CODE 44-69799-6940787		
SCHOOL Monterey Bay Academy		School Phone # (408)728-1481		
ADDRESS	(NUMBER) 783 San Andreas Road	(CITY) La Selva Beach	(ZIP CODE) 95076-1907	
BUILDING NAME Church		INSPECTION DATE 12-22-88		
FUNCTIONAL SPACE Cradle Room - #4 (23-CU4-AS)		INDICATE LINE # FROM FORM B 23		
TYPE OF FRIABLE ACBM	<input checked="" type="checkbox"/> SURFACING	<input type="checkbox"/> TSI	MISCELLANEOUS	
1. CONDITION OF ACBM (OVERALL RATING)				
<input checked="" type="checkbox"/> GOOD <input type="checkbox"/> DAMAGED <input type="checkbox"/> SIGNIFICANTLY DAMAGED				
2. POTENTIAL FOR DISTURBANCE (Overall Rating)				
<input checked="" type="checkbox"/> LOW <input type="checkbox"/> MODERATE <input type="checkbox"/> HIGH				
3. HAZARD ASSESSMENT (Combine ratings from items 1 and 2 and check appropriate box)				
CONDITION OF ACBM		Potential for Disturbance		
		LOW	MODERATE	HIGH
GOOD		X		
DAMAGED				
SIGNIFICANTLY DAMAGED				
4. RECOMMENDED RESPONSE ACTION(S) AND COST(S)		Estimated Costs		
<input checked="" type="checkbox"/> A. OPERATION AND MAINTENANCE		\$ 2328.00		
<input type="checkbox"/> B. REPAIR		\$		
<input checked="" type="checkbox"/> C. ENCAPSULATION		\$13968.00		
<input type="checkbox"/> D. ENCLOSURE		\$		
<input type="checkbox"/> E. REMOVAL		\$		
TOTAL		\$16296.00		

5. NARRATIVE OF RECOMMENDED RESPONSE ACTIONS	Schedule	
	start	complete
	7-9-89	7-9-95

The operation and maintenance will be discussed on form D in more detail. The acoustical spray is in good condition therefore encapsulate with ABS-100 sealant, or equivalent. Removal is also an option and would cost anywhere from \$23000.00 to \$46000.00.

PHYSICAL AND HAZARD ASSESSMENT OF FRIABLE
ACBM OR FRIABLE ASSUMED ACBM (Form C)
(SEC. 763.93)

C8

		CDS CODE 44-69799-6940787
SCHOOL Monterey Bay Academy		School Phone # (408) 728-1481

ADDRESS	(NUMBER) 783 San Andreas Road	(CITY) La Selva Beach	(ZIP CODE) 95076-1907
---------	----------------------------------	--------------------------	--------------------------

BUILDING NAME Girls Dormitory	INSPECTION DATE 12-22-88
----------------------------------	-----------------------------

FUNCTIONAL SPACE New Wing hallway	INDICATE LINE # FROM FORM B 27
--------------------------------------	-----------------------------------

TYPE OF FRIABLE ACBM	<input checked="" type="checkbox"/> SURFACING	<input type="checkbox"/> TSI	<input type="checkbox"/> MISCELLANEOUS
----------------------	---	------------------------------	--

1. CONDITION OF ACBM (OVERALL RATING)

☒ GOOD ☐ DAMAGED ☐ SIGNIFICANTLY DAMAGED

2. POTENTIAL FOR DISTURBANCE (Overall Rating)

☒ LOW ☐ MODERATE ☐ HIGH

3. HAZARD ASSESSMENT (Combine ratings from items 1 and 2 and check appropriate box)

CONDITION OF ACBM	Potential for Disturbance		
	LOW	MODERATE	HIGH
GOOD	X		
DAMAGED			
SIGNIFICANTLY DAMAGED			

4. RECOMMENDED RESPONSE ACTION(S) AND COST(S)	Estimated Costs
<input type="checkbox"/> A. OPERATION AND MAINTENANCE_____	\$ _____
<input type="checkbox"/> B. REPAIR_____	\$ _____
<input type="checkbox"/> C. ENCAPSULATION_____	\$ _____
<input checked="" type="checkbox"/> D. ENCLOSURE_____	\$ _____
<input type="checkbox"/> E. REMOVAL_____	\$ _____
TOTAL	\$ _____

5. NARRATIVE OF RECOMMENDED RESPONSE ACTIONS	Schedule	
	started	completed
	1985	1985

The old acoustical sprayed ceiling in the hallway has been resheeted with sheet rock creating enclosure. We have made note of this in the report for the record.

OPERATIONS AND MAINTENANCE PROGRAM
(FORM D)

23

				CDS CODE 44-69799-6940787
SCHOOL Monterey Bay Academy				SCHOOL PHONE # (408)728-1481
ADDRESS	(number)	(street)	(city)	(zip code)
	783	San Andreas Road	La Selva Beach	95076-1907

For each area where friable ACBM is present, assumed to be present, or is about to become present, write an operations and maintenance (O & M) program.

This O & M program must be developed for the entire school. The program must describe worker protection, initial and additional cleaning programs, building occupant protection (access control, signs, control of air movement, work practices, areacleaning, disposal methods), design and performance of other than small-scale, short-duration maintenance activities, and activities associated with minor and major fiber release episodes (Sec. 763.91).

IMPORTANT

Use Forms E through H to describe specific elements of this program. Use additional sheets when necessary.

All ACBM that is of a non-friable state abstain from sanding, drilling, or anything that would change the ACBM to a friable condition. If ACBM becomes friable the following steps will have to apply. For all other ACBM that is friable the following steps must apply when applicable.

INITIAL CLEANING:

Custodial Staff should:

Steam-clean all carpets throughout the building or vacuum them with a High Efficiency Particulate Air (HEPA)-filtered vacuum cleaner, but never with a conventional vacuum cleaner. Spray vacuum cleaner bags with water before removal and discard in sealed plastic bags according to EPA regulations for removal and disposal of asbestos. Discard vacuum filters in a similar manner.

HEPA-vacuum all curtains and books. Discard vacuum bags and filters in sealed plastic bags according to EPA regulations for disposal of asbestos waste.

Mop all non-carpeted floors with wet mop-s. Wipe all shelves and other horizontal surfaces with damp cloths. Use a mist spray bottle to keep cloths damp. Discard cloths and mop heads in sealed plastic bags according to EPA regulations for disposal of asbestos waste.

MONTHLY CLEANING:

Custodial Staff should:

Spray with water any debris found near surfacing ACM and place the debris in plastic bags using a dust pan. Rinse the pan with water in a utility sink. Report presence of debris immediately to the O&M Program Coordinator.

HEPA-vacuum all carpets.

Wet-mop all other floors and wipe all other horizontal surfaces with damp cloths.

Dispose of all debris, filters, mop heads, and cloths in plastic bags according to EPA regulations for disposal of asbestos waste.

* Please note following page: "A GUIDE FOR REDUCING ASBESTOS EXPOSURE"

A GUIDE FOR REDUCING ASBESTOS EXPOSURE

PURPOSE

Your school building contains materials which contain asbestos and may release fibers into the air. Breathing asbestos fibers is dangerous. This fact sheet tells how to reduce exposure to asbestos fibers. Please read it carefully.

PROTECTING YOURSELF FROM ASBESTOS

Some of the friable building materials in your school contain asbestos. Friable asbestos-containing materials crumble easily and release fibers into the air. Breathing these fibers may cause cancer and other diseases. The more asbestos you breathe, the greater your chances are of getting disease. You can take precautions that will reduce or eliminate the risk of being exposed to asbestos.

Find out from your supervisor where these friable asbestos-containing materials are in your building. Do not touch or disturb them unless you have to. If you must handle an asbestos-containing material, first lightly spray it with water, (EPA recommends using water which contains wetting agents, if they are available.) Wet asbestos-containing material will not release as many fibers.

Even if friable asbestos-containing materials are not disturbed, they may release asbestos fibers, which will fall slowly to the floor. If you are cleaning in areas which contain these materials, do not use a broom: it will stir the fibers into the air. Do not use a vacuum cleaner unless it is equipped with a High Efficiency Particulate Absolute filter. The fibers are so small they can pass through an ordinary vacuum cleaner and out into the room.

When cleaning in areas which contain friable asbestos-containing materials, use dampened mops and dustcloths. Dampened mops and dustcloths will hold the fibers much better than dry mops and dustcloths, and will reduce the number of fibers put back into the air. It is best to use mops with disposable heads and to throw away the mop head after use. Otherwise fibers will be released as the mop dries. Use either lightly dampened mops or cloths or a vacuum with a High Efficiency Particulate Absolute filter to clean areas where wet mopping cannot be used (such as carpeting or hardwood floors).

Clean tables and chairs in the area with damp cloths. Do not dust them with brushes or with dry cloths, and do not vacuum them.

After you use the mop heads and cloths, put them in a plastic bag while they are still wet. Dislodged materials should also be placed in plastic bags for disposal.

A LIST OF IMPORTANT POINTS TO REMEMBER

1. Do not handle or disturb friable asbestos containing materials unless necessary.
2. If you must handle asbestos-containing materials, wet them first.
3. If you must disturb asbestos (for example, to repair a light), see your supervisor before starting work. Then:
 - a. Place a plastic dropcloth below the work area.
 - b. Spray asbestos-containing material with water before you disturb it.
 - c. Make sure that only those persons who are necessary for the job are in the area.
 - d. Put all the asbestos you remove into a heavy plastic bag. Seal the bag and discard it.
 - e. After the job, clean all the ladders and tools you used with a wet cloth.
 - f. Roll up the dropcloth carefully and put it in a plastic bag. Discard the bag.
 - g. Clean the floor below the work area with a wet mop.
 - h. Put the mop head and the cloth used to clean the ladders in a plastic bag while they are still wet, seal the bag, and discard it.
4. If you must disturb or remove large sections of asbestos-containing material, see your supervisor before you begin. The National Institute for Occupational Safety and Health recommends that a respirator approved for toxic dusts be worn during such work.

You should make arrangements to turn off the school's ventilation system if you are disturbing or removing large sections of asbestos-containing material. The ventilation system should remain off until the work is completed and the area has been cleaned.

PERIODIC SURVEILLANCE PLAN
(FORM E)

23

				CDS CODE 44-69799-6940787
SCHOOL Monterey Bay Academy				SCHOOL PHONE # (408)728-1481
ADDRESS	(number)	(street)	(city)	(zip code)
	783	San Andreas Road	La Selva Beach	95076-1907

This plan must include a periodic surveillance of each building with friable ACM and nonfriable ACM at least every six months. The person performing periodic surveillance must receive two hours general training and 14 hours of additional training if work performed might disturb asbestos. The person will record the date, the area of inspection, the inspector's name, the description of any changes of the materials, and also visual inspect the areas(Sec. 763.92).

Persons dealing with disturbed ACM must have at least 16 hours of training in dealing and handling ACM. Inspection must be done every six months or by July 9, 1989 and every six months there after with a three year inspection by a certified state inspector or by July 9, 1992.

PERIODIC INSPECTION

Building inspectors should:

Inspect all ACM materials for damage or deterioration at least twice a year and report findings to the O&M program coordinator.

Investigate the source of debris found by the custodial staff.

Custodial and maintenance staff should:

Inform the O&M program coordinator when damage to ACM is observed or when debris is cleaned up.

* NOTE the attached: "Reassessment of Asbestos-Containing Materials"
"Training and Periodic surveillance".

REASSESSMENT OF ASBESTOS-CONTAINING MATERIALS

Location of asbestos-containing material(s) (address, building, room(s), or general description: _____

Type of asbestos-containing material(s):

1. Sprayed or troweled on ceilings or walls.
2. Sprayed or troweled on structural members.
3. Insulation on pipes, tanks, or boilers.
4. Other (describe): _____

Abatement Status:

1. The material has been encapsulated _____, enclosed _____, neither _____.

Assessment:

1. Evidence of physical damage: _____

2. Evidence of water damage: _____

3. Evidence of delamination or other deterioration: _____

4. Degree of accessibility of the material: _____

5. Degree of activity near the material: _____

6. Location in an air plenum, air shaft, or air stream: _____

7. Other observations (including the condition of the encapsulant or enclosure, if any): _____

Signed: _____ Date: _____
(Evaluator)

Sec. 763.92 Training and periodic surveillance.

(a) *Training.* (1) The local education agency shall ensure, prior to the implementation of the O&M provisions of the management plan, that all members of its maintenance and custodial staff (custodians, electricians, heating/air conditioning engineers, plumbers, etc.) who may work in a building that contains ACBM receive awareness training of at least 2 hours, whether or not they are required to work with ACBM. New custodial and maintenance employees shall be trained within 60 days after commencement of employment. Training shall include, but not be limited to:

- (i) Information regarding asbestos and its various uses and forms.
- (ii) Information on the health effects associated with asbestos exposure.
- (iii) Locations of ACBM identified throughout each school building in which they work.
- (iv) Recognition of damage, deterioration, and delamination of ACBM.
- (v) Name and telephone number of the person designated to carry out general local education agency responsibilities under Sec. 763.84 and the availability and location of the management plan.

(2) The local education agency shall ensure that all members of its maintenance and custodial staff who conduct any activities that will result in the disturbance of ACBM shall receive training described in paragraph (a)(1) of this section and 14 hours of additional training. Additional training shall include, but not be limited to:

- (i) Descriptions of the proper methods of handling ACBM.
- (ii) Information on the use of respiratory protection as contained in the EPA/NIOSH *Guide to Respiratory Protection for the Asbestos Abatement Industry*, September 1986.
- (iii) Hands-on training in the use of respiratory protection, other personal protection measures, and good work practices.

(3) Local education agency maintenance and custodial staff who have attended EPA-approved asbestos training or received equivalent training for O&M and periodic surveillance activities involving asbestos shall be considered trained for the purposes of this section.

(b) *Periodic surveillance.* (1) At least once every 6 months after a management plan is in effect, each local education agency shall conduct periodic surveillance in each building that it leases, owns, or otherwise uses as a school building that contains ACBM or is assumed to contain ACBM.

(2) Each person performing periodic surveillance shall:

- (i) Visually inspect all areas that are identified in the management plan as ACBM or assumed ACBM.
- (ii) Record the date of the surveillance, his or her name, and any changes in the condition of the material.
- (iii) Submit to the person designated to carry out general local education agency responsibilities under Sec. 763.84 a copy of such record for inclusion in the management plan.

REINSPECTION PLAN
(FORM F)

23

				CDS CODE 44-69799-6940787
SCHOOL Monterey Bay Academy				SCHOOL PHONE # (408)728-1481
ADDRESS	(number)	(street)	(city)	(zip code)
	783	San Andreas Road	La Selva Beach	95076-1907

The plan must meet the reinspection requirements of Section 763.85. This plan will include a reinspection every three years by an accredited inspector.

The school must be reinspected in three years or by July 9, 1992 by a Certified Inspector, and every six months by a local inspector, documenting the conditions and state of ACM. Any changes must be documented, giving date of inspection and name of inspector.

* Note: Please note the following page, REINSPECTION.

REINSPECTION;

1. At least once every 3 years after a management plan is in effect, each local education agency shall conduct a reinspection of all friable and nonfriable known or assumed ACBM in each school building that they lease, own, or otherwise use as a school building.
2. Each inspection shall be made by an accredited inspector.
3. For each area of a school building, each person performing a reinspection shall:

Visually reinspect, and reassess, under Sec. 763.88, the condition of all friable known or assumed ACBM.

Visually inspect material that was previously considered nonfriable ACBM and touch the material to determine whether it has become friable since the last inspection.

Identify and homogeneous areas with material that has become friable since the last inspection.

For each homogeneous area of newly friable material that is already assumed to be ACBM, bulk samples may be collected and submitted for analysis in accordance with Sec. 763.86 and 763.87.

Assess, under Sec. 763.88, the condition of the newly friable material in areas where samples are collected, and newly friable materials in areas that are assumed to be ACBM.

Reassess, under Sec. 763.88, the condition of friable known or assumed ACBM previously identified.

Record the following and submit to the person designated under Sec. 763.84 a copy of such record for inclusion in the management plan within 30 days of the reinspection:

1. The date of the reinspection, the name and signature of the person making the reinspection, State of accreditation, and if applicable, his or her accreditation number, and any changes in the condition of known or assumed ACBM.
2. The exact locations where samples are collected during the reinspection, a description of the manner used to determine sampling locations, the name and signature of each accredited inspector who collected the samples, State of accreditation, and, if applicable, his or her accreditation number.
3. Any assessments or reassessments made of friable material, the name and signature of the accredited inspector making the assessments, State of accreditation, and, if applicable, his or her accreditation number.

PARENT/EMPLOYEE NOTIFICATION PROGRAM
(FORM G)

23

				CDS CODE 44-69799-6940787
SCHOOL Monterey Bay Academy				SCHOOL PHONE # (408)728-1481
ADDRESS	(number)	(street)	(city)	(zip code)
	783	San Andreas Road	La Selva Beach	95076-1907

In the discussion section of this form, information should be included that describes steps taken to inform workers and building occupants, or their legal guardians, about inspections, response actions, and post response action activities, including periodic reinspection and surveillance activities that are planned or in progress. Notifications must be made once each school year (Sec. 763.84).

Please send a letter similar to the one enclosed to all parents, teachers, workers, and or legal guardian of all students. This letter must go out annually until asbestos containing building material (ACBM) is no longer found in the school. We also will need a signed copy of the letter that is sent out. Also post this information: that the school has been inspected for asbestos according with EPA regulations and a report is located at a centralized location for all to review. Please note the attached form "Notice to School Employees". This notification must remain until all ACBM is removed from the school. If your school does not contain ACBM this needs only be posted for 30 days. Please make sure your staff; teachers, workers, & custodial persons are aware of this report and where it can be found for review.

Dear Parents, Teachers, Workers, or Legal Guardians:

Asbestos containing building material (ACBM) has been located in our school. If you have any questions, please come in at your convenience and look over the management plan which is located at the administrative office.

This report and all records regarding AHERA activities will be maintained at a centralized location and will be made available to you so that you can more fully understand what plans or actions are in progress concerning: inspections, response actions, post response action activities, periodic reinspection and surveillance activities.

Thank you for your continual support in christian education.

(Principal)

NOTICE TO SCHOOL EMPLOYEES

In accordance with EPA regulations, this school has been inspected for friable (easily crumbled) and non-friable materials which contain asbestos. Friable asbestos-containing material may cause health problems.

Friable and non-friable asbestos-containing material is present in

(Name of School)

A record of the inspection, a diagram of the location(s) of friable and non-friable asbestos-containing materials, and a copy of relevant EPA regulations are available in:

(building)

(room)

For further information, interested persons should call 800-424-9065 (554-1404 in the Washington, DC area).

Signed:

(Name)

(title)

Date

EVALUATION OF RESOURCES NEEDED
(FORM H)

23

				CDS CODE 44-69799-6940787
SCHOOL Monterey Bay Academy				SCHOOL PHONE # (408)728-1481
ADDRESS	(number)	(street)	(city)	(zip code)
	783	San Andreas Road	La Selva Beach	95076-1907
estimated total cost of response actions \$ 33,145.00		estimated total cost of inspections \$ 11,275.00		estimated total cost of management plan \$ 15,033.00

Discussion should include such information as funding required, equipment, facilities, support personnel (Sec. 763.93).

FUNDING REQUIRED

40 CFR Part 763 Final Rule and Notice:

IV. Economic impact

The cost of an asbestos inspection is estimated to range from \$1,144 to \$1,627 per school for schools with both surfacing and thermal systems insulation ACM. This cost varies depending upon the size of the school, the amount and type of ACM contained in the school, and the type of professional doing the work. The costs of sampling and analysis if friable materials are found will depend upon the number of samples taken and analyzed. Costs of analysis are estimated to range from \$25 to \$47 per sample. Assuming the average school has an analyze 20 samples, the cost of analysis will be \$500 to \$940 per school. The cost of mapping ACM is estimated to range from \$110 to over \$270 per school.

The cost of developing a management plan if asbestos-containing surfacing ACM or thermal systems insulation ACM is present is estimated to range from \$1,025 for an average-size public primary school to \$1,420 for an average size public secondary school. These estimates are weighted average of the costs of plans developed by trained school personnel and by outside consultants.

The cost of training for school employees involves a variety of factors ranging from course and accreditation exam fees to the possible expenses for any out of town travel required for the training. The estimated course fee for a 2-hour awareness session required of all school maintenance employees in schools with ACM is approximately \$50 per person.. The additional 14 hours of training for school maintenance workers who may come in contact with asbestos in doing minor repair and maintenance work that disturbs asbestos is estimated to cost \$250. A fee of \$420 is estimated for the 24 hours of training required for the certification of asbestos abatement workers doing more than just minor repair and small glove-bag removal jobs. The fee for the 40-hour training course and certification required for asbestos abatement contractors is estimated to be \$640.

Response action costs depend primarily on the condition of the asbestos in a school and to a lesser extent on many other factors. In general, for surfacing ACM in all but the significantly damaged category, it is likely that the primary response action undertaken by a school will be special O&M activities. Use of O&M activities would likely continue until or unless the ACBM deteriorates to a "significantly damaged" condition. The annual cost of a special O&M program (excluding acquisition of special equipment) is estimated to range from \$3,800 for a typical public primary school to \$5,100 for a typical public secondary school. Initial cleaning costs are expected to range from \$950 to \$1,400.

The cost of removal depends upon many factors including size of the project. The estimated cost of removal for a 4,000 sq. ft. project in which surfacing material is removed would be approximately \$51,300. The cost of removal for a 900 sq. ft. boiler wrap project is estimated to be approximately \$30,900. The total discounted costs of response actions were estimate assuming schools undertake a combination of response actions that depend on the condition of the ACM.

EQUIPMENT

For handling small removal jobs of 32 sq. ft. or less or cleaning of ACBM, the following will be needed:

- Gloves
- Glove bags (depending on the type of removal)
- Tyvecs (disposable coveralls)
- Negative air mask respirator
- Nepa-filter vacuum cleaner
- Plastic sheeting
- Plastic bags ("Danger-Asbestos")

For more information about Asbestos safety order:

ENVIRONMENTAL PROTECTION AGENCY (EPA)

General Asbestos Info: Library: (415) 974-8076

Technical Assistance: Schools: (415) 974-7551, -7056

NESHAP for removal & demolition regulations, for contractors, building owners:

1. Local Air Pollution Control (delegated local authority for NESHAP regs.)

Bay Area: (F.S. Alameda, Contra Costa, Marin, Napa, San Mateo, Santa Clara, Sonoma & Solano): (415) 771-6000

Other counties: "name of county Air Pollution Control District".

2. Emergency Notifications: Local APCD (above) and Janet Crawford, EPA NESHAPs Coordinator: (415) 974-7633

CONSULTANT list: 1. In phone books under "Industrial Hygienists of Asb. Consultants"

2. By calling American Lung Association for their list

a. San Francisco Office: (415) 543-4410

b. Los Angeles Office: (213) 935-5864

3. Listed in "American Indust. Hygiene Assoc. Journal" in January ;and July issues: (216) 762-7294

4. Pamphlet: ASBESTOS SAFETY EQUIPMENT

100 Gall Drive Suite #4

Novato, Ca. 94949

ph. (415) 892-9359

FACILITIES

Disposal Waste Dumps:

Berkeley: (415) 540-2043

Fresno: (209) 445-5938

Sacramento: (916) 739-3145

Contact Mr. Milton Thorman, (209) 291-7700, for information about the nearest drop sight for all your asbestos.

SUPPORT PERSONNEL

PACIFIC ASBESTOS INFORMATION CENTER: UC Berkeley Ext. courses: (415) 643-7143

OSHA: Worker Protection, enforcement and Industrial Hygiene consultation:

Federal OSHA: Toll free general info: (800) 648-1003

CAL/OSHA: Clovers State employees only: gen. consultation: (415) 557-1946

AHERA; For management of AHERA regulations, to provide lists of accredited persons, to receive the Management plans: California: (916) 445-9327.

NESHAPS: National Emissions Standards for Hazardous Air Pollutants regulates the emission of asbestos fibers for handling of asbestos in most buildings, and the disposal of asbestos-containing waste. The EPA/NESHAPS must be notified before the beginning of any project of more than 160 sq. ft. or 260 linear feet. Notify by mail to Ms. Janet Crawford A-3-3, NESHAPS Coordinator, NESHAPS A-3-3. EPA Region 9, 215 Fremont St. S.F., CA., 94105.

Air pollution Control District (APCD): These local agencies have been delegated primary authority to enforce EPA/NASHAP regulations. Contract the nearest county agency for information and notification requirements for asbestos projects.
BAAQMD: (415) 771-6000.

The following providers have either full or contingent approval in Region 9. Successful completion of either a fully approved course or a contingently approved course provides full accreditation for course attendees. Only if EPA subsequently withdrew contingent approval would future course offering not have EPA approval.

- * ABMS/Excel Environ. Inc., Oakland, CA (415) 547-7144. Contingent approval: Workers; Contractor/Supervisors
- * Center for Accelerated Learning, Vacaville, CA. (707) 446-7996. Contingent approval: Contractor/Supervisors; Workers.
- * Insulators and Asbestos Industry of Northern California, Alameda, CA. (415) 522-7048.
- * IT Corp., Wilmington, CA. (213) 830-1781. Contingent approval: Workers; Contractor/Supervisors
- * Kellico, Fremont, CA. (415) 659-9751. Contingent approval: Workers.
- * Med-Tox, Tusting CA. (714) 259-0620. Contingent approval; Inspector; Contractor/Supervisor; Workers.

RECORDKEEPING REQUIREMENT

All records shall be maintained in a centralized location in the administrative office of both the school and the local education agency as part of the management plan. For each homogeneous area where all ACBM has been removed, the local education agency shall ensure that such records are retained for 3 years after the next reinspection required under Sec. 763.85 or for an equivalent period.

For each preventive measure and response action taken for friable and nonfriable ACBM and friable and nonfriable suspected ACBM assumed to be ACM, the local education agency shall provide;

- (1) A detailed written description of the measure or action, including methods used, the location where the measure or action was taken, reasons for selecting the measure or action, start and completion dates of the work, names and addresses of all contractors involved, and if applicable, their State of accreditation, and accreditation numbers, and if ACBM is removed, the name and location of storage or disposal site of the ACM.
- (2) The name and signature of any person collecting any air sample required to be collected at the completion of certain response actions specified by Sec. 763.90, the locations where samples were collected, date of collection, the name and address of the laboratory analyzing the samples, the date of analysis, the results of the analysis, the method of analysis, the name and signature of the person performing the analysis, and a statement that the laboratory meets the applicable requirements of Sec. 763.90.

For each person required to be trained under Sec. 763.92 (a) 1 & 2, the local education agency shall provide the person's name and job title, the date that training was completed by that person, the location of the training, and the number of hours completed in such training.

For each time that periodic surveillance under Sec. 763.92 (b) is performed, the local education agency shall record the name of each person performing the surveillance, the date of the surveillance, and any changes in the conditions of the materials.

For each time that cleaning under Sec. 763.91 (c) is performed, the local education agency shall record the name of each person performing the cleaning, the date of such cleaning, the locations cleaned, and the methods used to perform such cleaning.

For each time that operations and maintenance activities under Sec. 763.91(d) are performed, the local education agency shall record the name of each person performing the activity, the start and completion dates of the activity, the locations where such activity occurred, a description of the activity including preventive measures used, and if ACBM is removed, the name and location of storage or disposal site of the ACM.

* Napier & Associates, Torrance, CA. (213) 644-1924. Contingent approval:
Workers.

* Pacific Asbestos Information Center, Berkeley Extension, CA. (415) 643-7143.
Full approval: Inspector/Management planner; Contractor/Supervisor.

EPA-ACCREDITED COURSES FROM OTHER REGIONS AVAILABLE IN CALIFORNIA
Telephone providers for schedules and information.

* Clayton Envir. Conslt.
(415) 426-2600
Inspector/Mgmt.Planner

* Kaselaan & D'Angelo Assoc.
(213) 324-6825
Inspector/Mgmt.Planner

* Critical Environmental
Training, Texas:
(800) 527-1830
Contractor/Supervisor; Workers

* Local 22, Texas
Internt. Assoc. Of Heat & Frost
(713) 473-0888
Contractor/Supervisor, Workers

* Environmental Instit., Texas
(214) 553-8866
Inspector/Mgmt. Planner
Contractor/Supervisor

* NAC (National Asb. Council)
(404) 292-0629
Workers

* Hall-Kimbrell, Kansas
(800) 364-2860
Contractor/Supervisor,
Workers, Project Designer

* North West Envirocon, Or.
(503) 659-8899
Inspector/Mgmt.Planner

* IPC, Illinois
(312) 975-3495
Workers

* White Lung, Maryland
(415) 668-2594
(707) 839-9270
Inspector/Mgmt.Planner

For each time that major asbestos activity under Sec. 763.91 (e) is performed, the local education agency shall provide the name and signature, State of accreditation, and if applicable, the accreditation number of each person performing the activity, the start and completion dates of the activity, the locations where such activity occurred, a description of the activity including preventive measures used, and if ACBM is removed, the name and location of storage or disposal site of the ACM.

For each fiber release episode under Sec. 763.91 (f), the local education agency shall provide the date and location of the episode, the method of repair, preventive measures or response action taken, the name of each person performing the work, and if ACBM is removed, the name and location of storage or disposal site of the ACM.

PERMIT APPLICATION FOR PERFORMING MAINTENANCE/RENOVATION WORK

1. Exact location of area involved (including building number, room number, location within room, etc.) _____

2. Description of work involved _____

3. Starting Date _____ Anticipated Completion Date _____
4. * Approximate amount of asbestos present (linear feet, square feet, size of tank, etc.) _____

5. * Asbestos control methods to be used (i.e., glove bag, HEPA vacuum, wet methods, etc.) _____

6. * Protective equipment to be used (respirator, coveralls, etc.) _____

7. Name and telephone number/extension of supervisor. _____

TO BE FILLED OUT BY ASBESTOS PROGRAM MANAGER

Permit _____ Accepted _____ Rejected _____
Signed _____ Print _____
Permit Number _____
Emergency Contact _____

Please return this form to:

Eslinger Enterprises
9545 W. Hwy. 152
Dos Palos, Ca. 93620

* Note: These items may have to be filled out by an asbestos program manager.

FIBER RELEASE EPISODE REPORT

1. Address, building, and room number(s) (or description of area) where episode occurred: _____

2. The release episode was reported by _____
on _____ (date)
3. Describe the episode: _____

4. The asbestos-containing material was _____ / was not _____
cleaned up according to approved procedures. Describe the cleanup:

Signed: _____
(Asbestos Program Manager)

Date: _____