

Six Month Surveillance Summary

District: Central California Conference of 7th Day Adventist

School: Chowchilla S.D.A School

Date: 8/10/16

Inspector: Debra Hawthorn

Building	HMR Number	Asbestos Material	Location	Condition Code/Comments
Church	1	Carpet, Purple	Foyer, Library, Nursery, Pastor's Office, Ready room, Sanctuary, Stage, Vestibule	1
Church	2	Drywall, heavy knockdown texture	Foyer, Library, Sanctuary, Vestibule	1
Church	3	FRP & glue	Library, Restroom	1
Church	4	Drywall, orange peel texture	Restroom	1
Church	5	Drywall, knockdown texture 2	Nursery	1
Church	6	Drywall, w/ SOC	Sanctuary, Stage	1
Church	7	Drywall, smooth (no JC)	Ready room	1
Church	8	Carpet 2, Brown	Earliten Youth, Junior Earliten, Kindergarten Classroom, Kindergarten Sabbath School	1
Church	9	Drywall, smooth 2	Earliten Youth, Junior Earliten, Kindergarten Classroom, Kindergarten Sabbath School	1
Church	11	Plaster, rough texture	Junior Earliten	1
Church	12	Fiberboard, wood	Kindergarten Sabbath School	1
Church	14	Buttonboard plaster	Pastor's Office, Ready room, Stage	1
Church	22	Baseboard, 6" wood	Foyer, Library, Nursery, Pastor's Office, Ready room, Restroom, Sanctuary, Vestibule	1
Classroom Building	15	Carpet 3, Blue/grey	Room 1 closet, Room 1 office, Room 2 closet, Room 2 office, Room 3 classroom, Room 6 workroom, Room 7 classroom	1 4, 7 *

Condition Codes

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (Damaged 25% or more)
 Change in Condition: (4) No (5) Yes (if yes, explain under comments)
 Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
 Misc: (11) Inaccessible, No surveillance data (12) Other (Explain under comments)

* all code 4 & 7 items were removed Summer 2016.

Date Printed: 10/9/2014

Six Month Surveillance Summary

District: Central California Conference of 7th
Day Adventist

School: Chowchilla S.D.A. School

Date: 8/10/16

Inspector: Debra Hawthorth

Building	HMR Number	Asbestos Material	Location	Condition Code/Comments
Classroom Building	16	Plaster, smooth	Room 1 closet, Room 11 office, Room 11 storage, Room 12 utility room, Room 13 multi-purpose, Room 2 closet, Room 2 office, Room 3 classroom, Room 4 utility room, Room 5 workroom, Room 6 workroom, Room 7 classroom, Room 9 custodial	1
Classroom Building	17	Baseboard, 4" green	Room 1 closet	1, 4, 7 *
Classroom Building	18	Acoustic ceiling tile 1x1, random hole	Room 13 multi-purpose, Room 3 classroom, Room 7 classroom	1, 4, 7 *
Classroom Building	19	Wood panel	Room 3 classroom, Room 7 classroom	1, 4, 7 *
Classroom Building	20	Vinyl flooring, seamless	Room 4 utility room	1
Classroom Building	21	Baseboard, 4" tan vinyl	Room 4 utility room	1
Classroom Building	23	Carpet 4, grey multi	Room 5 workroom	1, 4, 7 *
Classroom Building	24	Ceramic tile, 12" grey	Room 10 Women's Restroom, Room 8 Men's restroom	1
Classroom Building	25	Ceramic tile, 6"x9" grey	Room 10 Women's Restroom, Room 8 Men's restroom	1
Classroom Building	26	Drywall, smooth 3	Room 10 Women's Restroom, Room 8 Men's restroom	1
Classroom Building	27	Vinyl flooring, seamless, grey mosaic	Room 11 storage, Room 12 utility room, Room 13 multi-purpose	1, 4, 7 *
Classroom Building	28	Baseboard, 4" dark grey vinyl	Room 11 storage, Room 12 utility room, Room 13 multi-purpose	1, 4, 7 *
Classroom Building	29	Floor tile 9" & mastic	Room 11 storage, Room 12 utility room	1, 4, 7 *
Classroom Building	30	Carpet 5, grey multi 2	Room 13 multi-purpose	1, 4, 7 *
Classroom Building	31	Wood panel 2	Room 13 multi-purpose	1, 4, 7 *

Condition Codes

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (Damaged 25% or more)

Change in Condition: (4) No (5) Yes (if yes, explain under comments)

Abated:

Misc:

(6) Repeated (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted (11) Inaccessible, No surveillance data (12) Other (Explain under comments)

Date Printed: 10/9/2014

Six Month Surveillance Summary

District: Central California Conference of 7th
Day Adventist

School: Chowchilla S.D.A School

Date: 8/12/16

Inspector: Debra Hewitt

Building	HMR Number	Asbestos Material	Location	Condition Code/Comments
Multi-use Building	32	Vinyl flooring, seamless, grey sand	Kitchen	2
Multi-use Building	33	Baseboard, 6" vinyl light brown	Kitchen	1
Multi-use Building	34	Drywall, smooth 4	Kitchen, Room 5 Foyer	2
Multi-use Building	35	Vinyl flooring, seamless, 4" square	Room 2 storage, Room 3 storage, Room 4 storage	1
Multi-use Building	36	Drywall, knockdown texture 3	Room 4 storage, Room 5 Foyer	1
Multi-use Building	37	Drywall, knockdown texture 4	Classroom, Storage Loft	1
Multi-use Building	38	Carpet 6, grey	Classroom, South closet	1
Multi-use Building	39	Drywall, heavy orange peel	Stage	1
Multi-use Building	40	Plaster, rough texture 2	Backstage Hall	1
Multi-use Building	41	Drywall, smooth 5	Backstage Hall	1

Condition Codes

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (Damaged 25% or more)
Change in Condition: (4) No (5) Yes (If yes, explain under comments)
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Misc: (11) Inaccessible, No surveillance data (12) Other (Explain under comments)

Date Printed: 10/9/2014