

Six Month Surveillance Summary

District: Central California Conference of 7th
Day Adventist

School: VHM Christian Santa Cruz

Date: 9/19/16

Inspector: Adalberto Casillas

| Building | HMR Number | Asbestos Material | Location | Condition Code/Comments |
|--------------------------|------------|--|---|-------------------------|
| 01 - Pre-School Building | 1 | Carpet and Mastic - Brown Multi | 01 - Pre-School Room 1 | O.K |
| 01 - Pre-School Building | 2 | 4" Baseboard and Mastic - Black | 01 - Pre-School Room 1, 03 - Pre-School Room 2, 05 - Pre-School Room 3 | O.K |
| 01 - Pre-School Building | 3 | Tack Board - Beige | 01 - Pre-School Room 1, 03 - Pre-School Room 2, 05 - Pre-School Room 3 | O.K |
| 01 - Pre-School Building | 4 | 12" ACT and Mastic - Pinhole | 01 - Pre-School Room 1, 02 - Pre-School Room 1 Restroom, 03 - Pre-School Room 2, 04 - Pre-School Room 2 Restroom, 05 - Pre-School Room 3, 06 - Pre-School Room 3 Restroom, 08 - Faculty Work Room Foyer, 09 - Faculty Work Room | O.K |
| 01 - Pre-School Building | 5 | CMU and Grout | 01 - Pre-School Room 1, 03 - Pre-School Room 2, 05 - Pre-School Room 3, 07 - Custodial Closet, 08 - Faculty Work Room Foyer, 09 - Faculty Work Room, 10 - IT Closet, 11 - Faculty Restroom 1, 12 - Faculty Restroom 2 | O.K |
| 01 - Pre-School Building | 6 | Masonite - Tan | 01 - Pre-School Room 1, 02 - Pre-School Room 1 Restroom, 03 - Pre-School Room 2, 04 - Pre-School Room 2 Restroom, 05 - Pre-School Room 3, 06 - Pre-School Room 3 Restroom | O.K |
| 01 - Pre-School Building | 7 | Epoxy - Grey | 02 - Pre-School Room 1 Restroom, 04 - Pre-School Room 2 Restroom, 06 - Pre-School Room 3 Restroom, 07 - Custodial Closet | O.K |
| 01 - Pre-School Building | 8 | Drywall - Smooth Texture | 02 - Pre-School Room 1 Restroom, 04 - Pre-School Room 2 Restroom, 06 - Pre-School Room 3 Restroom | O.K |
| 01 - Pre-School Building | 9 | Vinyl Sheet Floor & Mastic - Wood Look | 03 - Pre-School Room 2, 05 - Pre-School Room 3 | O.K |
| 01 - Pre-School Building | 10 | FRP - White | 07 - Custodial Closet | |

Condition Codes

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (Damaged 25% or more)
Change in Condition: (4) No (5) Yes (if yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Misc: (11) Inaccessible, No surveillance data (12) Other (Explain under comments)

Six Month Surveillance Summary

District: Central California Conference of 7th
Day Adventist

Date: 9/19/14

School: VHM Christian Santa Cruz

Inspector: Adalberto Casillas

| Building | HMR Number | Asbestos Material | Location | Condition Code/Comments |
|--------------------------|------------|---------------------------------------|---|-------------------------|
| 01 - Pre-School Building | 11 | Drywall - Troweled Texture | 07 - Custodial Closet, 08 - Faculty Work Room Foyer, 10 - IT Closet, 11 - Faculty Restroom 1, 12 - Faculty Restroom 2 | O.K |
| 01 - Pre-School Building | 12 | Carpet and Mastic - Blue Multi | 08 - Faculty Work Room Foyer, 09 - Faculty Work Room, 10 - IT Closet | O.K |
| 01 - Pre-School Building | 13 | 4" Baseboard and Mastic - Grey | 08 - Faculty Work Room Foyer, 09 - Faculty Work Room, 11 - Faculty Restroom 1, 12 - Faculty Restroom 2 | O.K |
| 01 - Pre-School Building | 14 | Linoleum & Mastic - Grey Specks | 11 - Faculty Restroom 1, 12 - Faculty Restroom 2 | O.K |
| 02 - Admin Building | 4 | 12" ACT and Mastic - Pinhole | 01 - Reception Area, 02 - Office 1, 03 - Meeting Room | O.K |
| 02 - Admin Building | 5 | CMU and Grout | 01 - Reception Area, 02 - Office 1, 03 - Meeting Room, 04 - Furnace Room, 07 - Electrical Room | O.K |
| 02 - Admin Building | 8 | Drywall - Smooth Texture | 05 - Girls RR, 06 - Boys RR | O.K |
| 02 - Admin Building | 12 | Carpet and Mastic - Blue Multi | 01 - Reception Area, 02 - Office 1, 03 - Meeting Room | O.K |
| 02 - Admin Building | 13 | 4" Baseboard and Mastic - Grey | 01 - Reception Area, 02 - Office 1, 03 - Meeting Room | O.K |
| 02 - Admin Building | 16 | Drywall - Orange Peel Texture | 01 - Reception Area, 02 - Office 1, 03 - Meeting Room | O.K |
| 02 - Admin Building | 17 | Drywall - Tape and Joint Compound | 04 - Furnace Room, 07 - Electrical Room | O.K |
| 02 - Admin Building | 36 | 8" Ceramic Tile and Grout - Grey | 05 - Girls RR, 06 - Boys RR | O.K |
| 02 - Admin Building | 37 | 4" x 6" Ceramic Tile and Grout - Grey | 05 - Girls RR, 06 - Boys RR | O.K |

Condition Codes

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (Damaged 25% or more)
Change in Condition: (4) No (5) Yes (If yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Misc: (11) Inaccessible, No surveillance data (12) Other (Explain under comments)

Six Month Surveillance Summary

District: Central California Conference of 7th
Day Adventist

Date: 9/19/14

School: VHM Christian Santa Cruz

Inspector: Adalberto Casille

| Building | HMR Number | Asbestos Material | Location | Condition Code/Comments |
|-------------------------|------------|--|---|-------------------------|
| 02 - Admin Building | 38 | 5" Ceramic Tile and Grout - Grey Multi | 05 - Girls RR, 06 - Boys RR | O.K |
| 03 - Classroom Building | 2 | 4" Baseboard and Mastic - Black | 04 - Classroom 1 | O.K |
| 03 - Classroom Building | 4 | 12" ACT and Mastic - Pinhole | 01 - Entry Hallway, 02 - Finance Office, 03 - Teacher Resource Center, 04 - Classroom 1, 05 - Classroom 2, 06 - Classroom 3 | O.K |
| 03 - Classroom Building | 5 | CMU and Grout | 01 - Entry Hallway, 02 - Finance Office, 03 - Teacher Resource Center, 04 - Classroom 1, 05 - Classroom 2, 06 - Classroom 3 | O.K |
| 03 - Classroom Building | 12 | Carpet and Mastic - Blue Multi | 01 - Entry Hallway, 02 - Finance Office, 03 - Teacher Resource Center | O.K |
| 03 - Classroom Building | 13 | 4" Baseboard and Mastic - Grey | 01 - Entry Hallway, 02 - Finance Office, 03 - Teacher Resource Center | O.K |
| 03 - Classroom Building | 18 | Carpet and Mastic - Green Multi | 04 - Classroom 1 | O.K |
| 03 - Classroom Building | 19 | Carpet and Mastic - Red | 05 - Classroom 2 | O.K |
| 03 - Classroom Building | 20 | 4" Baseboard and Mastic - Brown | 05 - Classroom 2 | O.K |
| 03 - Classroom Building | 21 | Carpet and Mastic - Red/Green Multi | 06 - Classroom 3 | O.K |
| 04 - Gymnasium Building | 1 | Carpet and Mastic - Brown Multi | 08 - Stage Storage Room Right | O.K |
| 04 - Gymnasium Building | 5 | CMU and Grout | 01 - Kitchen, 02 - Kitchen Pantry, 03 - Kitchen Water Heater Closet, 04 - Library, 05 - Gym Entry Lobby | O.K |

Condition Codes

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (Damaged 25% or more)
Change in Condition: (4) No (5) Yes (If yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Misc: (11) Inaccessible, No surveillance data (12) Other (Explain under comments)

District: Central California Conference of 7th
Day Adventist

School: VHM Christian Santa Cruz

Six Month Surveillance Summary

Date: 9/19/14

Inspector: Adalberto Casillas

| Building | HMR Number | Asbestos Material | Location | Condition Code/Comments |
|-------------------------|------------|---|--|-------------------------|
| 04 - Gymnasium Building | 8 | Drywall - Smooth Texture | 10 - Staircase to Upper Stage Storage Right, 14 - Staircase to Upper Stage Storage Left, 15 - Upper Stage Storage Left, 21 - Girls Restroom, 22 - Boys Restroom, 28 - Instrument Storage, 29 - File Storage, 31 - Storage Room | OK |
| 04 - Gymnasium Building | 12 | Carpet and Mastic - Blue Multi | 09 - Upper Stage Storage Right, 10 - Staircase to Upper Stage Storage Right, 17 - Stage Storage Room Left, 18 - Stage Storage Room Left Closet | OK |
| 04 - Gymnasium Building | 16 | Drywall - Orange Peel Texture | 19 - PE Storage 1 | OK |
| 04 - Gymnasium Building | 17 | Drywall - Tape and Joint Compound | 03 - Kitchen Water Heater Closet, 12 - Below Stairs Storage Right, 13 - Below Stairs Storage Left, 20 - PE Storage 2, 23 - Custodial Storage Room, 25 - Custodial Storage | OK |
| 04 - Gymnasium Building | 19 | Carpet and Mastic - Red | 27 - Music Room, 30 - Office | OK |
| 04 - Gymnasium Building | 20 | 4" Baseboard and Mastic - Brown | 05 - Gym Entry Lobby, 27 - Music Room, 29 - File Storage, 30 - Office | OK |
| 04 - Gymnasium Building | 22 | 12" VFT and Mastic - Beige | 01 - Kitchen, 02 - Kitchen Pantry, 16 - Stage Foyer Left | OK |
| 04 - Gymnasium Building | 23 | Drywall - Knockdown Texture | 01 - Kitchen, 04 - Library, 05 - Gym Entry Lobby, 07 - Stage Foyer Right, 08 - Stage Storage Room Right, 09 - Upper Stage Storage Right, 16 - Stage Foyer Left, 17 - Stage Storage Room Left, 18 - Stage Storage Room Left Closet, 24 - Custodial Foyer Area, 26 - Staircase to Upper Floor East, 27 - Music Room, 30 - Office, 32 - Staircase to Upper Floor West | OK |
| 04 - Gymnasium Building | 24 | Drywall - Unfinished | 02 - Kitchen Pantry, 03 - Kitchen Water Heater Closet | OK |
| 04 - Gymnasium Building | 25 | Linoleum & Mastic- 12" Green Tile Patt. | 04 - Library | OK |

Condition Codes

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (Damaged 25% or more)
Change in Condition: (4) No (5) Yes (if yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restrictd

Misc: (11) Inaccessible, No surveillance data (12) Other (Explain under comments)

Six Month Surveillance Summary

District: Central California Conference of 7th
Day Adventist

School: VHM Christian Santa Cruz

Date: 9/19/16

Inspector: Adalberto Casillas

| Building | HMR Number | Asbestos Material | Location | Condition Code/Comments |
|-------------------------|------------|---------------------------------------|---|-------------------------|
| 04 - Gymnasium Building | 26 | Carpet and Mastic - Green/Pink | 05 - Gym Entry Lobby | OK |
| 04 - Gymnasium Building | 27 | Carpet and Mastic - Blue | 04 - Library | OK |
| 04 - Gymnasium Building | 28 | 9" VFT and Mastic - Beige | 07 - Stage Foyer Right | OK |
| 04 - Gymnasium Building | 29 | Metal "L"-Shaped Baseboard | 06 - Gymnasium | OK |
| 04 - Gymnasium Building | 30 | Concrete w/Knockdown Texture | 08 - Stage Storage Room Right, 09 - Upper Stage Storage Right, 17 - Stage Storage Room Left, 18 - Stage Storage Room Left Closet, 24 - Custodial Foyer Area, 26 - Staircase to Upper Floor East, 27 - Music Room, 30 - Office, 32 - Staircase to Upper Floor West | OK |
| 04 - Gymnasium Building | 31 | 12" ACT and Mastic - Lined | 08 - Stage Storage Room Right, 17 - Stage Storage Room Left | OK |
| 04 - Gymnasium Building | 32 | Carpet and Mastic - Blue/Grey | 15 - Upper Stage Storage Left | OK |
| 04 - Gymnasium Building | 33 | 2" Baseboard and Mastic - Grey | 15 - Upper Stage Storage Left | OK |
| 04 - Gymnasium Building | 34 | 4" Baseboard and Mastic - Beige | 16 - Stage Foyer Left, 17 - Stage Storage Room Left, 18 - Stage Storage Room Left Closet | OK |
| 04 - Gymnasium Building | 35 | Carpet and Mastic - Brown/Orange | 19 - PE Storage 1 | OK |
| 04 - Gymnasium Building | 36 | 8" Ceramic Tile and Grout - Grey | 21 - Girls Restroom, 22 - Boys Restroom | OK |
| 04 - Gymnasium Building | 37 | 4" x 6" Ceramic Tile and Grout - Grey | 21 - Girls Restroom, 22 - Boys Restroom | OK |

Condition Codes

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (Damaged 25% or more)

Change in Condition: (4) No (5) Yes (if yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Misc: (11) Inaccessible, No surveillance data (12) Other (Explain under comments)

Six Month Surveillance Summary

District: Central California Conference of 7th
Day Adventist

School: VHM Christian Santa Cruz

Date: 9/19/16

Inspector: Adalberto Casillas

| Building | HMR Number | Asbestos Material | Location | Condition Code/Comments |
|----------------------------|------------|---|---|-------------------------|
| 04 - Gymnasium Building | 38 | 5" Ceramic Tile and Grout - Grey Multi | 21 - Girls Restroom, 22 - Boys Restroom | OK |
| 04 - Gymnasium Building | 39 | Concrete w/Orange Peel Skimcoat | 19 - PE Storage 1 | OK |
| 04 - Gymnasium Building | 40 | Concrete w/Smooth Skimcoat | 21 - Girls Restroom, 22 - Boys Restroom, 28 - Instrument Storage, 31 - Storage Room | OK |
| 04 - Gymnasium Building | 41 | Vinyl Floor Treads | 26 - Staircase to Upper Floor East, 32 - Staircase to Upper Floor West | OK |
| 04 - Gymnasium Building | 42 | 9" VFT and Mastic - Mauve | 27 - Music Room, 30 - Office | OK |
| 04 - Gymnasium Building | 43 | 9" VFT and Mastic - Tan w/White Streaks | 26 - Staircase to Upper Floor East, 28 - Instrument Storage, 29 - File Storage, 31 - Storage Room, 32 - Staircase to Upper Floor West | OK |
| 05 - Computer Lab Building | 1 | Carpet and Mastic - Brown Multi | 01 - Computer Lab, 02 - Classroom | OK |
| 05 - Computer Lab Building | 2 | 4" Baseboard and Mastic - Black | 01 - Computer Lab, 02 - Classroom | OK |
| 05 - Computer Lab Building | 4 | 12" ACT and Mastic - Pinhole | 01 - Computer Lab, 02 - Classroom | OK |
| 05 - Computer Lab Building | 5 | CMU and Grout | 01 - Computer Lab, 02 - Classroom | OK |
| 05 - Computer Lab Building | 23 | Drywall - Knockdown Texture | 01 - Computer Lab | OK |

Condition Codes

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (Damaged 25% or more)
Change in Condition: (4) No (5) Yes (if yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Misc: (11) Inaccessible, No surveillance data (12) Other (Explain under comments)