

Six Month Surveillance Summary

District: Central California Conference of 7th
Day Adventist

School: Los Banos SDA

Date: 8/29/16

Inspector: Donna Melashenko

Building	HMR Number	Asbestos Material	Location	Condition Code/Comments
Church	1	Carpet Brown	1st / 4th Grade Classroom, 1st / 4th Grade Hall, 5th / 8th Grade Classroom, 5th / 8th Grade Hall, Chapel, Office, Principals Office, Printer Lab, Reception	1
Church	2	Baseboard 4" Brown	1st / 4th Grade Classroom, 1st / 4th Grade Hall, 5th / 8th Grade Classroom, 5th / 8th Grade Hall, Office, Principals Office, Printer Lab, Reception	1
Church	3	Drywall smooth texture	1st / 4th Grade Classroom, 1st / 4th Grade Hall, 1st / 4th Grade Mens Restroom, 1st / 4th Grade Womens Restroom, 5th / 8th Grade Classroom, 5th / 8th Grade Hall, 5th / 8th Grade Mens Restroom, 5th / 8th Grade Womens Restroom, Office, Principals Office, Printer Lab, Reception, Storage Room	1
Church	5	Baseboard 4" Blue	1st / 4th Grade Mens Restroom, 1st / 4th Grade Womens Restroom, 5th / 8th Grade Mens Restroom, 5th / 8th Grade Womens Restroom, Storage Room	1
Church	6	Ceramic Tile 6" Blue and Grout	1st / 4th Grade Mens Restroom, 1st / 4th Grade Womens Restroom, 5th / 8th Grade Mens Restroom, 5th / 8th Grade Womens Restroom	1
Church	7	Carpet Purple	Storage Room	7
Church	8	Fiber Reinforced Panel	1st / 4th Grade Mens Restroom, 1st / 4th Grade Womens Restroom, 5th / 8th Grade Mens Restroom, 5th / 8th Grade Womens Restroom	1
Church	9	Carpet Red / Brown	Art Supplies, Entry Hall and Vestibule, Tables and Chairs	7

Condition Codes

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (Damaged 25% or more)

Change in Condition: (4) No (5) Yes (If yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Misc: (11) Inaccessible, No surveillance data (12) Other (Explain under comments)

Date Printed: 4/30/2014

Six Month Surveillance Summary

District: Central California Conference of 7th Day Adventist

School: Los Banos SDA

Date: 8/29/16

Inspector: Donna Mekshenko

Building	HMR Number	Asbestos Material	Location	Condition Code/Comments
Church	11	Block and Grout	Art Supplies, Attic, Chapel, Cradel Roll, Entry Hall and Vestibule, Hallway behind the Sanctuary, Janitor Closet, Kitchen, Mothers Room, Music Room #1, Music Room #2, Pastor Restroom, Pastor Study, Sanctuary, Tables and Chairs, Utility, Water Heater Closet, Womens Restroom	1
Church	13	Ceramic tile 18" and grout	Boys Restroom, Girls Restroom	1
Church	14	Block and mortar with heavy texture	Boys Restroom, Girls Restroom	1
Church	15	Plaster	Boys Restroom, Girls Restroom, Kitchen, Womens Restroom	1
Church	16	Carpet Red	Cradel Roll, Hallway behind the Sanctuary, Mothers Room, Pastor Restroom, Pastor Study, Sanctuary, Utility, Womens Restroom	7
Church	17	Ceramic Tile 12" Tan and Grout	Kitchen	1
Church	19	Drywall with knock down texture	Cradel Roll, Hallway behind the Sanctuary, Janitor Closet, Mothers Room, Music Room #1, Music Room #2, Pastor Restroom, Pastor Study, Utility	1
Church	20	Baseboard 4" Off White	Music Room #1	1
Church	21	Drywall Unfinished	Water Heater Closet	1
Church	22	Carpet Brown / Multi color	Music Room #2	1
Storage	11	Block and Grout	Storage	1

Condition Codes

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (Damaged 25% or more)
 Change in Condition: (4) No (5) Yes (If yes, explain under comments)
 Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
 Misc: (11) Inaccessible, No surveillance data (12) Other (Explain under comments)

Date Printed: 4/30/2014