

Six Month Surveillance Summary

District: Central California Conference of 7th
Day Adventist

School: Kern SDA Elementary

Date:

5-8-16

Inspector:

R. Pitts

Building	HMR Number	Asbestos Material	Location	Condition Code/Comments
Classroom	1	Carpet dark mult colored	Chapel, Grade 1-4, Grade 5-8, Library, Office	1
Classroom	2	Baseboard 4" brown	Chapel, Grade 1-4, Grade 5-8, Hallways, Janitorial, Library, Music, Office, Reception	1
Classroom	3	Block and mortar	Chapel, Grade 1-4, Grade 5-8, Hallways, Heater closet 1, Heater closet 2, Heater closet 3, Janitorial, Library, Music, Office, Reception, Storage	1, 2 AB
Classroom	4	Drywall with knock-down texture	Chapel	1
Classroom	5	Drywall smooth texture	Chapel, Grade 5-8, Heater closet 1, Heater closet 2, Heater closet 3	1
Classroom	6	Plaster acoustical texture	Grade 1-4, Grade 5-8, Hallways, Heater closet 1, Heater closet 2, Heater closet 3, Library, Music, Office, Reception	2 ABC
Classroom	7	Floor tile 12" Tan	Hallways, Janitorial, Music, Reception	2 AB
Classroom	8	Drywall with knock-down texture #2	Grade 1-4, Music	1
Classroom	9	Ceramic tile and grout	Boys restroom, Girls restroom	1
Classroom	10	Ceramic tile and grout #2	Boys restroom	1
Classroom	11	Plaster smooth	Boys restroom, Girls restroom, Janitorial, Storage	2 AB
Classroom	12	Transite	Attic	1
Classroom	13	Insulation blown-in	Attic	1
Gymnasium	14	Drywall painted	Gym, Stage	1
Gymnasium	15	Drywall unfinished	Furnace east, Furnace west, Gym	2

Condition Codes

- General Condition: (1) Good (2) Damaged (3) Significantly Damaged (Damaged 25 or more)
Change in Condition: (4) No (5) Yes (If yes, explain under comments)
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Misc: (11) Inaccessible, No surveillance data (12) Other (Explain under comments)

Six Month Surveillance Summary

District: Central California Conference of 7th
Day Adventist

School: Kern SDA Elementary

Date:

5-8-16

Inspector:

R.P.H.S

Building	HMR Number	Material	Location	Condition Code/Comments
Gymnasium	17	Linoleum brown pebble pattern	Kitchen/Dining, Storage/Pantry	I
Gymnasium	18	Baseboard 4" brown #2	Kitchen/Dining, Storage/Pantry	I
Gymnasium	19	Drywall with smooth/knock-down texture	Kitchen/Dining	I
Gymnasium	20	Drywall smooth texture #2	Storage/Pantry	I
Gymnasium	21	Floor tile 9" green	Pathfinders/Storage	II
Gymnasium	22	Fiber board	Pathfinders/Storage	II
Gymnasium	23	Insulation corrugated paper	Furnace east, Furnace west	II

Condition Codes

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (Damaged 25 or more)
Change in Condition: (4) No (5) Yes (If yes, explain under comments)
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Misc: (11) Inaccessible, No surveillance data (12) Other (Explain under comments)

Six Month Surveillance Summary

Comments

HMR #:	Comment:
3A	Lunchroom blockwall cracks
3B	Library blockwall cracks
4	Chapel drywall minor damage on stage
6A	Chapel acoustical ceiling water damage
6B	Lunchroom acoustical ceiling water damage
6C	Library acoustical ceiling has been repaired
7A	Hallway floor tile areas of bubbling and separation
7B	Lunchroom tile areas of bubbling and separation
11A	Girls restroom plaster cracks
11B	Boys restroom plaster cracks, wall damage
15	Gym drywall holes cut and cracks