

Six Month Surveillance Summary

District: Central California Conference of 7th
Day Adventist

School: Oakhurst S.D.A School

Date: 8/12/16

Inspector: Sonya Reaves

Building	HMR Number	Asbestos Material	Location	Condition Code/Comments
Classroom Building	1	Carpet, green	Room 1 Classroom	2
Classroom Building	2	FRP & glue	Room 1 Classroom, Room 4 Classroom	1
Classroom Building	4	Drywall, sponge texture	Room 11 Furnace room, Room 2 Office, Room 3 Workroom, Room 9 Janitorial	1
Classroom Building	5	Carpet 2, grey	Room 3 Workroom	1
Classroom Building	6	Carpet 3, maroon	Room 4 Classroom	1
Classroom Building	7	Wood panel & glue	Room 4 Classroom	1
Classroom Building	8	Vinyl floor covering	Room 5 Library, Room 9 Janitorial	1
Classroom Building	9	Drywall 2, knockdown texture	Room 5 Library	1
Classroom Building	10	Tackboard & glue	Room 5 Library	1
Classroom Building	11	Drywall 3, smooth	Room 10 Women's Restroom, Room 6 Restroom, Southwest, Room 7 Restroom, Southeast, Room 8 Men's Restroom	1
Classroom Building	12	Baseboard, 4" brown vinyl	Room 9 Janitorial	1

Condition Codes

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (Damaged 25% or more)

Change in Condition: (4) No (5) Yes (If yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Misc: (11) Inaccessible, No surveillance data (12) Other (Explain under comments)