

# Six Month Surveillance Summary

District: Central California Conference of 7th  
Day Adventist

Date: 9/7/2016

School: Peninsula Adventist School

Inspector: Yvonne Ford

Building	HMR Number	Asbestos Material	Location	Condition Code/Comments
01 - Classroom Building 1	2	Drywall - Smooth Texture	02 - Resource Room, 03 - Work Room, 04 - Girls Restroom Foyer, 08 - Exterior Furnace Closet	4
01 - Classroom Building 1	14	Carpet and Mastic - Grey	01 - Classroom	4
01 - Classroom Building 1	20	18" Ceramic Tile and Grout - White	07 - Boys Restroom	4
01 - Classroom Building 1	23	9" VFT and Mastic - Tan	01 - Classroom, 04 - Girls Restroom Foyer, 05 - Girls Restroom, 06 - Boys Restroom Foyer, 07 - Boys Restroom, 08 - Exterior Furnace Closet	4
01 - Classroom Building 1	24	Carpet and Mastic - Light Green	02 - Resource Room	4
01 - Classroom Building 1	25	2" Baseboard and Mastic - Tan	02 - Resource Room	4
01 - Classroom Building 1	26	Plaster - Stucco Finish	02 - Resource Room, 03 - Work Room	4
01 - Classroom Building 1	27	Carpet and Mastic - Aqua	04 - Girls Restroom Foyer, 06 - Boys Restroom Foyer	4
01 - Classroom Building 1	28	Transite Flue Pipe	04 - Girls Restroom Foyer	4
01 - Classroom Building 1	29	Linoleum and Mastic - Wood Squares	05 - Girls Restroom	4
01 - Classroom Building 1	30	Plaster - Smooth Finish	05 - Girls Restroom, 07 - Boys Restroom	4
01 - Classroom Building 1	31	Drywall - Knockdown Texture	08 - Exterior Furnace Closet	4
01 - Classroom Building 1	32	Drywall - Bare	09 - Exterior Water Heater Closet	4
02 - Classroom Building 2	2	Drywall - Smooth Texture	01 - Classroom, 03 - Kitchen, 04 - Custodial Closet	4

## Condition Codes

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (Damaged 25% or more)  
Change in Condition: (4) No (5) Yes (If yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Misc: (11) Inaccessible, No surveillance data (12) Other (Explain under comments)

## Six Month Surveillance Summary

**District:** Central California Conference of 7th  
Day Adventist

**Date:**

**School:** Peninsula Adventist School

**Inspector:**

Building	HMR Number	Asbestos Material	Location	Condition Code/Comments
03 - Office Building	8	Carpet and Mastic - Orange	05 - Meeting Room, 06 - Meeting Room 2	4
03 - Office Building	13	Moisture Barrier Paper	08 - Basement	4
03 - Office Building	28	Transite Flue Pipe	07 - Attic	4
04 - Chapel Building	9	12" Ceramic Tile and Grout-White Marble	01 - Chapel Foyer, 02 - Womens Restroom, 03 - Mens Restroom, 04 - Storage Room	4
04 - Chapel Building	10	Drywall - Medium Texture	01 - Chapel Foyer, 02 - Womens Restroom, 03 - Mens Restroom, 04 - Storage Room, 05 - Chapel AV Room, 06 - Chapel Storage Closet, 07 - Chapel	4
04 - Chapel Building	11	Carpet and Mastic - Red	05 - Chapel AV Room, 06 - Chapel Storage Closet, 07 - Chapel	4
04 - Chapel Building	12	Exterior Stucco	08 - Exterior Water Heater Closet	4

### Condition Codes

General Condition:  
Change in Condition:

(1) Good (2) Damaged (3) Significantly Damaged (Damaged 25% or more)  
(4) No (5) Yes (if yes, explain under comments)

Abated:

(6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Misc:

(11) Inaccessible, No surveillance data (12) Other (Explain under comments)