

Six Month Surveillance Summary

District: Central California Conference of 7th
Day Adventist

School: Armona Union

Date: 10-6-2016
Inspector: Luis Gerez

Building	HMR Number	Asbestos Material	Location	Condition Code/Comments
Building 1 - Administration	1	Carpet blue #1	Back stage prep, Boys Restroom vestibule, room 19, Chapel, room 20, Closet, Room 18, Corridor, Entrance, Girls Restroom vestibule, room 21, Library, room 14 / 15, Library, room 14 / 15 B, Storage, Music, Room 18	1
Building 1 - Administration	2	Plaster sanded #1	Back stage East, room 20, Back stage prep, Back stage West, room 20, Boys Restroom vestibule, room 19, Boys restroom, room 19, Closet, room 17, Closet, Room 18, Corridor, English, room 17, Entrance, Girls Restroom vestibule, room 21, Girls restroom, room 21, Library, room 14 / 15 A, furnace room, Library, room 14 / 15, Library, room 14 / 15 B, Storage, Music, Room 18, Office north, room 16, Storage south, room 16	1 4
Building 1 - Administration	3	Sprayed on Acoustic #1	English, room 17, Library, room 14 / 15, Music, Room 18	1
Building 1 - Administration	4	Plaster skimcoat on concrete	Boys Restroom vestibule, room 19, Boys restroom, room 19, Closet, room 17, Closet, Room 18, Corridor, English, room 17, Entrance, Girls Restroom vestibule, room 21, Girls restroom, room 21, Heater room, room 17, Library, room 14 / 15, Music, Room 18, Office north, room 16, Storage south, room 16	1
Building 1 - Administration	5	Carpet blue #2	Back stage East, room 20, Back stage prep, Back stage West, room 20, English, room 17, Office north, room 16, Storage south, room 16	1
Building 1 - Administration	6	Tectum panel 16"x48" with glue	Closet, Room 18, Storage south, room 16	1
Building 1 - Administration	7	Texture coat, Skip trowel	Boys Restroom vestibule, room 19, Boys restroom, room 19, Corridor, Entrance, Girls Restroom vestibule, room 21, Girls restroom, room 21, Office north, room 16	1
Building 1 - Administration	8	Baseboard 4" cream	English, room 17	1

Condition Codes

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (Damaged 25% or more)
Change in Condition: (4) No (5) Yes (If yes, explain under comments)
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Misc: (11) Inaccessible, No surveillance data (12) Other (Explain under comments)

Six Month Surveillance Summary

District: Central California Conference of 7th
Day Adventist
School: Armona Union

Date: 10.6.2016
Inspector: Luis Gutierrez

Building	HMR Number	Asbestos Material	Location	Condition Code/Comments
Building 1 - Administration	9	Texture splatter	English, room 17	1
Building 1 - Administration	10	Floor tile 9" concealed	English, room 17	1
Building 1 - Administration	11	Floor tile 9" brown with white	Closet, room 17	1
Building 1 - Administration	12	Drywall smooth #1	Closet, room 17, Closet, Room 18	1
Building 1 - Administration	15	Ceramic tile 2" with grout	Boys restroom, room 19	1
Building 1 - Administration	17	Texture, heavy trowel	Back stage East, room 20, Back stage West, room 20, Chapel, room 20	1
Building 1 - Administration	18	Stucco #1	Covered Walkway, South corridor / locker	1
Building 1 - Administration	19	Ceramic tile 8" with grout	Girls restroom, room 21	1
Building 1 - Administration	20	Stucco #2	South corridor / locker	1
Building 1 - Administration	21	Drywall splatter texture #1	Conference, room 24, Principal, room 23, South corridor / locker	1
Building 1 - Administration	22	Fire door	South corridor / locker	1
Building 1 - Administration	23	Carpet blue / grey	Conference, room 24, Nurse, room 22, Open office, room 22, Principal, room 23, Work room, room 22	1
Building 1 - Administration	24	Drywall trowell texture	Nurse, room 22, Open office, room 22	1
Building 1 - Administration	25	Ceramic tile 1"-2" with grout	Nurse restroom, room 22	1
Building 1 - Administration	26	Plaster sanded #2	Nurse restroom, room 22, Work room, room 22	1
Building 1 - Administration	27	Ceramic tile 4"x6" with grout	Nurse restroom, room 22	1

Condition Codes

General Condition:

Change in Condition:

Abated:

Misc:

(1) Good (2) Damaged (3) Significantly Damaged (Damaged 25% or more)

(4) No (5) Yes (if yes, explain under comments)

(6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

(11) Inaccessible, No surveillance data (12) Other (Explain under comments)

Six Month Surveillance Summary

District: Central California Conference of 7th
Day Adventist
School: Armona Union

Date: 10-6-2016
Inspector: Luis Gutierrez

Building	HMR Number	Asbestos Material	Location	Condition Code/Comments
Building 1 - Administration	28	Drywall unfinished w/ joint compound #1	Vault	1
Building 1 - Administration	29	Mudded duct tape (off white)	Attic	1
Building 1 - Administration	30	Blown-In Insulation	Attic	1
Building 1 - Administration	900	Transite pipe	Back stage East, room 20, Back stage prep, Back stage West, room 20, Heater room, room 17	1
Building 2 - Science / Home Ec	31	Carpet blue #3	Government / Econ, Office at Government / Econ, Office at Religion, Office at Spanish, Religion, Science Classroom, Science Office, Spanish	1
Building 2 - Science / Home Ec	32	Baseboard 4" grey	Chemical Storage, Government / Econ, Home Ec, Home Ec Laundry, Home Ec Storage, Office at Government / Econ, Office at Religion, Office at Spanish, Religion, Science Classroom, Science Lab, Science Office, Science stockroom, Spanish	1
Building 2 - Science / Home Ec	33	Drywall splatter texture #2	Chemical Storage, Government / Econ, Home Ec, Home Ec Laundry, Home Ec Storage, Mens Restroom, Office at Government / Econ, Office at Religion, Office at Spanish, Religion, Science Classroom, Science Lab, Science Office, Science stockroom, Spanish, Water Heater room, Womens Restroom	1
Building 2 - Science / Home Ec	35	Tackboard	Government / Econ, Home Ec, Science Classroom, Science Lab, Spanish	1
Building 2 - Science / Home Ec	36	Floor tile 12" Blue / Grey	Chemical Storage, Home Ec, Home Ec Laundry, Home Ec Storage, Science Classroom, Science Lab, Science stockroom	1
Building 2 - Science / Home Ec	37	Stucco #3	Covered Walkway	1
Building 2 - Science / Home Ec	38	Linoleum grey pebble pattern	Mens Restroom, Womens Restroom	1

Condition Codes

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (Damaged 25% or more)
Change in Condition: (4) No (5) Yes (If yes, explain under comments)
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Misc: (11) Inaccessible, No surveillance data (12) Other (Explain under comments)

Six Month Surveillance Summary

District: Central California Conference of 7th
Day Adventist

School: Armona Union

Date:

10/6/2016

Inspector:

Luis Gutierrez

Building	HMR Number	Asbestos Material	Location	Condition Code/Comments
Building 2 - Science / Home Ec	39	Fiber Reinforced Panel with glue	Home Ec, Mens Restroom, Womens Restroom	1
Building 3 - Maintenance / Shops	1	Carpet blue #1	Classroom, room 5	1
Building 3 - Maintenance / Shops	11	Floor tile 9" brown with white	Storage, room 9	1
Building 3 - Maintenance / Shops	32	Baseboard 4" grey	Maintenance, room 7	1
Building 3 - Maintenance / Shops	40	Drywall splatter texture #3	Industrial Arts, room 4, Storage, room 9	1
Building 3 - Maintenance / Shops	41	Drywall unfinished w/ joint compound #2	Industrial Arts, room 4, Wood shop storage, room 6	1
Building 3 - Maintenance / Shops	42	Baseboard 3" brown	Storage, room 9	1
Building 3 - Maintenance / Shops	43	Sprayed on Acoustic over drywall	Classroom, room 5, Storage, room 9	1
Building 3 - Maintenance / Shops	44	Drywall with Heavy trowel texture	Classroom, room 5	1
Building 3 - Maintenance / Shops	45	Ceramic tile 6" with grout	Classroom, room 5	1
Building 3 - Maintenance / Shops	46	Drywall smooth #2	Maintenance, room 7, Wood shop storage, room 6, Wood Shop, room 6	1
Building 4 - Kindergarten	42	Baseboard 3" brown	Classroom Bible, room 1	1
Building 4 - Kindergarten	47	Carpet brown	Classroom Bible, room 1	1
Building 4 - Kindergarten	49	Floor tile 12" Off white	Classroom Bible, room 1	1

Condition Codes

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (Damaged 25% or more)
Change in Condition: (4) No (5) Yes (if yes, explain under comments)

Abated:

(6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Misc:

(11) Inaccessible, No surveillance data (12) Other (Explain under comments)

Six Month Surveillance Summary

District: Central California Conference of 7th
Day Adventist

School: Armona Union

Date: 10-6-2016

Inspector: Lisa Gutierrez

Building	HMR Number	Asbestos Material	Location	Condition Code/Comments
Building 4 - Kindergarten	50	Carpet lt brown	Kindergarten	1
Building 4 - Kindergarten	51	Baseboard 4" Beige	Kindergarten, Kindergarten restroom, Kindergarten Storage	1
Building 4 - Kindergarten	53	Drywall smooth #4	Kindergarten, Kindergarten restroom, Kindergarten Storage, room 3	1
Building 4 - Kindergarten	54	Sprayed on Acoustic #2	Kindergarten, Kindergarten restroom, Kindergarten Storage, room 3	1
Building 4 - Kindergarten	55	Floor tile 12" Tan/white popcorn	Kindergarten, Kindergarten restroom, Kindergarten Storage	1
Building 4 - Kindergarten	56	Carpet purple	Storage, room 3	1
Building 4 - Kindergarten	57	Baseboard 4" purple	Storage, room 3	1
Building 6 - Elementary Gym	58	Carpet green / brown	Entry, room 23, Stage entry east, room 27, Stage entry west, room 29, Stage, room 28	1
Building 6 - Elementary Gym	59	Baseboard 3" Green	Entry, room 23	1
Building 6 - Elementary Gym	60	Block and mortar	Boys Locker / Shower, room 8, Boys Restroom, room 7, Custodial, room 27, Entry, room 23, Girls Locker / Shower, room 6, Girls Restroom, room 5, Gym, room 30, Kitchen, room 24, Meeting, room 25, Restroom #1, Restroom #2, Stage entry east, room 27, Stage entry west, room 29, Stage Storage east, room 27, Stage storage west, room 26, Stage, room 28, Storage / Water Heater, Storage 10, Storage 2, Storage 3, Storage, room 29, Supply, room 4, Supply, room 8	1 41
Building 6 - Elementary Gym	61	Sprayed on Acoustic #3	Entry, room 23, Storage 10, Storage 3	1

Condition Codes

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (Damaged 25% or more)
Change in Condition: (4) No (5) Yes (if yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Misc: (11) Inaccessible, No surveillance data (12) Other (Explain under comments)

Six Month Surveillance Summary

District: Central California Conference of 7th
Day Adventist
School: Armona Union

Date: 10/6/2016
Inspector: Luis Gutierrez

Building	HMR Number	Asbestos Material	Location	Condition Code/Comments
Building 6 - Elementary Gym	62	Drywall smooth #5	Boys Locker / Shower, room 8, Boys Restroom, room 7, Custodial, room 27, Girls Locker / Shower, room 6, Girls Restroom, room 5, Kitchen, room 24, Meeting, room 25, Restroom #1, Restroom #2, Stage entry east, room 27, Stage entry west, room 29, Stage Storage east, room 27, Stage storage west, room 26, Stage, room 28, Storage / Water Heater, Storage 2, Storage, room 29, Supply, room 4, Supply, room 8	1
Building 6 - Elementary Gym	63	Carpet brown #2	Restroom #1, Restroom #2, Storage 10, Storage 3	1
Building 6 - Elementary Gym	64	Texture coat	Gym, room 30	1
Building 6 - Elementary Gym	65	Floor tile 12" Brown marble	Kitchen, room 24	1
Building 6 - Elementary Gym	66	Linoleum Brown / Red	Custodial, room 27, Kitchen, room 24, Restroom #3, room 27	1
Building 6 - Elementary Gym	67	Baseboard 4" Brown	Kitchen, room 24	1
Building 6 - Elementary Gym	69	Carpet blue #4	Meeting, room 25	1
Building 6 - Elementary Gym	70	Baseboard 4" blue	Meeting, room 25	1
Building 6 - Elementary Gym	71	Wall covering with glue	Meeting, room 25	1
Building 6 - Elementary Gym	72	Carpet orange	Stage Storage east, room 27, Stage storage west, room 26	1
Building 6 - Elementary Gym	73	Drywall splatter texture #4	Restroom #3, room 27	1
Building 7 - Elementary Classroom Wing	74	Carpet grey / brown	Grade 1-2, room 5, Grade 3-4, room 3, Grade 5-6, room 2, Grade 7-8, room 1	1
Building 7 - Elementary Classroom Wing	76	Baseboard 4" grey #2	Grade 1-2, room 5, Grade 3-4, room 3, Grade 5-6, room 2, Grade 7-8, room 1	1

Condition Codes

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (Damaged 25% or more)
Change in Condition: (4) No (5) Yes (If yes, explain under comments)
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Misc: (11) Inaccessible, No surveillance data (12) Other (Explain under comments)

Six Month Surveillance Summary

District: Central California Conference of 7th
Day Adventist
School: Armona Union

Date:

10-6-2016

Inspector:

W. Brown

Building	HMR Number	Asbestos Material	Location	Condition Code/Comments
Building 7 - Elementary Classroom Wing	77	Ceramic tile 1"-2" with grout #2	Boys restroom, room 9, Girls restroom, room 10, Storage, room 6	
Building 7 - Elementary Classroom Wing	78	Plaster sanded #3	Boys restroom, room 9, Custodial, room 11, Girls restroom, room 10, HVAC room, Storage, room 12, Storage, room 6	
Building 7 - Elementary Classroom Wing	79	Ceramic tile 4"x6" with grout #2	Boys restroom, room 9, Girls restroom, room 10, Storage, room 6	
Building 7 - Elementary Classroom Wing	80	Floor tile 9" blue	Grade 1-2, room 5, Mens restroom, room 7, Womens restroom, room 8	
Building 7 - Elementary Classroom Wing	81	Carpet lime green	Lounge, room 4	
Building 7 - Elementary Classroom Wing	82	Sprayed on acoustic #4	Lounge, room 4	
Building 7 - Elementary Classroom Wing	83	Drywall	Heater closet #1, Heater closet #2, Heater closet #3, Heater closet #4, Lounge, room 4	
Building 7 - Elementary Classroom Wing	84	Plaster smooth #1	Mens restroom, room 7, Womens restroom, room 8	
Building 8 - Preschool	85	Linoleum blue/purple pebble pattern	Entry, Kindergarten classroom	
Building 8 - Preschool	86	Baseboard 4" Tan	Entry, Kindergarten classroom, Restroom	
Building 8 - Preschool	87	Carpet red	Kindergarten classroom, Storage #1	
Building 8 - Preschool	88	Plaster trowel texture	Corridor south, Entry, Kindergarten classroom, Kitchen, Office	
Building 8 - Preschool	89	Floor tile 12" grey marble	Restroom	
Building 8 - Preschool	90	Plaster acoustical #2	Corridor south, Entry, Kindergarten classroom, Kitchen, Office	

Condition Codes

General Condition:
Change in Condition:

- (1) Good (2) Damaged (3) Significantly Damaged (Damaged 25% or more)
(4) No (5) Yes (if yes, explain under comments)

Abated:

- (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
(11) Inaccessible, No surveillance data (12) Other (Explain under comments)

Date Printed: 4/30/2014

Six Month Surveillance Summary

District: Central California Conference of 7th
Day Adventist

School: Armona Union

Date: 10/6/2016

Inspector: Luis Gutierrez

Building	HMR Number	Asbestos Material	Location	Condition Code/Comments
Building 8 - Preschool	91	Drywall smooth #6	Restroom, Storage #1	1
Building 8 - Preschool	92	Linoleum concealed	Entry, Kindergarten classroom	1
Building 8 - Preschool	93	Fiber Reinforced Panel with glue #2	Restroom	1
Building 8 - Preschool	94	Drywall unfinished w/ joint compound #3	Storage #2	1
Building 8 - Preschool	95	Linoleum white square pattern	Corridor south, Kitchen	1
Building 8 - Preschool	96	Carpet orange #2	Office	1
Building 8 - Preschool	97	Wall paper and glue	Office	1

Condition Codes

General Condition:
Change in Condition:

(1) Good (2) Damaged (3) Significantly Damaged (Damaged 25% or more)
(4) No (5) Yes (If yes, explain under comments)

Abated:

(6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Misc:

(11) Inaccessible, No surveillance data (12) Other (Explain under comments)