

Six Month Surveillance Summary

District: Central California Conference of 7th
Day Adventist

Date: 9-06-2016

School: Central Valley Christian Academy

Inspector: Joseph Dorchuck

Building	HMR Number	Asbestos Material	Location	Condition Code/Comments
01-Bus Barn	1	Fireproofing	01-Garage	4, 11
01-Bus Barn	2	Drywall- Tape and Joint compound	02-Office	1
01-Bus Barn	3	Linoleum-White w/Mastic	03-Restroom	1
01-Bus Barn	4	Baseboard 4" Grey w/Mastic	03-Restroom	1
01-Bus Barn	5	Drywall-Orange Peel Texture	03-Restroom, 04-Storage	1 (03, 04)
02-Gymnasium	6	Carpet-Blue/Purple Multi-Mastic	01-Gymnasium Lobby, 13-Womens Locker Hallway, 17-Mens Locker Hallway	1 (01-17)
02-Gymnasium	7	Carpet Grey-Mastic	01-Gymnasium Lobby, 13-Womens Locker Hallway, 17-Mens Locker Hallway, 35-Recording Studio 1	1 (01-35)
02-Gymnasium	8	CMU-Mortar	01-Gymnasium Lobby, 02-Projection Room, 03-Lobby Storage, 06-Lobby Mens Restroom, 07-Lobby Womens Restroom, 08-Lobby Mens Custodial, 12-Gymnasium Southeast Storage, 13-Womens Locker Hallway, 14-Womens Locker/Shower, 15-Womens Coaches Office, 16-Womens Hallway Storage, 17-Mens Locker Hallway, 18-Mens Locker Hallway Storage, 19-Mens Locker/Shower, 20-Weight Room, 21-Back Stage Entry Hall, 22-Music/Choir Hallway, 23-Music Office, 24-Choir Room, 25-Choir Room #9, 26-Choir Room Storage, 27-Choir/Instrument Storage, 28-Room 6, 29-Room 5, 30-Room 4, 31-Room 3, 32-Room 2, 33-Womens Restroom, 34-Mens Restroom, 35-Recording Studio 1, 36-Recording Studio 1 Storage, 44-Exterior Water Heater Closet, 45-Laudry Room	12-(06, 07, 08) Being Remodeled ALL OTHERS 1-GOOD

Condition Codes

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (Damaged 25% or more)
Change in Condition: (4) No (5) Yes (if yes, explain under comments)
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Misc: (11) Inaccessible, No surveillance data (12) Other (Explain under comments)

Date Printed: 11/7/2014

Six Month Surveillance Summary

District: Central California Conference of 7th
Day Adventist

School: Central Valley Christian Academy

Date: 9-06-2016

Inspector: Joseph Dorchuck

Building	HMR Number	Asbestos Material	Location	Condition Code/Comments
02-Gymnasium	9	ACT 12" Fissure-Glue	01-Gymnasium Lobby, 03-Lobby Storage, 06-Lobby Mens Restroom, 07-Lobby Womens Restroom, 08-Lobby Mens Custodial, 12-Gymnasium Southeast Storage, 14-Womens Locker/Shower, 15-Womens Coaches Office, 16-Womens Hallway Storage, 18-Mens Locker Hallway Storage, 19-Mens Locker/Shower, 20-Weight Room, 22-Music/Choir Hallway, 23-Music Office, 28-Room 6, 29-Room 5, 31-Room 3, 32-Room 2, 33-Womens Restroom, 34-Mens Restroom, 36-Recording Studio 1 Storage, 39-Instrument Storage, 40-Music Library, 41-Band Storage, 42-Organ Studio	12, Being Remodeled (06,07,08) all others: 1 Good
02-Gymnasium	10	Rock-Mortar	01-Gymnasium Lobby	1
02-Gymnasium	11	Carpet-Green Shag	02-Projection Room	1
02-Gymnasium	12	Drywall Unfinished	02-Projection Room, 21-Back Stage Entry Hall, 36-Recording Studio 1 Storage, 44-Exterior Water Heater Closet, 45-Laundry Room	1 (02-45)
02-Gymnasium	13	VFT 12" Brown Oatmeal-Mastic	04-Kitchen	1
02-Gymnasium	14	Baseboard 4" Cream-Mastic	04-Kitchen, 33-Womens Restroom, 34-Mens Restroom, 35-Recording Studio 1, 37-Recording Studio 2	1-All Good
02-Gymnasium	15	Masonite White	04-Kitchen	1
02-Gymnasium	16	FCP-2x4 White Metal	04-Kitchen	1
02-Gymnasium	17	Ceramic tile 1" Brown-Grout	06-Lobby Mens Restroom, 07-Lobby Womens Restroom	12, Being Remodeled
02-Gymnasium	18	Ceramic tile 6" Brown-Grout	06-Lobby Mens Restroom, 07-Lobby Womens Restroom	12 (06,07) (Being Remodeled)

Condition Codes

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (Damaged 25% or more)
Change in Condition: (4) No (5) Yes (If yes, explain under comments)
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Misc: (11) Inaccessible, No surveillance data (12) Other (Explain under comments)

Date Printed: 11/7/2014

Six Month Surveillance Summary

District: Central California Conference of 7th
Day Adventist

School: Central Valley Christian Academy

Date:

9-06-16

Inspector:

Joseph Dorehuck

Building	HMR Number	Asbestos Material	Location	Condition Code/Comments
02-Gymnasium	19	Ceramic Tile 4" Creamw/Speck-Grout	06-Lobby Mens Restroom, 07-Lobby Womens Restroom	12 (06,07) Being Remodeled
02-Gymnasium	20	Linoleum Beige Pebble-Mastic	08-Lobby Mens Custodial, 26-Choir Room Storage, 27-Choir/Instrument Storage, 29-Room 5, 32-Room 2, 36-Recording Studio 1 Storage	12-(08) Being Re- modeled 1-Good all others
02-Gymnasium	21	Baseboard L Shape Plastic-Mastic	09-Main Gymnasium	1
02-Gymnasium	22	Drywall Knockdown Texture	10-Stage, 11-Stage Entry, 13-Womens Locker Hallway, 17-Mens Locker Hallway, 23-Music Office, 38-Band Room, 39-Instrument Storage, 40-Music Library, 41-Band Storage, 42-Organ Studio, 43-Custodial Closet	1 (10-43)
02-Gymnasium	23	Wood Paneling-Glue	10-Stage, 40-Music Library	1 (10, 40)
02-Gymnasium	24	Carpet Grey Multi-Mastic	11-Stage Entry, 21-Back Stage Entry Hall, 22-Music/Choir Hallway, 23-Music Office, 24-Choir Room, 25-Choir Room #9, 28-Room 6, 31-Room 3, 37-Recording Studio 2	1 (11-37)
02-Gymnasium	25	Baseboard 4" Brown-Mastic	11-Stage Entry, 21-Back Stage Entry Hall, 22-Music/Choir Hallway, 23-Music Office, 24-Choir Room, 25-Choir Room #9, 28-Room 6, 29-Room 5, 31-Room 3, 32-Room 2	1 (11-32)
02-Gymnasium	26	Linoleum Yellow Pebble-Mastic	12-Gymnasium Southeast Storage	1
02-Gymnasium	27	Baseboard 4" Beige-Mastic	12-Gymnasium Southeast Storage, 26-Choir Room Storage, 27-Choir/Instrument Storage, 36-Recording Studio 1 Storage, 39-Instrument Storage, 41-Band Storage	1 (12-41)
02-Gymnasium	28	Ceramic Tile 1" Off White-Grout	14-Womens Locker/Shower, 19-Mens Locker/Shower	1 (14,19)

Condition Codes

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (Damaged 25% or more)

Change in Condition: (4) No (5) Yes (if yes, explain under comments)

Abated:

(6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restrictd

Misc:

(11) Inaccessible, No surveillance data (12) Other (Explain under comments)

Date Printed: 11/7/2014

Six Month Surveillance Summary

District: Central California Conference of 7th
Day Adventist

School: Central Valley Christian Academy

Date: 9-06-2016

Inspector: Joseph Dorchuck

Building	HMR Number	Asbestos Material	Location	Condition Code/Comments
02-Gymnasium	29	Ceramic Tile 4" Brown Marble-Grout	14-Womens Locker/Shower, 19-Mens Locker/Shower	1 (14, 19)
02-Gymnasium	30	Carpet Multi Grey-Mastic	15-Womens Coaches Office	1
02-Gymnasium	31	Baseboard 4" Black-Mastic	15-Womens Coaches Office	1
02-Gymnasium	32	Ceramic tile 12"x6" Beige/Orange-Grout	14-Womens Locker/Shower, 19-Mens Locker/Shower	1 (14, 19)
02-Gymnasium	33	ACT 12" Pinhole-Glue	26-Choir Room Storage, 27-Choir/Instrument Storage	1 (26, 27)
02-Gymnasium	34	Carpet Red-Mastic	30-Room 4	1
02-Gymnasium	35	ACT 12" Semi Smooth-Glue	30-Room 4	1
02-Gymnasium	36	Linoleum White Pebble-Mastic	33-Womens Restroom	1
02-Gymnasium	37	Linoleum Light Blue Pebble-Mastic	34-Mens Restroom	1
02-Gymnasium	38	Drywall Smooth Texture	35-Recording Studio 1, 37-Recording Studio 2	1 (35, 37)
02-Gymnasium	40	Duct Sealant White	36-Recording Studio 1 Storage	1
02-Gymnasium	41	ACT 12" Pinhole-Glue-glue	38-Band Room	1
02-Gymnasium	42	Linoleum Tan Stone Pattern-Mastic	39-Instrument Storage, 41-Band Storage	1 (39, 41)
02-Gymnasium	43	Carpet Green-Mastic	40-Music Library	1
02-Gymnasium	44	Sealant Wall Black	45-Laundry Room	1

Condition Codes

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (Damaged 25% or more)
Change in Condition: (4) No (5) Yes (If yes, explain under comments)
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Misc: (11) Inaccessible, No surveillance data (12) Other (Explain under comments)

Date Printed: 11/7/2014

Six Month Surveillance Summary

District: Central California Conference of 7th
Day Adventist

School: Central Valley Christian Academy

Date: 9-06-2016

Inspector: Joseph Dorchuck

Building	HMR Number	Asbestos Material	Location	Condition Code/Comments
02-Gymnasium	45	Floor Filler	45-Laundry Room	1
03-Student Center/Shop Building	46	Drywall Smooth Texture 2	01-Student Center, 02-Student Center Restroom, 03-Student Center Water Heater Closet, 04-Student Center Storage, 07-Shop	1 (01-07)
03-Student Center/Shop Building	47	Ceramic Tile 12" Tan-Grout	02-Student Center Restroom	1
03-Student Center/Shop Building	48	Carpet Olive Green-Mastic	05-Shop Storage	1
03-Student Center/Shop Building	49	Drywall Orange Peel Texture	05-Shop Storage, 06-Shop Classroom, 08-Paint Room, 09-Shop Storage, 10-Shop Office, 11-Shop Restroom	1 (05-11)
03-Student Center/Shop Building	50	ACT 1'x4' Pinhole Fissure	09-Shop Storage	1
04-Maintenance Bldg	51	Drywall Knockdown Texture 2	01-Garage Area	1
04-Maintenance Bldg	52	Carpet Brown- Mastic	02-Maintenance Office	1

Condition Codes

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (Damaged 25% or more)
Change in Condition: (4) No (5) Yes (If yes, explain under comments)
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Misc: (11) Inaccessible, No surveillance data (12) Other (Explain under comments)

Date Printed: 11/7/2014