

Six Month Surveillance Summary

District: Central California Conference of 7th
Day Adventist

School: San Francisco Adventist School

Date: December 13, 2014

Inspector: Lizbeth Caraballo

Building	HMR Number	Asbestos Material	Location	Condition Code/Comments
House	35	Carpet and Mastic - Yellow	01 - Interior Space	
Main Building	1	9" VFT and Mastic - Grey w/White Streak	01 - Principals Office, 02 - Principal Office Storage, 05 - Classroom 2, 08 - Classroom 2 Storage Closet, 12 - Classroom 1 Storage Closet	1
Main Building	2	4" Baseboard and Mastic - Black	01 - Principals Office, 04 - Classroom 3, 05 - Classroom 2, 09 - Classroom 1, 18 - Storage, 20 - Janitor Closet, 23 - Electrical Room, 25 - Room 101 Closet, 27 - Office Hallway and Stairwell, 28 - Office, 30 - Original Principal Office, 31 - Office Hallway, 35 - Treasurer Office, 36 - Secretary Office, 38 - Back Hallway South, 39 - Lab, 40 - Hallway Southeast, 41 - Room 202 Computer Lab, 42 - Room 202 Storage-Heater Closet, 43 - Room 201, 44 - Room 201 Closet, 45 - Storage Room	1
Main Building	3	Drywall - Medium Texture	01 - Principals Office, 02 - Principal Office Storage, 04 - Classroom 3, 05 - Classroom 2, 09 - Classroom 1, 19 - Back Hallway, 28 - Office, 29 - Office Storage Closet, 30 - Original Principal Office, 31 - Office Hallway, 35 - Treasurer Office, 36 - Secretary Office, 37 - Library	1
Main Building	4	Drywall - Knockdown Texture	01 - Principals Office, 04 - Classroom 3, 05 - Classroom 2, 08 - Classroom 2 Storage Closet, 09 - Classroom 1, 12 - Classroom 1 Storage Closet, 16 - MPR, 18 - Storage, 23 - Electrical Room, 25 - Room 101 Closet, 26 - Room 101 Hot Water Heater, 27 - Office Hallway and Stairwell, 28 - Office, 30 - Original Principal Office, 31 - Office Hallway, 32 - Cumulative File Room	1
Main Building	5	Carpet and Mastic - Grey w/Black Specks	01 - Principals Office, 04 - Classroom 3	1

Condition Codes

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (Damaged 25% or more)
Change in Condition: (4) No (5) Yes (if yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Misc: (11) Inaccessible, No surveillance data (12) Other (Explain under comments)

Six Month Surveillance Summary

District: Central California Conference of 7th
Day Adventist

School: San Francisco Adventist School

Date: Dec 13, 2016

Inspector: Lizbeth Caraballo

Building	HMR Number	Asbestos Material	Location	Condition Code/Comments
Main Building	6	4" Baseboard and Mastic - Brown	02 - Principal Office Storage, 12 - Classroom 1 Storage Closet, 17 - Office Hallway, 19 - Back Hallway, 32 - Cumulative File Room, 33 - Mens Restroom, 34 - Womens Restroom, 37 - Library, 46 - Stairwell	1
Main Building	7	6" Ceramic Tiles and Grout - Grey	03 - Womens Restroom, 06 - Classroom 2 Restroom 1, 07 - Classroom Restroom 2, 10 - Classroom 1 Restroom 1, 11 - Classroom 1 Restroom 2, 13 - Boys Restroom	1
Main Building	8	4" Baseboard and Mastic - Off-White	03 - Womens Restroom, 13 - Boys Restroom	1
Main Building	9	Drywall - Smooth Texture	03 - Womens Restroom, 16 - MPR, 33 - Mens Restroom, 34 - Womens Restroom, 38 - Back Hallway South	1
Main Building	10	4" Ceramic Tiles and Grout - White	03 - Womens Restroom, 06 - Classroom 2 Restroom 1, 07 - Classroom Restroom 2, 10 - Classroom 1 Restroom 1, 11 - Classroom 1 Restroom 2, 13 - Boys Restroom, 21 - Mens Restroom, 22 - Womens Restroom	1
Main Building	11	Carpet and Mastic - Teal/Black	05 - Classroom 2	1
Main Building	12	Drywall - Orange Peel Texture	06 - Classroom 2 Restroom 1, 07 - Classroom Restroom 2, 10 - Classroom 1 Restroom 1, 11 - Classroom 1 Restroom 2, 13 - Boys Restroom, 18 - Storage, 20 - Janitor Closet, 21 - Mens Restroom, 22 - Womens Restroom, 23 - Electrical Room, 24 - Room 101, 25 - Room 101 Closet, 39 - Lab, 40 - Hallway Southeast, 41 - Room 202 Computer Lab, 42 - Room 202 Storage-Heater Closet, 43 - Room 201, 44 - Room 201 Closet, 45 - Storage Room, 46 - Stairwell	1
Main Building	13	Carpet and Mastic - Brown	09 - Classroom 1	1

Condition Codes

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (Damaged 25% or more)
Change in Condition: (4) No (5) Yes (if yes, explain under comments)
Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted
Misc: (11) Inaccessible, No surveillance data (12) Other (Explain under comments)

Six Month Surveillance Summary

District: Central California Conference of 7th
Day Adventist

School: San Francisco Adventist School

Date:

Dec 13, 2016

Inspector:

Urbeth Garaball

Building	HMR Number	Asbestos Material	Location	Condition Code/Comments
Main Building	14	Drywall - Tape and Joint Compound Only	14 - Boys Restroom Hot Water Heater, 15 - Boys Restroom Closet, 26 - Room 101 Hot Water Heater	1
Main Building	15	Carpet and Mastic - Teal/Grey/Tan	16 - MPR	1
Main Building	16	Linoleum and Mastic - Beige	16 - MPR	1
Main Building	17	12" VFT and Mastic - Light Blue	17 - Office Hallway	1
Main Building	18	Wood Paneling	17 - Office Hallway, 27 - Office Hallway and Stairwell	1
Main Building	19	Linoleum and Mastic - Tan	18 - Storage, 19 - Back Hallway, 23 - Electrical Room, 25 - Room 101 Closet, 40 - Hallway Southeast, 46 - Stairwell	1
Main Building	20	12" ACT and Mastic - Pinhole	19 - Back Hallway	1
Main Building	21	Plaster-Stucco	19 - Back Hallway, 38 - Back Hallway South	1
Main Building	22	2" Ceramic Tiles and Grout - Brown	21 - Mens Restroom, 22 - Womens Restroom	1
Main Building	23	Carpet and Mastic - Red/Tan Multi	24 - Room 101	1
Main Building	24	4" Baseboard and Mastic - Red	24 - Room 101	1
Main Building	25	12" ACT and Mastic - Large Fissure	24 - Room 101, 39 - Lab	1
Main Building	26	Linoleum and Mastic - Tan Tile Pattern	38 - Back Hallway South, 39 - Lab, 45 - Storage Room	1
Main Building	27	CMU and Grout	26 - Room 101 Hot Water Heater	1

Condition Codes

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (Damaged 25% or more)

Change in Condition: (4) No (5) Yes (if yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Misc: (11) Inaccessible, No surveillance data (12) Other (Explain under comments)

Six Month Surveillance Summary

District: Central California Conference of 7th Day Adventist

School: San Francisco Adventist School

Date: December 13, 2014
Inspector: Lizabeth Garaballido

Building	HMR Number	Asbestos Material	Location	Condition Code/Comments
Main Building	28	Carpet and Mastic - Gold	27 - Office Hallway and Stairwell	1
Main Building	29	9" VFT and Mastic - Teal w/White Streak	27 - Office Hallway and Stairwell	1
Main Building	30	Carpet and Mastic - Tan/Light Blue	28 - Office, 30 - Original Principal Office, 31 - Office Hallway, 35 - Treasurer Office, 36 - Secretary Office, 37 - Library	1
Main Building	31	9" VFT & Mastic - Grey w/White & Blue	32 - Cumulative File Room, 33 - Mens Restroom, 34 - Womens Restroom	1
Main Building	32	Carpet and Mastic - Blue	40 - Hallway Southeast	1
Main Building	33	12" ACT and Mastic - Random Pinhole	40 - Hallway Southeast, 41 - Room 202 Computer Lab, 43 - Room 201, 44 - Room 201 Closet	1
Main Building	34	Carpet and Mastic - Light Blue	43 - Room 201, 44 - Room 201 Closet	1
Main Building	38	Linoleum and Mastic - Off-White	41 - Room 202 Computer Lab, 42 - Room 202 Storage-Heater Closet	1
Music Portable	36	Carpet and Mastic - Light Brown	01 - Main Room, 02 - West Room, 03 - East Room	1
Music Portable	36	Carpet and Mastic - Light Brown	01 - Main Room, 02 - West Room, 03 - East Room	1
Music Portable	36	Carpet and Mastic - Light Brown	01 - Main Room, 02 - West Room, 03 - East Room	1

Condition Codes

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (Damaged 25% or more)

Change in Condition: (4) No (5) Yes (if yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Misc: (11) Inaccessible, No surveillance data (12) Other (Explain under comments)