

Six Month Surveillance Summary

District: Central California Conference of 7th
Day Adventist

School: Mariposa

Date: 5-6-15

Inspector: Wendy Roth

Building	HMR Number	Asbestos Material	Location	Condition Code/Comments
Church, Building 4	10	Carpet red	Chapel, Room 7, Foyer, Room 1, Mail room, Room 4, Stage, Room 8, Vestibule, Room 2	1, 4
Church, Building 4	11	Drywall knock-down texture #2	Foyer, Room 1, Vestibule, Room 2	1, 4
Church, Building 4	12	Carpet brown #2	Office, Room 8, Stairway and hall, Room 12, Storage, Room 10, Training, Room 3	2, 4
Church, Building 4	13	Plaster heavy texture	Baptism, Room 11, Chapel, Room 7, Closet, Room 15A, Closet, Room 16A, Closet, Room 16B, Closet, Room 16C, Mail room, Room 4, Mens restroom, Room 13, Office, Room 8, Restroom closet, Room 6, Sabbath school 1, Room 15, Sabbath school 2, Room 16, Stage, Room 9, Stairway and hall, Room 12, Storage, Room 10, Training, Room 3, Womens restroom, Room 14	2, 4
Church, Building 4	14	Drywall heavy texture	Mail room, Room 4, Restroom, Room 5	1, 4
Church, Building 4	15	Linoleum cream	Restroom, Room 5	1, 4
Church, Building 4	17	Ceramic tile 8" with grout	Mens restroom, Room 13, Womens restroom, Room 14	1, 4
Church, Building 4	18	Ceramic tile 1" with grout	Mens restroom, Room 13, Womens restroom, Room 14	1, 4
Church, Building 4	19	Carpet yellow	Sabbath school 1, Room 15, Sabbath school 2, Room 16	2, 4
Church, Building 4	20	Plaster smooth	Mechanical, Room 17	1, 4
Church, Building 4	21	Drywall with joint compound	Basement storage, Room 19	2, 4
Church, Building 4	22	Plaster rough texture	Basement storage 2, Room 20, Basement storage, Room 19, Exit, Room 21	2, 4
Church, Building 4	23	Transite	Attic, Basement storage, Room 19, Mechanical, Room 17, Pipe chase	1, 4

Condition Codes

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (Damaged 25% or more)

Change In Condition: (4) No (5) Yes (if yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Endosed (10) Isolated & Restricted

Misc: (11) Inaccessible, No surveillance data (12) Other (Explain under comments)

Six Month Surveillance Summary

District: Central California Conference of 7th
Day Adventist

School: Mariposa

Date: 3-6-15

Inspector: Wendy Roth

Building	HMR Number	Asbestos Material	Location	Condition Code/Comments
Church, Building 4	25	Drywall knock-down texture #3	Basement storage 2, Room 20, Classroom, Room 22, Exit, Room 21	1, 4
Church, Building 4	26	Carpet blue	Classroom, Room 22	1, 4
Classroom, Building 1	1	Linoleum Off white	Room 1, Entry, Room 3, Classroom, Room 4, Kitchen, Room 6, Mens restroom, Room 7, Womens restroom, Room 9, Vestibule	1, 4
Classroom, Building 1	2	Baseboard 4" tan	Room 1, Entry, Room 10, Closet, Room 2, Classroom, Room 3, Classroom, Room 5, Classroom closet, Room 8, Alcove, Room 9, Vestibule	1, 4
Classroom, Building 1	3	Drywall splatter texture #1	Room 1, Entry, Room 6, Mens restroom, Room 7, Womens restroom, Room 8, Alcove	1, 4
Classroom, Building 1	4	Carpet brown	Room 10, Closet, Room 2, Classroom, Room 3, Classroom, Room 5, Classroom closet, Room 8, Alcove	1, 4
Classroom, Building 1	5	Drywall knock-down texture	Room 10, Closet, Room 2, Classroom, Room 3, Classroom, Room 4, Kitchen, Room 5, Classroom closet, Room 6, Mens restroom, Room 7, Womens restroom, Room 9, Vestibule	1, 4
Classroom, Building 1	6	Drywall smooth texture	Room 2, Classroom, Room 3, Classroom, Room 4, Kitchen	1, 4
Classroom, Building 1	7	Ceramic tile 4" with grout	Room 4, Kitchen	2, 4
Fellowship Hall, Building 2	4	Carpet brown	Hall	1, 4
Fellowship Hall, Building 2	8	Drywall splatter texture #2	Hall	1, 4
Fellowship Hall, Building 2	9	Linoleum tan	Hall	1, 4

Condition Codes

General Condition: (1) Good (2) Damaged (3) Significantly Damaged (Damaged 25% or more)

Change in Condition: (4) No (5) Yes (If yes, explain under comments)

Abated: (6) Repaired (7) Removed (8) Encapsulated (9) Enclosed (10) Isolated & Restricted

Misc: (11) Inaccessible, No surveillance data (12) Other (Explain under comments)

Date Printed: 5/13/2014